

SCHEDULE 2

Essential health and safety requirements relating to the design and construction of equipment and protective systems intended for use in potentially explosive atmospheres

Hazards arising from stray electric and leakage currents

1.3.3 Stray electric and leakage currents in conductive equipment parts which could result in, for example, the occurrence of dangerous corrosion, overheating of surfaces or sparks capable of provoking an ignition must be prevented.