

## SCHEDULE 1

### Rendering requirements

#### Part II

#### Methods of rendering

##### *Method 1*

##### *Natural fat batch atmospheric (150 mm particle size)*

#### **Crushing**

2. The raw material shall be reduced in size by crushing so that the particle size does not exceed 150 mm. Final reduction equipment shall be checked daily and its condition recorded. Any broken equipment shall be repaired without delay to ensure that the final particle size is achieved.