

SCHEDULE 1

Rendering requirements

Part II

Methods of rendering

Method 4

Natural fat batch (Batch Pressure)

Separation and storage of final products

4. After cooking, the material shall be discharged from the cookers and separated into its tallow and protein fractions. Protein and tallow shall be stored separately.