
STATUTORY RULES OF NORTHERN IRELAND

2016 No. 427

The Mines Regulations (Northern Ireland) 2016

PART 3

CONTROL OF MAJOR HAZARDS

Inrushes

Precautions against inrushes

- 33.** The mine operator shall ensure that inrush into any working in a mine of—
- (a) gas from disused workings (whether mine workings or not); or
 - (b) water or material that flows, or is likely to flow when wet, from any source,
- is prevented.