

SCHEDULE 6

Rendering requirements

PART II

Methods of Rendering

METHOD 5

DEFATTED

CONTINUOUS OR BATCH

Time and temperature

4. The specified risk material may be cooked such that the time-temperature requirements are achieved at the same time.