

SCHEDULE 2
SOLVENT EMISSIONS

PART 3
Duties on operators

Data reporting

10.—(1) The operator of a solvents installation must on request provide SEPA with such information as it may reasonably request to verify compliance under Part 8 of Annex VII to the Industrial Emissions Directive with—

- (a) emission limit values in waste gases, fugitive emission limit values and total emission limit values, or
- (b) the requirements of any reduction scheme.

(2) Information may be provided in a solvent management plan prepared under Part 7 of Annex VII to the Industrial Emissions Directive.

Monitoring of emissions

11. The operator of a solvents installation must monitor emissions from the installation in accordance with Part 6 of Annex VII to the Industrial Emissions Directive.