



Mines and Quarries Act 1954

1954 CHAPTER 70

PART III

SAFETY, HEALTH AND WELFARE (MINES)

Machinery and Apparatus

82 Fencing of exposed parts of machinery

- (1) Subject to the provisions of this section, every flywheel and every other dangerous exposed part of any machinery used as, or forming, part of the equipment of a mine shall be securely fenced ; and where means of fencing are prescribed with respect to any such part of any such machinery as aforesaid, the fencing provided in pursuance of the foregoing provisions of this subsection for that part shall be provided by those means.
- (2) It shall be the duty of the manager of every mine to ensure that fencing provided in pursuance of the foregoing subsection is properly maintained and is kept in position while the parts required to be fenced are in motion or in use, except where such parts are exposed for an examination or adjustment which it is necessary to carry out while they are in motion or use and all such conditions as may be prescribed are complied with.