

## FIRST SCHEDULE

### THE MISCELLANEOUS MINES (GENERAL) REGULATIONS, 1956, HAVING EFFECT AS IF MADE UNDER SECTION ONE HUNDRED AND FORTY-ONE OF THE MINES AND QUARRIES ACT, 1954

## PART V

### Provisions relating to carriage of persons and things through shafts, staple-pits and unwalkable outlets

#### *Loading*

**20.** Where a kibble is used in any shaft or staple-pit in which persons are or may be underneath the kibble, no person shall signal it away unless he is satisfied that—

- (a) no loose mineral is carried above the level of the rim;
- (b) tools, equipment or other materials for use or used in the mine are not loaded together with mineral;
- (c) when things which project above the rim are carried, they are securely fastened to the bow or chains supporting the kibble;
- (d) nothing capable of causing injury is adhering to the outside of the kibble; and
- (e) when the kibble is being raised, it is in line with the pulleys and carefully steadied.