

FIRST SCHEDULE

THE MISCELLANEOUS MINES (GENERAL) REGULATIONS, 1956, HAVING EFFECT AS IF MADE UNDER SECTION ONE HUNDRED AND FORTY-ONE OF THE MINES AND QUARRIES ACT, 1954

PART V

Provisions relating to carriage of persons and things through shafts, staple-pits and unwalkable outlets

Loading

18. Where persons are to be carried through a shaft, staple-pit or unwalkable outlet in a cage or carriage, the banksman or other person authorised to transmit signals in relation thereto shall not signal the cage or carriage away if it or any deck thereof contains more than the maximum number of persons allowed to be carried or if the gates with which it is provided are not properly closed.

19.—(1) No minerals, equipment or materials (other than things which are required to be or are normally kept by a person in his possession) shall be carried through a shaft, staple-pit or unwalkable outlet whilst persons are being carried through it, whether in the same direction or not, and no person shall signal away a cage, carriage or kibble if he has any cause to believe that the preceding provisions of this paragraph would thereby be infringed.

(2) Nothing in paragraph (1) of this regulation shall prevent—

- (a) persons who are to work in a shaft, staple-pit or outlet having with them when being carried there through equipment or materials which they will or may require for the purposes of that work; or
- (b) persons accompanying animals or bulky materials which cannot be lowered or raised in a cage or carriage;

and for the purposes of the said paragraph no account shall be taken of the carriage of the owner or manager of the mine or of any official, engineer or technician in the case of whom the manager has by notice directed that the said paragraph shall not apply.

20. Where a kibble is used in any shaft or staple-pit in which persons are or may be underneath the kibble, no person shall signal it away unless he is satisfied that—

- (a) no loose mineral is carried above the level of the rim;
- (b) tools, equipment or other materials for use or used in the mine are not loaded together with mineral;
- (c) when things which project above the rim are carried, they are securely fastened to the bow or chains supporting the kibble;
- (d) nothing capable of causing injury is adhering to the outside of the kibble; and
- (e) when the kibble is being raised, it is in line with the pulleys and carefully steadied.