

**Changes to legislation:** There are currently no known outstanding effects for the The Furniture and Furnishings (Fire) (Safety) Regulations 1988, Paragraph 2. (See end of Document for details)

### SCHEDULE 3

---

**Commencement Information**

**11** [Sch. 3](#) in force at 1.3.1990, see [reg. 1\(2\)\(h\)](#)

**2.** The interliner, water-soaked or not as the case may be, shall be tested using cover fabric corresponding to the specification set out in paragraph 3 below and foam filling corresponding to the specification set out in paragraph 4 below. The test shall be conducted using ignition source 5 of BS 5852: Part 2.

**Changes to legislation:**

There are currently no known outstanding effects for the The Furniture and Furnishings (Fire) (Safety) Regulations 1988, Paragraph 2.