

SCHEDULE 1

ESSENTIAL REQUIREMENTS

Discrimination and Sensitivity

6. A cold-water meter shall be sufficiently sensitive and the discrimination threshold shall be sufficiently low for the intended measurement task.