

SCHEDULE 4

Modules for conformity assessment

PART 2

Module A (internal production control)

3. The manufacturer must take all necessary measures to ensure that the manufacturing process of a listed product ensures that the product complies with the general technical documentation.