
STATUTORY INSTRUMENTS

2014 No. 3248

The Mines Regulations 2014

PART 3

CONTROL OF MAJOR HAZARDS

Explosive atmospheres

Explosive atmospheres

- 22.**—(1) The mine operator must ensure that—
- (a) there are in place in the zones classified under regulation 7(1) of DSEAR, specific arrangements to detect the presence, and monitor the concentration, of flammable gas; and
 - (b) measures are taken to reduce the level of flammable gas in any zone in which it has been detected to as low a level as is reasonably practicable.
- (2) The measures referred to in paragraph (1)(b) must include (where necessary) drainage, removal and dilution.