
STATUTORY INSTRUMENTS

2014 No. 3248

The Mines Regulations 2014

PART 3

CONTROL OF MAJOR HAZARDS

Explosive atmospheres

Burning and welding in coal mines

25. The mine operator must ensure that—
- (a) no burning or welding equipment is used except in a shaft or inset; and
 - (b) before using any such equipment in a shaft or inset, an appropriate assessment is made of the risks of the proposed operation and appropriate steps are taken to mitigate the risks identified.