

---

STATUTORY INSTRUMENTS

---

**2014 No. 3248**

The Mines Regulations 2014

PART 3

CONTROL OF MAJOR HAZARDS

Inrushes

**Precautions against inrushes**

- 33.** The mine operator must ensure that inrush into any working in a mine of—
- (a) gas from disused workings (whether mine workings or not); or
  - (b) water or material that flows, or is likely to flow when wet, from any source,
- is prevented.