

SCHEDULE

Article 2

INSTALLATIONS

PART 1

Installations stationed at the time the Order is made

(1) Name or other designation of the offshore installation	(2) Latitude	(3) Longitude
[^{F1} CATS T1], Block 22/9, Andrew Field	57°42.667'N	01°43.466'E
[^{F2} CATS T5], Block 22/27a, Banff Field	57°01.752'N	01°12.124'E
Buzzard Gas Export PLEM, Block 13/30c, Buzzard Field	58°03.793'N	01°02.013'W
Buzzard Oil Export PLEM, Block 20/11, Buzzard Field	57°33.961'N	00°53.716'W
[^{F3} CATS T2], Block 22/18a, ETAP Field	57°21.983'N	01°28.119'E
Europa (EZ), Block 49/22, Europa Field	53°14.824'N	02°17.743'E
Ganymede (ZD), Block 49/22, Ganymede Field	53°19.439'N	02°14.199'E
[^{F4} CATS T6], Block 29/12, Judy Field	56°39.793'N	01°12.112'E
LOGGS Complex PA, Block 49/16, LOGGS Field	53°23.399'N	02°00.135'E
LOGGS Complex PC, Block 49/16, LOGGS Field	53°23.379'N	02°00.185'E
LOGGS Complex PP, Block 49/16, LOGGS Field	53°23.354'N	02°00.228'E
LOGGS Complex PR, Block 49/16, LOGGS Field	53°23.330'N	02°00.266'E
LOGGS North Valiant PD, Block 49/16, LOGGS Field	53°23.369'N	02°00.277'E
Mimas (MN), Block 48/9a, Mimas Field	53°45.729'N	01°42.282'E
North Valiant (SP), Block 49/16, North Valiant Field	53°21.377'N	02°02.315'E
Saturn (ND), Block 48/10b, Saturn Field	53°43.460'N	01°53.733'E

Changes to legislation: There are currently no known outstanding effects for the The Offshore Installations (Safety Zones) Order 2018. (See end of Document for details)

South Valiant (TD), Block 49/21, 53°19.055'N South Valiant Field	02°05.664'E
Tethys (TN), Block 49/11b, Tethys 53°39.007'N Field	02°03.370'E
Vampire/Valkyrie (OD), Block 49/16, Vampire/Valkyrie 53°27.900'N Field	02°02.472'E
Vanguard (QD), Block 49/16, 53°22.652'N Vanguard Field	02°06.616'E
Victor JD, Block 49/22, Viking Field 53°19.641'N	02°21.739'E
Viking AR, Block 49/12, Viking 53°32.006'N Field	02°15.285'E
Viking Bravo Complex BA, Block 49/17, Viking Field 53°26.908'N	02°19.772'E
Viking Bravo Complex BC, Block 49/17, Viking Field 53°26.874'N	02°19.854'E
Viking Bravo Complex BD, Block 49/17, Viking Field 53°26.802'N	02°19.906'E
Viking Bravo Complex BP, Block 49/17, Viking Field 53°26.837'N	02°19.881'E
Viking CD, Block 49/17, Viking 53°25.396'N Field	02°22.522'E
Viking DD, Block 49/17, Viking 53°26.469'N Field	02°23.628'E
Viking ED, Block 49/16, Viking 53°25.986'N Field	02°09.190'E
Viking GD, Block 49/17, Viking 53°26.851'N Field	02°15.291'E
Viking HD, Block 49/17, Viking 53°29.797'N Field	02°19.462'E
Viking KD, Block 49/12a, Viking 53°31.687'N Field	02°13.303'E
Viking LD, Block 49/17, Viking 53°28.494'N Field	02°13.819'E
Viscount (VO), Block 49/16, 53°23.167'N Viscount Field	02°08.910'E
Vulcan (RD), Block 49/21, Vulcan 53°14.822'N Field	02°01.387'E
Vulcan (UR), Block 48/25b, Vulcan 53°15.437'N Field	01°58.216'E

Changes to legislation: There are currently no known outstanding effects for the *The Offshore Installations (Safety Zones) Order 2018*. (See end of Document for details)

Textual Amendments

- F1** Words in Sch. Pt. 1 substituted (20.12.2018) by [The Offshore Installations \(Safety Zones\) \(No. 2\) Order 2018 \(S.I. 2018/1281\)](#), arts. 1(2), **3(1)**
- F2** Words in Sch. Pt. 1 substituted (20.12.2018) by [The Offshore Installations \(Safety Zones\) \(No. 2\) Order 2018 \(S.I. 2018/1281\)](#), arts. 1(2), **3(2)**
- F3** Words in Sch. Pt. 1 substituted (20.12.2018) by [The Offshore Installations \(Safety Zones\) \(No. 2\) Order 2018 \(S.I. 2018/1281\)](#), arts. 1(2), **3(3)**
- F4** Words in Sch. Pt. 1 substituted (20.12.2018) by [The Offshore Installations \(Safety Zones\) \(No. 2\) Order 2018 \(S.I. 2018/1281\)](#), arts. 1(2), **3(4)**

PART 2

Installations not stationed at the time the Order is made

(1) Name or other designation of the offshore installation	(2) Latitude	(3) Longitude
F5 Lancaster Turret Mooring System and Buoy, Block 205/21a, Lancaster Field	F5 60°10.79'N	F5 03°52.20'W

Textual Amendments

- F5** Words in Sch. Pt. 2 omitted (21.8.2019) by virtue of [The Offshore Installations \(Safety Zones\) \(No. 2\) Order 2019 \(S.I. 2019/1166\)](#), arts. 1(2), **4**

Changes to legislation:

There are currently no known outstanding effects for the The Offshore Installations (Safety Zones) Order 2018.