STATUTORY RULES OF NORTHERN IRELAND

2013 No. 198

CLEAN AIR

The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013

Made - - - - 19th July 2013
Coming into operation 23rd August 2013

The Department of the Environment makes the following Regulations in exercise of the powers conferred by Article 17(7) of the Clean Air (Northern Ireland) Order 1981 MI.

The Department is satisfied that the classes of fireplaces prescribed in column (1) of the Schedule can, subject to the conditions prescribed in column (2) of the Schedule, be used for burning fuel other than authorised fuels M2 without producing any smoke or a substantial quantity of smoke.

Marginal Citations

M1 S.I. 1981/158 (N.I. 4)

M2 Fuels declared by the Department of the Environment to be authorised fuels for the purposes of Article 2(2) of the Clean Air (Northern Ireland) Order 1981 are specified in S.R. 2012 No. 399.

Citation and commencement

1. These Regulations may be cited as the Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 and shall come into operation on 23rd August 2013.

Exempted Fireplaces

2. The classes of fireplaces prescribed in column (1) of the Schedule shall, subject to the conditions prescribed in column (2) of the Schedule, be exempt from the provisions of Article 17 of the Clean Air (Northern Ireland) Order 1981.

Revocation

3. The Smoke Control Areas (Exempted Fireplaces) (No.2) Regulations (Northern Ireland) 2012 are revoked.

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Marginal Citations

M3 S.R. 2012 No. 379

Sealed with the official seal of the Department of the Environment on 19th July 2013.

L.S.

Department of the Environment

Wesley Shannon A senior officer of the

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

> **SCHEDULE** Regulation 2

(1) Class of fireplace

(2) Conditions

The fireplace must be installed, maintained and operated in accordance with the following specifications:

Permitted fuels (other than authorised fuels):

Any fireplace specially designed or adapted combustion of liquid fuel.

Any fireplace (other than a fireplace fired by pulverised fuel) constructed on or after 1st July 1965 and installed before 1st September 1970 and equipped with mechanical stokers, or adapted between those dates for use with such stokers.

No fuel shall be used other than that for which the mechanical stoker was designed.

Any fireplace designed to burn coal (other than a fireplace fired by pulverised coal) with a heating capacity exceeding 160 megajoules per hour constructed and installed on or after 1st July 1965 and equipped with mechanical stokers or adapted on or after that date for use with such stokers.

No fuel shall be used other than that for which the mechanical stoker was designed.

60i and manufactured by Jetmaster manual Fires Limited, Unit 2 Peacock No Trading Estate, Goodwood 1" Road, Eastleigh, Hampshire, and supplementary instruction preservatives or coatings. SO50 4NT.

reference: 106870 Issue dated February manual reference: "Part No 106872 Issue No. 1" dated May 2010.

stoves Installation and use instruction Wood logs. The fuel must "Part not contain halogenated organic No. compounds or heavy metals as 2010 a result of treatment with wood

100SE Smoke Woodburning manufactured by BB18 6BN.

Exempt The manufacturer's instruction Untreated dry wood with a Stove manual reference 100SE Issue maximum moisture content of ESSE 1. A permanent stop must be in 20%, maximum length of Engineering Limited, Long place on the secondary air inlet 200mm and maximum width or Ing, Barnoldswick, Lancashire. to prevent closure beyond the diameter of 120mm. The fuel 50% open position.

must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Ecoburn 5 SC, Hamlet Solution "Rev 02" dated April 2010. 5 SC and Villager Espirit 5

Aarrow Signature 5 SC, Aarrow Instruction manual references Wood logs. The fuel must

not contain halogenated organic compounds or heavy metals as

SC Stoves manufactured by All the appliances will be a result of treatment with wood Industrial

Arada Limited, The Fire Works, fitted with a mechanical stop preservatives or coatings. Estate, to prevent closure of the air Axminster, Devon. EX13 5HU. control beyond 20mm from the closed position and 50mm beyond the fully open position.

stove manufactured Esse Barnoldswick, BB18 6BN.

controls beyond the 50% open preservatives or coatings. position must be implemented.

Acquisitions Bloomsbury 5kW Instruction manual references Wood logs. The fuel must by "01/12(PP)" dated January not contain halogenated organic Engineering Limited, 2012. The fitting of a system compounds or heavy metals as Ouzedale Foundry, Long Ing, to prevent closure of the air a result of treatment with wood-

Ouzledale Foundry, Ing. Barnoldswick, Colne, Lancashire, BB8 6BN.

Acquisitions Cannonbury 4 Installation and Operating Wood logs. The fuel must manufactured by Instruction manual reference not contain halogenated organic Esse Engineering Ltd, The "v71 of 09/11/2010" dated compounds or heavy metals as Long 09/11/2010.

a result of treatment with woodpreservatives or coatings.

AW1MF manufactured by ACR "AW1MF Heat Products Ltd, Unit 1 3"

0101 dated 28/01/2013. Tyseley, Birmingham, B11 3RP. closure of the secondary air preservatives or coatings. control lever beyond 12mm open must be implemented.

ACR Astwood Multifuel stove Instruction manual references Wood logs. The fuel must Version not contain halogenated organic A compounds or heavy metals as Weston Works, Weston Lane, mechanical stop to prevent a result of treatment with wodd-

Asgï;½rd 1D, 2D and 7D wood "Pevex1001/AH/ver1" burning stoves manufactured by dated June 2011. 8220, Brabrand, Denmark.

ensure that the primary and preservatives or coatings. secondary air controls do not close beyond 95% and 50% respectively.

Aduro 3D, 8D, 10D, 11D and Instruction manual references Dry wood logs. The fuel must and not contain halogenated organic compounds or heavy metals as Aduro A/S, Silkeborgvej 765 Fitted with permanent stops to a result of treatment with wood-

manufactured by Aduro A/ "Pevex1002/AH/ver1" S, Silkeborgvej 765 8220, dated June 2011. Brabrand, Denmark.

ensure that the primary and preservatives or coatings. secondary air controls do not close beyond 95% and 50% respectively.

Aduro 9D wood burning stove Instruction manual references Dry wood logs. The fuel must and not contain halogenated organic compounds or heavy metals as Fitted with permanent stops to a result of treatment with wood-

1208 Kak Tak Commercial 21st December 2011. Building 317-319 Des Voeux Road, Central Hong Kong 999077.

Alberg 7 manufactured by Elite Instruction manual references Wood logs. The fuel must Group Trading Limited, Room "EGTL03A Version 1.4" dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

SE Wood Burning Stove.

Alpha I model number AL905- Instruction manual references Wood logs. The fuel must "HF277-SE/UK-NI-ROI/

not contain halogenated organic

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Manufactured by Hi-Flame V2D.18-07-12" Fireplace UK Limited

Unit 5A

Business Park Manor Lane Holmes Chapel

Cheshire

dated July compounds or heavy metals as 2012.

Holmes Chapel Fitted with a mechanical stop to preservatives or coatings. prevent closure of the main air

position.

control beyond the 50% open

CW4 8AF.

SE Wood Burning Stove. Manufactured by Hi-Flame D.14-07-12" dated July 2012. Fireplace UK Limited

Unit 5A Holmes Chapel to prevent secondary air control preservatives or coatings.

Business Park Manor Lane Holmes Chapel Cheshire CW4 8AF.

"AL907-SE/UK-NI-ROI/V3-

Alpha II model number AL907- Instruction manual references Wood logs. The fuel must not contain halogenated organic compounds or heavy metals as

a result of treatment with wood-

Angus Orligno 200 18, 25, Instruction manual references "Wood logs. The fuel must 40, 60 and 80kW gasification EV-20111002" dated October not contain halogenated organic boilers manufactured by Eko- 2011. Vimar Orlanski Sp�łka z ograniczona odpowiedzialnościa, ul. Nyska 17 b 48-385 Otmuchï; ½w, Poland.

Angus Orligno 7-25kW boiler manufactured " Eko-Vimar Spï/.½łka Z ograniczona odpowiedzialnościa, ul. Nyska 17b, 48-385 Otmuch�w, Poland.

Angus Super 18, 25, 40, Instruction manual references "Wood logs. The fuel must 60 and 80kW gasification EV-20111001" dated October not contain halogenated organic boilers manufactured by Eko- 2011. Vimar Orlanski Sp�łka z ograniczona odpowiedzialnością, ul. Nyska 17 b 48-385 Otmuch�w, Poland.

Apollo Inset Limited, 194-200 Battersea October 2011. 4ND.

Fitted with a mechanical stop a result of treatment with woodclosure beyond the 20% open position, and a 70mm opening of the door rope seal to allow a constant flow of air when sold into smoke control areas.

EV-20121003" Orlanski 03/10/2012.

500 Instruction manual references Wood pellets. The fuel must dated not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

compounds or heavy metals as

a result of treatment with woodpreservatives or coatings.

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

stove Instruction manual references Wood logs. The fuel must manufactured by Chesneys "CH8K Apollo – V2" dated 31 not contain halogenated organic

> that prevents closure of the preservatives or coatings. air controls further than 40mm from open must be implemented.

compounds or heavy metals as Park Road, London, SW11 The fitting of a system a result of treatment with wood-

and 50 manufactured by Apollo installed, Incineration Systems Limited.

Apollo incinerator types 10, 25 The incinerators shall be No maintained 10-25-50".

fuel shall be used and other than wood and wood operated in accordance with shavings. The fuel must not the manufacturer's instructions contain halogenated organic dated 2nd November 1992 and compounds or heavy metals as bearing the reference "Apollo a result of treatment with woodpreservatives or coatings.

Arimax Bio 300kW Arimax Bio 400kW Arimax Bio 500kW boilers PO Box 59, Fin - 43101, dated 30/03/2010. Saarijarvi.

"INSTALLATION **OPERATION**

Instruction manual references 6-8mm wood pellets with a AND moisture content less than MANUAL 10%. The fuel must not Manufactured by Artierm Oy, Arimax Bio 120-3000kW" contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

stove and Neptuni 6kW pellet "ARITERM-SP-PX26868stove manufactured by Ariterm B.2" dated 15/12/2011. Sweden AB, Flottiljvï,½gen 15, 392 41 Kalmar, Sweden.

Ariterm Ekerum 6kW pellet Instruction manual references Wood pellets. The fuel must

not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

stove manufactured by Ariterm "ARITERM-SP-PX26868-Sweden AB, Flottiljvï; ½gen B.1" dated 15/12/2011. 15, 392 41 Kalmar, Sweden.

Ariterm Mysinge 6kW pellet Instruction manual references Wood pellets. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Biomass Limited, Unit 12, dated 06/2009. 35 Pinfold Road, Thurmaston, Leicester, LE4 8AT.

manufactured by Ashwell "ASH-gt150/101 Version 1.2"

Ashwell Green-Tec 150 boiler Instruction manual reference Wood pellets. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

manufactured by Biomass Limited, Unit 12, dated 06/2009. 35 Pinfold Road, Thurmaston, Leicester, LE4 8AT.

Ashwell Green-Tec 195 boiler Instruction manual reference Ashwell "ASH-gt195/102 Version 1.2"

Wood pellets. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Ashwell Green-Tec 300 boiler Instruction manual reference Wood pellets. The fuel must manufactured by Biomass Limited, Unit 12, dated 06/2009. 35 Pinfold Road, Thurmaston, Leicester, LE4 8AT.

Ashwell "ASH-gt300/103 Version 1.2"

not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Avalon 4 stove manufactured Instruction manual references Wood logs. The fuel must Hunter Stoves Trevilla Park, Slaughterbridge, 13/06/2012. 9TT.

Ltd, "JINAVA04 RevC" stop that prevents closure of preservatives or coatings. the secondary air slider beyond 30% open.

dated not contain halogenated organic The appliance compounds or heavy metals as Camelford, Cornwall, PL32 must be fitted with a permanent a result of treatment with wood-

Avalon 5 manufactured by Stoves Ltd, Trevilla Park, 13/06/2012. Slaughterbridge, Camelford, Cornwall, PL32 9TT.

slimline stove Instruction manual references Wood logs. The fuel must Hunter "JINAVS05 RevC"

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Avalon 6 stove manufactured Instruction manual references Wood logs. The fuel must Stoves Trevilla Park, Slaughterbridge, 13/06/2012. Camelford, Cornwall, PL32 9TT.

Ltd, "JINAVA06 RevC"

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

manufactured Stoves Ltd, Trevilla Park, 13/06/2012. Slaughterbridge, Cornwall, PL32 9TT.

RevC" Hunter "JINAVC05 stop that prevents closure of preservatives or coatings. the secondary air slider beyond 30% open.

Avalon Compact 5 stove Instruction manual references Wood logs. The fuel must dated not contain halogenated organic The appliance compounds or heavy metals as Camelford, must be fitted with a permanent a result of treatment with wood-

Avalon slimline manufactured Stoves Ltd, Trevilla Park, 27/06/2012. Slaughterbridge, Camelford, Cornwall, PL32 9TT.

8 stove Instruction manual references Wood logs. The fuel must Hunter "JINAVS08 rev B" dated not contain halogenated organic

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Biomass Limited.

reference BIOMASS".

B9 Wood Chip Gasifer Unit The manufacturer's instructions No fuel shall be used other than manufactured by B9 Energy dated 2002 and bearing the untreated wood chips, shredded "001/B9ENERGY wood or small untreated pieces of wood.

ECO 52 Barbas Hallenstraat 17, 5531 AB 2010. Bladel, The Netherlands.

manufactured by Interfocos, "02 - 327332" dated March not contain halogenated organic

Stove Instruction manual references Wood logs. The fuel must compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Barbas Unilux-3 40, 5kW The Unilux-3 40 Instruction Wood logs. The fuel must Interfocos BV, Hallenstraat Manual, document Version preservatives or coatings. 17, NL-5531, AB, BLADEL, 01-327332 dated October 2009. Netherlands.

wood burning insert and Barbas Manual, document Version not contain halogenated organic ECO 40, 5kW wood burning 01-326587 dated August 2009. compounds or heavy metals as roomheater manufactured by The ECO 40 Instruction a result of treatment with wood

Barbas Unilux 3- 52 Stove Instruction manual references Wood logs. The fuel must Hallenstraat 17, 5531 AB 2010. Bladel, The Netherlands.

manufactured by Interfocos, "03 - 326587" dated March not contain halogenated organic

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Hampstead LS 8, Hampstead October 2011. Limited, 194-200 Battersea air controls further than

manufactured by Chesneys that prevents closure of the preservatives or coatings.

Barrington 8, Belgravia 8, Instruction manual references Wood logs. The fuel must Flatford 8, Hampstead 8, "CH8K – V12" dated 31 not contain halogenated organic compounds or heavy metals as XLS 8, and Petworth 8 stoves The fitting of a system a result of treatment with wood-

4ND.

Park Road, London SW11 40mm from open must be implemented.

Baxi Bioflo Salzburg, Austria.

by Windhager Zentralheizung references "720574401" dated not contain halogenated organic GmbH, Anton-Windhager-Str. 2010 and installation and compounds or heavy metals as 20, A-5201 Seekirchen bei servicing instruction manual a result of treatment with wood-"720574501" dated 2010.

manufactured Operating instruction manual Wood pellets. The fuel must preservatives or coatings.

5, Be Modern Monterrey "OCT10/GB" dated Multi Fuel Shropshire, SY1 3AB.

manufactured by Broseley Fires the closure of the secondary preservatives or coatings. Ltd, Knights Way, Battlefield air flaps to be less than Enterprise Park, Shrewsbury, 8mm open position should be implemented.

Be Modern Monroe 5, Monroe Instruction manual references Wood logs. The fuel must not contain halogenated organic 5, Monterrey 5 and York 6th October 2010. The fitting compounds or heavy metals as Stoves of a system that prevents a result of treatment with wood-

Be Modern Monterrey 7, Instruction manual references Wood logs. The fuel must Broseley Fires Ltd, Knights the secondary air flaps to be preservatives or coatings. Park, Shrewsbury, Shropshire, should be implemented. SY1 3AB.

Way, Battlefield Enterprise less than 10mm open position

Monterrey 7, Be Modern "OCT10/GB" dated 6th October not contain halogenated organic Monroe 7 and Monroe 7 Multi 2010. The fitting of a system compounds or heavy metals as Fuel Stoves manufactured by that prevents the closure of a result of treatment with wood-

Beech Oven manufactured by Beech dated Australia.

3rd March Wood Fired Ovens, Brisbane, and bearing the reference "BBP236UK".

Wood Fired Pizza The manufacturer's instructions No fuel shall be used other than 2000 untreated dry hardwood.

Binder Wood Fired models Binder Gesellschaft Installation, mit beschri; 1/2nkter Haftung and (GmbH) of Austria.

Boiler The manufacturer's and Wood Wood Maintenance" 17th May 2005. bearing the reference WELBinderManualrev0.doc, revision 0.

pellets 22-49 Energy Limited's instructions chips. The fuel must not (49kW output), manufactured entitled "Binder Equipment contain halogenated organic Commissioning compounds or heavy metals as dated a result of treatment with wood and preservatives or coatings.

Binder Wood Boiler models 80-175 (75-149kW cyclone with ZA 80-175, manufactured and Gesellschaft 17th mit beschri; ½nkter Haftung WELBinderManualrev0.doc, (GmbH) of Austria.

Fired The manufacturer's and Wood Wood models Installation, Maintenance" revision 0.

pellets wood or RRK Energy Limited's instructions chips. The fuel must not output) entitled "Binder Equipment contain halogenated organic Commissioning compounds or heavy metals as dated a result of treatment with wood May 2005 reference preservatives or coatings.

Binder Wood Fired Boiler The 130-250 Wood 200-350 (250-300kW output), Installation,

manufacturer's Energy

and Wood pellets Limited's chips. The fuel must not (185-230kW output), RRK instructions "Binder Equipment contain halogenated organic Commissioning compounds or heavy metals as

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

RRK 400-600 (350-500kW and output) and RRK 640-850 17th (650-840kW output) cvclone model ZA. manufactured by Binder Gesellschaft mit beschrï; ½nkter Haftung (GmbH) of Austria.

Maintenance" dated a result of treatment with wood May 2005, reference preservatives or coatings. with WELBinderManualrev0.doc, type revision 0.

Limited's Wood

Binder Wood Fired Boiler The model RRK 1000 (1200kW Wood model MZA, manufactured Installation, Gesellschaft and by Binder mit beschri; ½nkter Haftung 17th (GmbH) of Austria.

manufacturer's Energy Maintenance" WELBinderManualrev0.doc, revision 0.

Energy

instructions

and Wood pellets or wood Limited's chips. The fuel must not output), with multi-cyclone instructions "Binder Equipment contain halogenated organic Commissioning compounds or heavy metals as dated a result of treatment with wood May 2005, reference preservatives or coatings.

pellets

for chips. The fuel must not

wood

or

Binder Wood Fired Boiler Wood 1200-1650 operating model RRK Binder model MZA Binder Appliances referenced: contain halegonated organic multicyclone and automatic 2009 July Binder O&M compounds or heavy metals as manufactured by revision8.doc Operation and a result of treatment with wood mit Maintenance Manual, Revision preservatives or coatings. Binder Gesellschaft beschrï;½nkter Haftung 8, dated 15 July 2009. (GmbH) of Austria.

Limited's Wood Energy instructions Gesellschaft mit beschij. ½nkter Maintenance Manual, Revision preservatives or coatings.

8, dated 15 July 2009.

pellets or for chips. The fuel must not multicyclone Binder appliances referenced: contain halegonated organic July Binder O&M compounds or heavy metals as Binder revision8.doc Operation and a result of treatment with wood

pellets

Binder Wood Fired Boiler Wood model RRK 1800-2300 Binder operating model MZA and automatic ignition 2009 Haftung (GmbH) of Austria.

Binder Wood Fired Boiler Wood model RRK 2500-3000 Binder operating model MZA ignition 2009 and manufactured Haftung (GmbH) of Austria.

220 and fitted with Zyklovent 220-250 dated April 2005, reference planed wood shavings. cyclone separator manufactured Bedienungsanleitung Englisch The **HERZ** Armaturen v2.0 doc. Ges.m.b.H, Gesch�ftsbereich HERZ,

Sebersdorf 138, Austria. Biomatic 300. 350. 500 fitted

A-8272

Feuerungstechnik,

Limited's Wood Energy for chips. The fuel must not instructions multicyclone Binder appliances referenced: contain halegonated organic July Binder O&M compounds or heavy metals as Binder revision8.doc Operation and a result of treatment with wood Gesellschaft mit beschij. ½nkter Maintenance Manual, Revision preservatives or coatings. 8, dated 15 July 2009.

250 The manufacturer's instructions Chipped wood, wood pellets or

fuel must contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

400 The manufacturer's instructions Chipped wood, wood pellets or with dated April 2005, reference planed wood shavings. Zyklovent 300-500 cyclone Bedienungsanleitung Englisch The separator manufactured by v2.0 doc.

fuel must contain halogenated organic

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

HERZ Armaturen Ges.m.b.H, Geschi; ½ftsbereich, Feuerungstechnik, A-8272 Sebersdorf 138. Austria.

Riomatic

preservatives or coatings. boiler Instruction manual references Wood pellets. The fuel must

+20manufactured by Ariterm "ARITERM-VTT-Sweden AB, S-07229-11.1" Flottiljvï, ½gen 15, 392 41 21/05/2012. Kalmar, Sweden.

not contain halogenated organic dated compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

compounds or heavy metals as

a result of treatment with wood

and Biomatic +20 ultra light "ARITERM-VTTboiler manufactured by Ariterm S-07229-11.2" Sweden AB Flottiljvï₆½gen 15, 21/05/2012. 392 41 Kalmar, Sweden.

Biomatic +20 light boiler Instruction manual references Wood pellets. The fuel must

not contain halogenated organic dated compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Biomatic +40boiler Instruction manual references Wood pellets. The fuel must manufactured by Ariterm "ARITERM-VTT-Sweden AB S-06765-11.1" Flottiljvï, ½gen 15, 392 41 21/05/2012. Kalmar, Sweden.

not contain halogenated organic dated compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Biomatic +40 light boiler Instruction manual references Wood pellets. The fuel must and Biomatic +40 ultra light "ARITERM-VTTboiler manufactured by Ariterm S-06765-11.2" Sweden AB Flottiljvi; ½gen 15, 21/05/2012. 392 41 Kalmar, Sweden.

not contain halogenated organic dated compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

4 9kW Stove Instruction manual reference Wood logs. The fuel must Roru Righpur "BFF010" dated 26/01/2011. Limited, T/A Boru Stoves, The The air controls must be fixed compounds or heavy metals as Hive, Ballydine, Gooldscross, such that they can't be closed a result of treatment with woodmore than:

not contain halogenated organic preservatives or coatings.

- manufactured by Ireland.
- Primary air slide 2mm - Secondary air slide 2mm
- Tertiary air slide 30%.

(also known as Navitron "BUR/11/10" dated October not contain halogenated organic Stalham 8kW), manufactured 2011. by Burley Appliances, Lands' End Way, Oakham, Rutland, LE15 6RB.

Burley Brampton 8kW stove Instruction manual references Wood logs. The fuel must compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Appliances, Lands' End Way, hole must be 19mm. Oakham, Rutland, LE15 6RB.

(also known as Navitron Bacton "BUR/11/10" dated October not contain halogenated organic 4kW), manufactured by Burley 2011. The radius of the air inlet compounds or heavy metals as

Burley Debdale 4kW stove Instruction manual references Wood logs. The fuel must a result of treatment with woodpreservatives or coatings.

6RB.

Burley Hollywell SE (also Instruction manual references Wood. The fuel must not Way, Oakham, Rutland, LE15 that prevents the tertiary air preservatives or coatings. controller from closing more

known as Navitron Cromer "BUR/11/05" dated January contain halogenated organic 5kW), manufactured by Burley 2011. The appliance must compounds or heavy metals as Appliances Ltd, Lands End be fitted with an air plate a result of treatment with wood-

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

> than 17mm and opening more than 45mm.

Bushman Large Commercial Instruction manual references Wood logs. The fuel must Pizza Oven manufactured by "LCOINST" dated 01/2011. Dingley Dell Enterprises Ltd, PO Box 3534, Kidderminster, Worcestershire, DY14 9ZE.

not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Bushman Large Pizza Oven manufactured by "LDOINST" dated 01/2011. Dingley Dell Enterprises Ltd, PO Box 3534, Kidderminster, Worcestershire, DY14 9ZE.

Domestic Instruction manual references Wood logs. The fuel must

not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Pizza Oven manufactured by "MCOINST" dated 01/2011. Dingley Dell Enterprises Ltd, PO Box 3534, Kidderminster, Worcestershire, DY14 9ZE.

Bushman Medium Commercial Instruction manual references

Wood logs. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Bushman Medium Domestic Instruction manual references Pizza Oven manufactured by "MDOINST" dated 01/2011. Dingley Dell Enterprises Ltd, PO Box 3534, Kidderminster, Worcestershire, DY14 9ZE.

Wood logs. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Bushman Small Commercial Instruction manual references Pizza Oven manufactured by "SCOINST" dated 01/2011. Dingley Dell Enterprises Ltd, PO Box 3534, Kidderminster, Worcestershire, DY14 9ZE.

Wood logs. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Bushman Small Pizza Oven manufactured by "SDOINST" dated 01/2011. Dingley Dell Enterprises Ltd, PO Box 3534, Kidderminster, Worcestershire, DY14 9ZE.

Domestic Instruction manual references Wood logs. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Stoves 9TT.

stop that prevents closure of preservatives or coatings. the secondary air slider beyond 30% open.

Camelot 4 stove manufactured Instruction manual references Wood logs. The fuel must Ltd, "JINCAM04 Rev B" dated not contain halogenated organic Trevilla Park, Slaughterbridge, 24/04/2012. The appliance compounds or heavy metals as Camelford, Cornwall, PL32 must be fitted with a permanent a result of treatment with wood-

manufactured by Slaughterbridge, Cornwall, PL32 9TT.

Hunter "JINCAC05 RevB" Stoves Ltd, Trevilla Park, 14/06/2012. The appliance compounds or heavy metals as Camelford, must be fitted with a permanent a result of treatment with woodstop that prevents closure of preservatives or coatings. the secondary air slider beyond 30% open.

Camelot 5 Compact stove Instruction manual references Wood logs. The fuel must dated not contain halogenated organic

manufactured by Trevilla Park, 15/06/2012. Stoves Ltd. Slaughterbridge, Camelford, Cornwall, PL32 9TT.

slimline stove Instruction manual references Wood logs. The fuel must Hunter "JINCAS05 RevB"

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Camelot 6 stove manufactured Instruction manual references Wood logs. The fuel must Stoves Trevilla Park, Slaughterbridge, 24/04/12. Camelford, Cornwall, PL32 9TT.

Ltd. "JINCAM06 Rev B" dated not contain halogenated organic

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Camelot slimline manufactured by Stoves Ltd, Trevilla Park, 27/06/12. Slaughterbridge, Camelford, Cornwall, PL32 9TT.

8 stove Instruction manual references Wood logs. The fuel must Hunter "JINCAS08 revB"

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Carillon 4:3 manufactured by Instruction manual references Wood logs. The fuel must 104 M. Precalcino, 36030 December 2010. Vicenza, Italy.

La Nordica Spa, Via Summano "7196755-Rev.09" dated 22nd not contain halogenated organic to prevent closure of the preservatives or coatings.

secondary air control beyond

the 40% open position.

compounds or heavy metals as Fitted with a mechanical stop a result of treatment with wood-

Carillon 16:9 Spa, Via Summano 104 M. December 2010. Precalcino, 36030 Vicenza, Italy.

manufactured by La Nordica "7196755-Rev.09" dated 22nd not contain halogenated organic

to prevent closure of the preservatives or coatings. secondary air control beyond the 40% open position.

Crystal Instruction manual references Wood logs. The fuel must compounds or heavy metals as Fitted with a mechanical stop a result of treatment with wood-

Carron 11kW SE Hurlingham Business Park, September Heath, Grantham, Exempt)". Fulbeck Lincolnshire, NG32 3HL.

2012 Α the secondary preventing beyond 4mm open must be implemented.

Stove Instruction manual references Wood logs. The fuel must manufactured by JIG UK Ltd, "Carron 11kW Stove model not contain halogenated organic (Smoke compounds or heavy metals as modification a result of treatment with woodair preservatives or coatings.

by Jig UK Limited, Hurlingham "BHC401-406" Business Park, Fulbeck Heath, January 2011. Grantham, Lincolnshire, NG32 3HL.

dated Fitted with a system preventing a result of treatment with woodthe closure of the secondary preservatives or coatings. air control openings beyond

Carron Dante SE Manufactured Instruction manual references Wood logs. The fuel must 12th not contain halogenated organic compounds or heavy metals as

Carron Stove manufactured by Instruction manual references Dry and split wood logs Jig UK Limited Hurlingham "91-62351" dated July 2009. Business Park, Fulbeck Heath,

14mm.

of a maximum length of 23cm. The fuel must not contain halogenated organic

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Grantham, Lincolnshire NG32 3HL.

by Jig UK Limited, Hurlingham "BHC501-506" Business Park, Fulbeck Heath, January 2011. 3HL.

 12^{th} dated

the closure of the secondary air preservatives or coatings. control openings beyond 3mm.

compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Carron Stove SE Manufactured Instruction manual references Wood logs. The fuel must not contain halogenated organic compounds or heavy metals as Grantham, Lincolnshire, NG32 Fitted with a system preventing a result of treatment with wood-

by Hunter Stoves Limited, Unit "JINHCE08 6, The Old Mill Industrial 06/12/11 Devon, EX5 4RJ.

CB800 Skagen manufactured Instruction manual references Wood logs. The fuel must revE" and Estate, Stoke Canon, Exeter, manual "JINHCE08SCK revB" a result of treatment with wooddated 06/12/11.

Fitted with smoke control area kit "JHCE0801" when sold into smoke control areas.

dated not contain halogenated organic instruction compounds or heavy metals as preservatives or coatings.

150 and 200 manufactured by published in CBR Engineers Limited.

CBR Flexifuel Heater, models The manufacturer's instructions (a) 1989 Flexifuel 150/200/1989".

and No fuel shall be used other than bearing the reference "FF/CBR hardwood or softwood offcuts, or chipboard. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings;

(b)

The fireplaces shall not be used to burn sawdust in bulk.

CBR Flexifuel Heater, models The by CBR Engineers Limited.

manufacturer's (a) 300, 400 and 600 manufactured instructions, published in 1987 No fuel shall be used other than and bearing the reference "FF/ hardwood or softwood offcuts." CBR Flexifuel 87".

or chipboard. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings;

(b)

The fireplaces shall not be used to burn sawdust in bulk.

Engineers Limited.

CBR Turbo Heat, models The manufacturer's instructions (a) Heat 88".

200, 300, 400, 500, 600 and published in 1988 and bearing No fuel shall be used other than 800 manufactured by CBR the reference "FF/CBR Turbo hardwood or softwood offcuts, or chipboard. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings;

The fireplaces shall not be used to burn sawdust in bulk.

Charnwood C-Four & Sons Ltd, Bishops Way, Newport, Isle of Wight, PO30 5WS.

manufactured by A.J Wells "CFOUR V1" dated 08/2011.

stove Instruction manual references Wood logs. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

C-Five Charnwood PO30 5WS.

Burning Stove manufactured by "C-series v2" dated 09.12. not contain halogenated organic A.J. Wells & Sons Ltd, Bishops Fitted with a mechanical stop compounds or heavy metals as Way, Newport, Isle of Wight, to prevent air control opening a result of treatment with woodclosure beyond the 58mm open preservatives or coatings. position when sold into smoke control areas.

Wood Instruction manual references Wood logs. The fuel must

C-Six Charnwood & Sons Ltd, Bishops Way, 2012. 5WS.

prevents the closure of the air preservatives or coatings. control opening beyond 58mm of the open position must be implemented.

stove Instruction manual references Wood logs. The fuel must manufactured by A.J. Wells "Ref. C-4 C-6 v1" dated March not contain halogenated organic compounds or heavy metals as Newport, Isle of Wight, PO30 The fitting of a system that a result of treatment with wood-

PO30 5WS.

closure beyond the 64mm open preservatives or coatings. position when sold into smoke control areas.

Charnwood C-Seven Wood Instruction manual references Wood logs. The fuel must Burning Stove manufactured by "C-series v2" dated 09.12. not contain halogenated organic A.J. Wells & Sons Ltd, Bishops Fitted with a mechanical stop compounds or heavy metals as Way, Newport, Isle of Wight, to prevent air control opening a result of treatment with wood-

PO30 5WS.

closure beyond the 64mm open preservatives or coatings. position when sold into smoke control areas.

Charnwood C-Eight Wood Instruction manual references Wood logs. The fuel must Burning Stove manufactured by "C-series v2" dated 09.12. not contain halogenated organic A.J. Wells & Sons Ltd, Bishops Fitted with a mechanical stop compounds or heavy metals as Way, Newport, Isle of Wight, to prevent air control opening a result of treatment with wood-

Charnwood Country 4 wood Modification PO30 5WS.

burning stove manufactured by manual references "TIS.95" not contain halogenated organic A.J Wells & Sons, Bishops dated 01/2011 and instruction compounds or heavy metals as Way, Newport, Isle of Wight, manual "Country 4 MKII" a result of treatment with wooddated 01/2011.

The appliance must be fitted with the manufacturer's smoke reduction kit when used within a smoke control area to fix the minimum aperture of the secondary air inlets to a minimum of 21mm open.

instruction Wood logs. The fuel must preservatives or coatings.

and Sons Ltd, Bishops Way, SR01. 10 Issue A".

Charnwood Cove 1SR stove Installation and Use Instruction Wood logs. The fuel must manufactured by A.J.Wells manual references "COVE 1 not contain halogenated organic

compounds or heavy metals as

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

5WS.

such that the minimum closure preservatives or coatings. of the air control is equivalent to that found with the control pushed in 15mm from the fully open position.

Newport, Isle of Wight, PO30 An adjustment of the air control a result of treatment with wood

5WS.

No. 010/AY83/S) to prevent the preservatives or coatings. airwash flaps at the back of the stove from being closed beyond 2mm.

Charnwood Island 1 stove Instruction manual references Wood logs. The fuel must manufactured by A.J. Wells "Island I.II.III 12.10 IssueB" not contain halogenated organic and Son Limited, Bishops Way, dated December 2010. Fitted compounds or heavy metals as Newport, Isle of Wight, PO30 with a stop bracket (Kit a result of treatment with wood-

5WS.

No. 010/BY83/S) to prevent the preservatives or coatings. airwash flaps at the back of the stove from being closed beyond 2mm.

Charnwood Island 2 stove Instruction manual references Wood logs. The fuel must manufactured by A.J. Wells "Island I.II.III 12.10 IssueB" not contain halogenated organic and Son Limited, Bishops Way, dated December 2010. Fitted compounds or heavy metals as Newport, Isle of Wight, PO30 with a stop bracket (Kit a result of treatment with wood-

and Son Limited, Bishops Way, dated December 2010. 5WS.

Charnwood Island 3 stove Instruction manual references Wood logs. The fuel must manufactured by A.J. Wells "Island I.II.III 12.10 IssueB" not contain halogenated organic Newport, Isle of Wight, PO30 Fitted with a stop bracket (Kit a result of treatment with wood-No. 010/CY83/S) to prevent the preservatives or coatings. airwash flaps at the back of the

compounds or heavy metals as

and Son Limited, Bishops Way, dated December 2010. Newport, Isle of Wight, PO30 5WS.

Charnwood Tor Pico stove Instruction manual references Wood logs. The fuel must manufactured by A.J. Wells "Tor & Tor Pico 12.10 IssueB" not contain halogenated organic

stove from being closed beyond

2mm.

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Charnwood Tor and Sons Ltd, Bishops Way, Issue A". Newport, Isle of Wight, PO30 5WS.

manufactured by A.J.Wells manual references "Tor 02. 10 not contain halogenated organic

stove Installation and Use Instruction Wood logs. The fuel must compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Stoves: Flatford4, Hampstead manual references "CH4K-V4" 4. Alpine also Providence 4.

sold dated 7th December 2009. as: Sunbeam 4, Dakota 4, The appliance must be fitted a result of treatment with wood with a mechanical stop to preservatives or coatings. prevent closure of the air control beyond the 34mm open

Pacific 4 also sold as: Murano 4, Apollo 4.

Chelsea 4 also sold as: position. Wellington 4, Guernsey 4, Belgravia 4.

Chesneys 4 Series (4.6kW) Chesneys 4 series Instruction Wood logs. The fuel must not contain halogenated organic compounds or heavy metals as

Manufactured by Chesneys, 194-200 Battersea Park Road, London, SW11 4ND.

Stoves: Flatford 6, Barrington Petworth 6, Hampstead Alpine 6, also sold as: Sunbeam 6. Dakota 6. also sold as: Wellington 6, position. Guernsey 6, Belgravia 6. Manufactured by Chesneys, 194-200 Battersea Park Road, London, SW11 4ND.

manual references "CH6K-V4" not contain halogenated organic 6, dated 7th December 2009. 6, The appliance must be fitted a result of treatment with wood with a mechanical stop to preservatives or coatings. 6, prevent closure of the air Providence 6 and the Chelsea control beyond the 10mm open

Chesneys 6 Series (7kW) Chesneys 6 series Instruction Wood logs. The fuel must compounds or heavy metals as

Classic 25. model 49 and (GmbH), Gunderding A-4952, Weng, Austria.

Carnaby Road, Estate. Bridlington. East Yorkshire, YO15 3QY.

Clean Air Systems CAS 300 To be operated in accordance Chipped or sawdust softwood, Limited. Lancaster Carnaby Industrial Estate. Bridlington, East Yorkshire, YO15 3QY.

Cleanburn CB900 & Cleanburn Sonderskoven Inset, Wood A" by Hunter Stoves Limited, Devon, EX5 4RJ.

35, The manufacturer's installation Wood pellets. The fuel must wood manual for the Classic Pellet not contain halogenated organic pellet boilers manufactured Boilers reference No. 22, compounds or heavy metals as by Hargassner Gesellschaft Pellet Boilers, Type Classic a result of treatment with wood mit beschrij/2nkter Haftung 25,31,35,40,49,60, reference preservatives or coatings. 8, BA Classic 25L-60L Nr 21 0508.

Clean Air Systems CAS 200, To be operated in accordance Softwood, hardwood, medium Industrial dated January 2011.

Road, version 1 dated January 2011.

Inset Instruction manual references Wood logs. The fuel must CB900 "JINHCN09 Slider Stop Rev not contain halogenated organic 17/01/12 dated burning stoves. Manufactured instruction manual "JINHCN09 a result of treatment with wood-Rev F" dated 24/01/12. Fitted preservatives or coatings. Unit 6, The Old Mill Industrial with a mechanical stop to Estate, Stoke Canon, Exeter, prevent secondary air control closure beyond the 20% open position when sold into smoke control areas.

400 and 600 hand fired with the Handbook for CAS density fibreboard (MDF) or airheaters manufactured by hand fired airheater range chipboard offcuts. The fuel Inventair Limited, Lancaster reference 24600H version 1 must not contain halogenated organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

Max airheater and cyclone with the Handbook for CAS 300 hardwood, medium density manufactured by Inventair Max airheater reference 300A fibreboard (MDF) or chipboard offcuts. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

and compounds or heavy metals as

Cleanburn R4 manufactured by Instruction manual references Wood logs. The fuel must Hunter Stoves Limited, Unit 6, "JINCLR04 Rev E" dated not contain halogenated organic

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

The Old Mill Industrial Estate, 02/12/11 EX5 4RJ.

and dated 05/12/11.

Fitted with "smoke control area

instruction compounds or heavy metals as Stoke Canon, Exeter, Devon, manual "JINCLR04SCK revB" a result of treatment with woodpreservatives or coatings.

kit JCLR0401" when sold into smoke control areas. manufactured

inset stove Instruction manual references Wood logs. The fuel must Hunter "JINCLR05 Rev B 10/12/12" not contain halogenated organic Stoves Ltd, Trevilla Park, and "JINCLR05SCK revA" compounds or eavy metals as a Camelford, dated 06/07/12. The appliance result of treatment with woodmust be fitted with smoke preservatives or coatings.

control area kit JCLR0501.

by Stoves Ltd, Trevilla Park, 10/12/12 Slaughterbridge, Cornwall, PL32 9TT.

Slaughterbridge, Cornwall, PL32 9TT.

> and dated 06/07/12. The appliance preservatives or coatings. mustbe fitted with smoke control area kit JCLR0501.

Cleanburn R6 inset stove Instruction manual references Wood logs. The fuel must Hunter "JINCLR06 Rev B" dated not contain halogenated organic instruction compounds or eavy metals as a Camelford, manual "JINCLR05SCK revA" result of treatment with wood-

stove Hunter Stoves 9TT.

Cleanburn Sonderskoven 5 Instruction manual references Wood logs. The fuel must Camelford, Cornwall, PL32 control must contain six 5mm preservatives or coatings. holes.

manufactured "JINHCN05 Rev B" dated not contain halogenated organic Ltd, 04/10/2012. The valve plate compounds or heavy metals as Trevilla Park, Slaughterbridge, adjusted by the secondary air a result of treatment with wood-

Clearburn Junior Limited. Dean Prior Buckfastleigh

Devon

TQ11 0LS.

to prevent secondary air control preservatives or coatings. closure beyond 83mm open position when sold into smoke control areas.

SE. Instruction manual references Wood logs. The fuel must Manufactured by Dean Forge "JRSE Issue 1" dated March not contain halogenated organic compounds or heavy metals as Fitted with a mechanical stop a result of treatment with wood-

Stoves Limited.

Clearview models 650 and 750 The manufacturer's instructions No fuel shall be used other than and the Vision 500 model, dated 1 January 1993 and firewood which has been split, manufactured by Clearview in the case of the Clearview stacked and air dried. models 650 and 750, bearing the reference "1/42" and in the case of Vision 500 model, bearing the reference "V1/42".

Clearview Pioneer Solution 400 and Pioneer Oven "Operating manufactured by clearview stamped and signed "Smoke coatings. Stoves of More Works, Bishops Control". Castle, Shropshire, SY9 5HH.

400, The manufacturer's instructions Air-dried wood logs. The fuel

Instructions must not contain halogenated wood burning stoves fitted Clearview Vision/Vision Inset/ organic compounds or heavy with a tamperproof mechanical Pioneer & Solution" dated 1st metals as a result of treatment stop on the air slide/damper, July 2006, reference V1/42, with wood preservatives or

Contura 510, Contura 520T, Installation Instruction IAV SE/ Untreated dry wood with less Contura 560K, Contura 570, 611820. 134, 285 23 Markaryd, Sweden. position.

Contura 580W manufactured Installation Instruction IAV SE/ Untreated dry wood with less by NIBE AB Box 134, 285 23 EX 0740-1 511911. Markaryd, Sweden.

Nibe, Box 134, S-285 23 "811064 Markaryd, Sweden.

Contura 750A manufactured Instruction manual references Wood logs. The fuel must by Nibe, Box 134, S-285 23 "811064 Markaryd, Sweden.

Contura 780 manufactured by Instruction manual references Wood logs. The fuel must Nibe, Box 134, S-285 23 "811064 Markaryd, Sweden.

Contura 810, 820 T, 850, 860 Instruction manual references Wood logs. The fuel must T, and 880, manufactured by "811118 Nibe Stoves, Box 134, S-285 23 C800-1" Markaryd, Sweden.

Markaryd, Sweden.

Contura 550, Contura 550A, EX 0726-6 611821 Lighting than 20% moisture. Contura 550W, Contura 560T, Instruction BAV SE/EX 0717-2 The

manufactured by NIBE AB Box closure beyond the 20% open preservatives or coatings.

A permanent stop must be in The position.

Contura 750 manufactured by Instruction manual references Wood logs. The fuel must BAV C750/780-1".

> with a mechanical stop to preservatives or coatings. prevent closure beyond the 28% open position.

BAV C750/780-1".

with a mechanical stop to preservatives or coatings. prevent closure beyond the 28% open position.

BAV C750/780-1". The appliance must be fitted a result of treatment with wood-

with a mechanical stop to preservatives or coatings. prevent closure beyond the 28% open position.

BAV and Supplementary operating a result of treatment with woodinstructions GB-2" dated June 2011. Fitted with a mechanical stop to prevent air control closure beyond the 38% open position.

BAV GB-2" dated June 2011. preservatives or coatings.

fuel must not contain halogenated organic Contura 580, Contura 585, A permanent stop must be in compounds or heavy metals as Contura 590, Contura 590T, place on the air inlet to prevent a result of treatment with wood

than 20% moisture.

fuel must place on the air inlet to prevent contain halogenated organic closure beyond the 20% open compounds or heavy metals as a result of treatment with wood preservatives or coatings.

SE-EX not contain halogenated organic compounds or heavy metals as The appliance must be fitted a result of treatment with wood-

SE-EX not contain halogenated organic compounds or heavy metals as The appliance must be fitted a result of treatment with wood-

> SE-EX not contain halogenated organic compounds or heavy metals as

SE-EX not contain halogenated organic dated 28-06-2011 compounds or heavy metals as "811142 BAV preservatives or coatings.

Contura i4 Modern and Contura Instruction manual references Dry wood logs. The fuel must i4 Classic manufactured by "811136 BAV C i4 GB-1" dated not contain halogenated organic Nibe Stoves, Box 134, S-285 23 04-07-2011 and supplementary compounds or heavy metals as operating instructions "811142 a result of treatment with wood-

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

> Fitted with a mechanical stop to prevent closure beyond the 28% open position.

Bishops Way, Newport, Isle of July 2009. Wight, PO30 5WS.

Cove 2 SR manufactured by Instruction manual references Dry and split wood logs of a A.J.Wells & Sons Ltd of "Cove2SR 07.09 IssB" dated maximum length of 23cm.

fully closed position.

Crator JS5500 multi-fuel stove Instruction manual references Wood logs. The fuel must dated June 2012.

The fuel must A permanent stop must be in contain halogenated organic place on air control to prevent compounds or heavy metals as closure beyond 14mm from the a result of treatment with wood preservatives or coatings.

stove not contain halogenated organic instruction manual Issue 1" compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

manufactured by James Smellie "Crator multi-fuel Limited, Unit N Leona Industrial Estate Nimmings Road Halesowen West Midlands B62 9JO.

Cronspisen stove, using the The manufacturer's instructions No fuel shall be used other than 5 channel chimney system, bearing the reference "January firewood which has been split, manufactured by Cronspisen 1992 Serial No. UM 351B". Produktion AB.

stacked and air dried.

Box 313, S-341 26 Ljungby, reference 161 505 27 06/1. Sweden.

manufactured by Enertech AB, dated 20th February 2007.

CTC Ecoflex 15 and 20 The manufacturer's instructions Wood pellets. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

D'Alessandro GSA manufactured by D'Alessandro "2.0-1-QGSA130XEN0612" Termomeccanica, Cerreto, 55, 66010 Miglianico, Chieti, Italy.

130 Instruction manual references Contrada dated 26/06/2012.

Wood chips. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

CS CSA and 180. 230 and manufactured by D'Alessandro dated 02/2009. Termomeccanica, Contrada Cerreto, 55, 66010 Miglianico, Chieti, Italy.

D'Alessandro Termomeccanica Instruction manual references " 130, Ver. 2.0 – QCSA2000XEN0209

Wood pellets. The fuel must not contain halogenated organic 300kW [UK SMOKE CONTROL]" compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

D'Alessandro Termomeccanica Instruction manual references "Wood pellets. The fuel must manufactured by D'Alessandro dated 02/2009. Termomeccanica, Cerreto, 55, 66010 Miglianico, must be fitted. Chieti, Italy.

CS and CSA 400, 500, 650, 800, Ver. 2.0 – QCSA 2000 XEN 0209 not contain halogenated organic 950, 1300, 1650 and 2000kW [UK SMOKE CONTROL]" compounds or heavy metals as

Contrada The optional multi-cyclone preservatives or coatings.

a result of treatment with wood-

CS and CSA

D'Alessandro Termomeccanica Instruction manual references "Wood pellets. The fuel must Ver. 2.0 – QCSA100XXIT0209 not contain halogenated organic compounds or heavy metals as

manufactured by D'Alessandro dated 02/2009. Termomeccanica, Contrada Cerreto, 55, 66010 Miglianico,

Chieti, Italy.

D'Alessandro Termomeccanica Instruction manual references Wood pellets. The fuel must CSI 20kW manufactured by "Ver. D'Alessandro Termomeccanica.

Cerreto, 55, 66010 Miglianico, Chieti, Italy.

Dartmoor 5 SE stove. Manufactured by Dean Forge "DM5 Issue 1" dated March not contain halogenated organic Limited

Dean Prior Buckfastleigh

Devon TQ11 0LS.

by VWC International Limited. dated

Burning Stove. Gonay Limited, Rue De Lambinon, 3 Harze.

Belgium 4920.

EX5 4RJ.

boilers 40, 60, 80 and 100kW [UK SMOKE CONTROL]" a result of treatment with wood-

2.0 OCSI100XXIT0209"

Contrada 02/2009.

Instruction manual references Wood logs. The fuel must 2012

to prevent secondary air control preservatives or coatings. closure beyond the 30% open position when sold into smoke

control areas

November and bearing the reference stacked and air-dried.

"200-8632".

Design 800 Green, Wood Instruction manual reference Wood logs. The fuel must "07DH8000A" dated 11/11. when sold into smoke control preservatives or coatings.

areas.

The Old Mill Industrial Estate, 02/12/11 and dated 05/12/11.

Fitted with "smoke control area kit JDLU0401" when sold into smoke control areas

Di Lusso R5 inset stove Instruction manual references Wood logs. The fuel must manufactured by Stoves Ltd, Trevilla Park, 10/12/12 Slaughterbridge, Cornwall, PL32 9TT.

and revA" dated 06/07/2012. The preservatives or coatings. must be fitted appliance with smoke control area kit JDLU0501.

Di Lusso R6 inset stove Instruction manual references Wood logs. The fuel must manufactured by

preservatives or coatings.

 not contain halogenated organic dated compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

compounds or heavy metals as Fitted with a mechanical stop a result of treatment with wood-

Defiant Encore manufactured The manufacturer's instructions No fuel shall be used other than 1991 firewood that has been split.

not contain halogenated organic Manufactured by Bodart & Fitted with a "UK kit for compounds or heavy metals as smokeless areas Design 800" a result of treatment with wood-

Di Lusso R4 manufactured by Instruction manual references Wood logs. The fuel must Hunter Stoves Limited, Unit 6, "JINDLU04 Rev E" dated not contain halogenated organic instruction compounds or heavy metals as Stoke Canon, Exeter, Devon, manual "JINDLU04SCK revB" a result of treatment with woodpreservatives or coatings.

> Hunter "JINDLU05 Rev B" dated not contain halogenated organic additional compounds or heavy metals as Camelford, instructions "JINDLU05SCK a result of treatment with wood-

Hunter "JINDLU06 RevB" dated not contain halogenated organic

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Cornwall, PL32 9TT.

Slaughterbridge, Camelford, manual "JINDLU05SCK revA" a result of treatment with wood-06/07/2012. dated appliance must be fitted with smoke control area kit JDLU0501.

Stoves Ltd, Trevilla Park, 10/12/2012 and instruction compounds or heavy metals as The preservatives or coatings.

Dimplex Langbrook Southampton.

5kW Instruction manual references Wood logs. The fuel must Clean Burn Stove manufactured "08/51568/0 – Issue 3" dated not contain halogenated organic by Dimplex, GDC Group 28 Jun 2012. Fitted with a compounds or heavy metals as Limited, Millbrook House, mechanical stop to prevent a result of treatment with wood-Grange Drive, Hedge End, secondary air control slider preservatives or coatings. closure beyond the 40% open position when sold into smoke control areas.

Dimplex SE Selborne manufactured stove ESSE Engineering Ouzledale Foundry, BB18 6BN.

by "SE Selbourne 5 Issue 1" dated not contain halogenated organic Ltd, 08 2009. Long All appliances will be fitted a result of treatment with wood Ing, Barnoldswick, Lancashire, with a mechanical stop to preservatives or coatings. prevent closure beyond the 50% open position when sold into

5 Instruction manual references Wood logs. The fuel must compounds or heavy metals as

Dovre 250 (model DV-250) The Nijverheidsstraat 18, BE-2381 Issue 1. Weelde, Belgium.

smoke control areas.

to prevent closure beyond the coatings. 75% open position.

manufacturer's Untreated dry wood. The fuel manufactured by Dovre NV, instructions, reference PM 250 must not contain halogenated organic compounds or heavy A permanent stop must be in metals as a result of treatment place on the secondary air inlet with wood preservatives or

Dovre Vintage 30 (DV-VIN30, Instruction manual references Wood logs. The fuel must DV-VIN30WH, DV-TBVIN30 03.27681.100 dated April 2011 not contain halogenated organic and DV-TBVIN30WH), Dovre and PM813 Issue 1 dated May compounds or heavy metals as Vintage 35 (DV-VIN35, DV- 2012 and when fitted with a result of treatment with wood-VIN35WH, DV-TBVIN35 and a permanent stop preventing preservatives or coatings. DV-TBVIN35WH) and Dovre closure of the secondary air Vintage 50 DV-VIN50WH, DV-TBVIN50 and DV-TBVIN50WH) stoves manufactured by Dovre N.V. Nijverheidsstraat 18, B-2381 Weelde, Belgium.

(DV-VIN50, supply beyond 50%.

Dovre Castings Limited.

Dovre woodstove models 500G The manufacturer's instructions No fuel shall be used other and 700G manufactured by dated October 1995 bearing the than wood. The fuel must following reference—

model 500G: "500G";

model 700G: "700G".

not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Stove manufactured by Dunsley dated Heat Limited.

Dunsley Yorkshire Multifuel The manufacturer's instructions Untreated dry wood. Peat or 1998, peat briquettes with, in either 5th August reference A/22160 as amended case, less than 25% moisture. by those dated 4th December Union 2004, reference D13.

Coal Briquettes. manufactured by Rheinbraun AG of Germany comprising lignite compressed briquettes of approximately 15cm in length with square ends and with a sulphur content not exceeding 1% of the total

weight.

CPL Wildfire, manufactured by Coal Products Limited, Immingham, which comprise bituminous coal with a volatile content of 32% to 36% (as to approximately 96% of the total weight) and a cold cure resin binder (as to the remaining weight); are manufactured from those constituents by a process involving roll-pressing; have an average weight of either 80-90 grams or 160-170 grams; and have a sulphur content not exceeding 1.8% of the total weight.

Stove and Boiler manufactured dated by Dunsley Heat Limited.

August by those dated October 2004, reference GHD/ DUN4B/1.

Dunsley Yorkshire Multifuel The manufacturer's instruction Untreated dry wood. The fuel must not contain halogenated reference A/22160, as amended organic compounds or heavy 4th metals as a result of treatment with wood preservatives or coatings.

> Peat or peat briquettes with, in either case, less than 25% moisture

> Union Coal Briquettes, manufactured by Rheinbraun AG of Germany comprising lignite compressed briquettes of approximately 15cm in length with square ends and with a sulphur content not exceeding 1% of the total weight.

> CPL Wildfire, manufactured by Coal Products Limited, Immingham, which comprise bituminous coal with a volatile content of 32% to 36% (as to approximately 96% of the

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

> total weight) and a cold cure resin binder (as to the remaining weight); are manufactured from those constituents by a process involving roll-pressing; have an average weight of between 80-90 grams or between 160-170 grams; and have a sulphur content not exceeding 1.8% of the total weight.

Dunsley Yorkshire manufactured by Dunsley Heat dated Limited.

Stove, The manufacturer's instructions Untreated dry wood. Peat or 1998. August reference A/22160 as amended case, less than 25% moisture. by those dated 4th December 2004, reference D13.

peat briquettes with, in either Union Coal Briquettes, manufactured by Rheinbraun AG of Germany comprising lignite compressed briquettes of approximately 15cm in length with square ends and with a sulphur content not exceeding 1% of the total weight.

CPL Wildfire, manufactured by Coal Products Limited, Immingham, which comprise bituminous coal with a volatile content of 32% to 36% (as to approximately 96% of the total weight) and a cold cure resin binder (as to the remaining weight); are manufactured from those constituents by a process involving roll-pressing; have an average weight of either 80-90 grams or 160-170 grams; and have a sulphur content not exceeding 1.8% of the total weight.

Dunsley Woodburning manufactured by Dunsley Heat reference D13W. Limited.

Yorkshire The manufacturer's instructions Untreated dry wood. The fuel

Stove, dated 4th December 2004, must not contain halogenated organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

Dunsley Limited.

Yorkshire The manufacturer's instructions Untreated dry wood. The fuel 2004 4th October reference GHD/DUN4B/1.

Woodburning Stove and Boiler dated 4th December 2004, must not contain halogenated manufactured by Dunsley Heat reference D13W together with organic compounds or heavy the manufacturer's instructions metals as a result of treatment with wood-preservatives or coatings.

Unit One Weston Works, dated 02 2009. Weston Lane. Birmingham B11 3RP.

Earlswood manufactured by Instruction manual reference Wood logs. The fuel must ACR Heat Products Limited, "EW 1MF technical manual" not contain halogenated organic

> Tyseley, When the primary air control is a result of treatment with wood in the closed position, it remains preservatives or coatings. permanently open by 5mm and is prevented from closing fully by a screw.

compounds or heavy metals as

Foster House, 2 Redditch Road, 12/12/11. Studley, Warwickshire, B80 7AX.

Ecco Stove E580 Manufactured Instruction manual reference Wood logs. The fuel must by Landy Vent UK Limited, "Ecco Stove 580 manual" dated not contain halogenated organic

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Ecco Stove E678 manufactured Instruction manual references Wood logs. The fuel must by Landy Vent UK Limited, "01/11/3" dated 28/01/2011. 7AX.

Foster House, 2 Redditch Road, Fitted with a system to fix the compounds or heavy metals as Studley, Warwickshire, B80 secondary air (airwash) to a a result of treatment with wood-4mm open position.

not contain halogenated organic preservatives or coatings.

Ecco Stove E850 manufactured Instruction manual references Wood logs. The fuel must 7AX.

prevents the closure of the preservatives or coatings. secondary air flaps beyond 4mm (3 turns).

by Landy Vent UK Limited, "02/10" dated 10th October not contain halogenated organic Foster House, 2 Redditch Road, 2010. The appliance must be compounds or heavy metals as Studley, Warwickshire, B80 fitted with a system that a result of treatment with wood-

Eclipse Junior, Northern Incinerators Limited. 88".

Standard, The manufacturer's instructions No fuel shall be used, other

Senior, Jumbo 30 and Jumbo 50 dated 21 June 1988 and bearing than fuel consisting of scrap incinerators, manufactured by the reference "NORCIN TECH wood and foliage. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

stove boiler manufactured by "cod. 33080, Italy.

004770900" Palazzetti Lelio S.p.A, Via 10/2011 and supplementary compounds or heavy metals as Roveredo 103, Porcia (PN), information "Clean Air Act a result of treatment with wood-1993 Areas" reference 004723000 dated 01/2012.

Ecofire Barbara wood pellet Instruction manual references Wood pellets. The fuel must dated not contain halogenated organic and Smoke Control preservatives or coatings.

Ecofire Giulia Idro, Ecofire Instruction manual references Wood pellets. The fuel must Kelly Idro Plus and Ecofire "cod.004770432" dated 02/11 not contain halogenated organic wood Palazzetti Lelio S.p.A, Via Control Roveredo 103, Porcia (PN), 004723000 dated 01/2012. 33080, Italy.

Areas"

pellet and supplementary information compounds or heavy metals as stove boilers manufactured by "Clean Air Act 1993 and Smoke a result of treatment with woodreference preservatives or coatings.

Eco-Ideal manufactured by Hunter Stoves "JINECO01 Limited, unit 6, Old Mill 20/07/11.

Stove Instruction manual references Dry wood logs. The fuel must revC"

dated not contain halogenated organic compounds or heavy metals as

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Industrial Estate, Stoke Canon, The appliance must be fitted a result of treatment with wood-Exeter. Devon EX5 4RJ.

with a permanent stop that preservatives or coatings. prevents closure of the secondary air slider beyond 30% open.

Eco-Ideal Eco 2 manufactured by Hunter Stoves "JINECO02 Limited, unit 6, Old Mill 20/07/11. Exeter. Devon EX5 4RJ.

Stove Instruction manual references Dry wood logs. The fuel must revC"

with a permanent stop that preservatives or coatings. prevents closure of the secondary air slider beyond 30% open.

dated not contain halogenated organic compounds or heavy metals as Industrial Estate, Stoke Canon, The appliance must be fitted a result of treatment with wood-

Eco-Ideal Eco 4 manufactured by Hunter Stoves "JINECO04 Limited, unit 6, Old Mill 20/07/11. Industrial Estate, Stoke Canon, Exeter, Devon EX5 4RJ.

Stove Instruction manual references Dry wood logs. The fuel must revC"

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Eco-Ideal Eco manufactured by Hunter Stoves "JINECO06 Limited, unit 6, Old Mill 20/07/11. Industrial Estate, Stoke Canon, Exeter, Devon EX5 4RJ.

revC"

6 Stove Instruction manual references Dry wood logs. The fuel must dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Wood Energy Solutions Donaskeigh **Tipperary** Co. Tipperary

2012.

E-Compact 15 wood pellet Instruction manual references 6mm wood pellets. The fuel stove boiler manufactured by " E-COMPACT 15 Outdoor must not contain halogenated Pellet Boiler v1.5" dated 05 organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

E-Compact 28 Pellet Boiler Instruction manual references 6mm wood pellets. The fuel manufactured by Wood Energy "Installation & Solutions Limited, Donaskeigh, Manual V.2.1" dated 07/12. Tipperary, Co. Tipperary, Ireland.

Ireland.

Operation must not contain halogenated organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

as 8). Manufactured by Saltfire dated 24.01.2011. Stoves Limited, Units 1 and 2, The Omega Centre, Sandford Lane, Wareham, BH20 4DY.

Ekol Crystal "ECO7operation-Revision 2A"

Ecowarm Crystal 6 (also Instruction manual references Wood logs. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Ellipse manufactured by La Instruction manual references Wood logs. The fuel must M. Precalcino, 36030 Vicenza, December 2010. Italy.

Nordica Spa, Via Summano 104 "7196901-Rev.09" dated 22nd Fitted with a mechanical stop a result of treatment with woodto prevent closure of the preservatives or coatings. secondary air control beyond

not contain halogenated organic compounds or heavy metals as

the 40% open position.

USF-W Endress manufactured Industriestraï;½e 18, D-91593 dated 03/2010. Burgbernheim.

250 Instruction manual references Wood Chips by Endress "Operating and Maintenance The

pellets. and fuel must Holzfeuerungsanlagen GmbH, manual Endress USF -W250" contain halogenated organic compounds or heavy metals as Reference EMAN – USFW250. a result of treatment with woodpreservatives or coatings.

Endress USF-W manufactured bv Industriestraï;½e 18, D-91593 dated Burgbernheim.

350 Instruction manual references Wood Chips Endress "Operating and Maintenance The 03/2010 EMAN – USFW350.

and pellets. fuel must not Holzfeuerungsanlagen GmbH, manual Endress USF -W350" contain halogenated organic Reference compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

USF-W Endress manufactured bv Burgbernheim.

500 Instruction manual references Wood Endress "Operating and Maintenance The Holzfeuerungsanlagen GmbH, manual Endress USF -W500" contain halogenated organic Industriestraï¿/2e 18, D-91593 dated 03/2010 Reference compounds or heavy metals as EMAN – USFW500.

Chips and pellets. fuel must a result of treatment with woodpreservatives or coatings.

USF-W Endress Industriestra�e 18, D-91593 dated Burgbernheim.

800 Instruction manual references Wood Chips Endress "Operating and Maintenance The Holzfeuerungsanlagen GmbH, manual Endress USF -W800" contain halogenated organic 03/2010 EMAN – USFW800.

and pellets. fuel must Reference compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Endress USF-W manufactured by Industriestraï, ½e 18, D-91593 dated Burgbernheim.

1000 Instruction manual references Wood Chips Endress "Operating and Maintenance The Holzfeuerungsanlagen GmbH, manual Endress USF –W1000" contain halogenated organic 03/2010 EMAN – USFW1000.

and pellets. fuel must Reference compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Endress VR-S by Industriestraï, ½e 18, D-91593 dated Burgbernheim.

300 Instruction manual references Wood Chips Endress "Operating and Maintenance The 03/2010 EMAN – VRS300.

and pellets. fuel must not Holzfeuerungsanlagen GmbH, manual Endress VR-S300" contain halogenated organic Reference compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Endress VR-W manufactured by Industriestraï;½e 18, D-91593 dated Burgbernheim.

400 Instruction manual references Wood Chips Endress "Operating and Maintenance The 03/2010 EMAN – VRW400.

and pellets. fuel must Holzfeuerungsanlagen GmbH, manual Endress VR -W400" contain halogenated organic Reference compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

VR-W Endress bv Industriestraï₆½e 18, D-91593 dated Burgbernheim.

600 Instruction manual references Wood Chips Endress "Operating and Maintenance The 03/2010 EMAN - VRW600.

and pellets. fuel must Holzfeuerungsanlagen GmbH, manual Endress VR-W600" contain halogenated organic Reference compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Endress VR-W manufactured by Industriestra�e 18, D-91593 dated Burgbernheim.

900 Instruction manual references Wood Endress "Operating and Maintenance The 03/2010 EMAN - VRW900.

Chips and pellets. fuel must Holzfeuerungsanlagen GmbH, manual Endress VR-W900" contain halogenated organic Reference compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

En-tech model 15, 18. 25 and boilers manufactured by En- reference Gesellschaft Haftung beschr�nkter (GmbH), Gewerbezone 3, A-9300 St Veit, Glan-Hunnenbrunn, Austria.

10, The manufacturer's installation Wood pellets. The fuel must 35 manual dated **IMENP** tech Energietechnikproduktion 11/2009 for the Firefox pellet a result of treatment with wood mit boiler.

11/2009, not contain halogenated organic 10-35 compounds or heavy metals as preservatives or coatings.

boilers manufactured by En- manual tech Energietechnikproduktion reference Gesellschaft beschrï;½nkter (GmbH). Gewerbezone 3. A-9300 St Veit. Glan-Hunnenbrunn, Austria.

dated **IMPK** mit 11/2009 EN for the Firefox a result of treatment with wood Haftung pellet boiler.

En-tech model PK 15 and 25 The manufacturer's installation Wood pellets. The fuel must 11/2009, not contain halogenated organic PK15/25 compounds or heavy metals as preservatives or coatings.

En-tech model PK boilers manufactured by En- manual tech Energietechnikproduktion reference IMPK PK45 11/2009 compounds or heavy metals as Gesellschaft beschrï;½nkter Haftung (GmbH), Gewerbezone 3, A-9300 St Veit, Glan-Hunnenbrunn, Austria.

45 The manufacturer's installation Wood pellets. The fuel must dated

11/2009, not contain halogenated organic mit EN for the Firefox pellet boiler. a result of treatment with wood preservatives or coatings.

manufactured by: Uniconfort Manual v1" dated July 2011. srl, Via dell'Industria 21, 35018, San Martino Di Lupari (PD) Italy.

EOS 30 346kW output wood Use and Maintenance manual Wood pellets. The fuel must pellet boiler with multicyclone reference "Uniconfort EOS30 not contain halogenated organic

compounds or heavy metals as a result of treatment with wood preservatives or coatings.

EOS 35 407kW output wood Use and Maintenance manual Wood pellets. The fuel must manufactured by: Uniconfort Manual v1" dated July 2011. srl, Via dell'Industria 21, 35018, San Martino Di Lupari (PD) Italy.

pellet boiler with multicyclone reference "Uniconfort EOS35 not contain halogenated organic

compounds or heavy metals as a result of treatment with wood preservatives or coatings.

pellet boiler with multicyclone reference "Uniconfort EOS40 manufactured by: Uniconfort Manual v1" dated July 2011. srl, Via dell'Industria 21, 35018, San Martino Di Lupari (PD) Italy.

EOS 40 464kW output wood Use and Maintenance manual Wood pellets. The fuel must

not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

pellet boiler with multicyclone references srl, Via dell'Industria 21, 35018 September 2010. San Martino Di Lupari (PD), Italy.

Esse 100DD stove manufactured Esse Ouzedale Foundry, Long Ing, October 2011. Barnoldswick, BB18 6BN.

Ouzledale BB18 6BN.

Esse 301 SE manufactured by Long Foundry, Barnoldswick, Lancashire, BB18 6BN.

Esse 350 SE manufactured by Engineering Ltd, Ouzledale Foundry. Long Ing. Barnoldswick. Lancashire, BB18 6BN.

Esse 1622 inset manufactured by Ing, Barnoldswick, Lancashire, 2010. BB18 6BN.

EOS 60 700kW output wood Installation Instruction manual 6mm diameter wood pellets. "K135-07332 The manufactured by: Uniconfort Uniconfort MUN v 2" dated contain halogenated organic

bv "10/11 Engineering Limited, INSTR.ST-100DDSE/u" dated compounds or heavy metals as The fitting of a system to preservatives or coatings. prevent closure of the air controls beyond the 50% open position must be implemented.

Esse 125SE stove manufactured Instruction manual references Wood logs. The fuel must by Esse Engineering Ltd, "Esse 125SE Issue 1" dated 08 not contain halogenated organic Foundry, Long 2009. All appliances will be compounds or heavy metals as Ing, Barnoldswick, Lancashire, fitted with a mechanical stop to a result of treatment with word prevent closure beyond the 50% preservatives or coatings. open position when sold into smoke control areas.

stove Instruction manual references Wood logs. The fuel must Esse "v45" dated 09/11/2010. The not contain halogenated organic Engineering Ltd, Ouzledale primary air control must not be compounds or heavy metals as Ing, fully air tight when closed.

> stove Instruction manual references Wood logs. The fuel must Esse "v45" dated 09/11/2010.

stove Installation and Esse manual reference "1622/Integra not contain halogenated organic Engineering Limited, Long INSET revision c" dated July compounds or heavy metals as

All appliances used in smoke preservatives or coatings. control areas must be fitted with a mechanical stop to fix secondary air control fully open.

ETA HACK 20, 25, 35, 50, Instruction manual reference Wood chips. The fuel must beschrankter Haftung (GmbH), be used when using wood chips preservatives or coatings. A 4716, Hofkirchen an der with a moisture content below 15%.

fuel must compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

5kW Instruction manual references Wood logs. The fuel must (PP) not contain halogenated organic a result of treatment with wood-

a result of treatment with woodpreservatives or coatings.

not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

operation Dry wood logs. The fuel must a result of treatment with wood

70, 90, 130 and 200 woodchip "HACK20-200 Bedienung 201 In Obcolin Nain halogenated organic boilers. Manufactured by ETA dated 06/2011. Integrated flue compounds or heavy metals as Heiztechnik Gesellschaft mit gas recirculation system must a result of treatment with wood-

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Trattnach, Gewerbepark Austria.

A 4716, Hofkirchen an der pellets. Trattnach, Gewerbepark Austria.

ETA HACK 20, 25, 35, 50, Instruction manual reference Wood pellets. The fuel must 70, 90, 130 and 200 woodchip "HACK20-200 Bedienung 201 In 66c di Main halogenated organic boilers. Manufactured by ETA dated 06/2011. Integrated flue compounds or heavy metals as Heiztechnik Gesellschaft mit gas recirculation system must a result of treatment with woodbeschrankter Haftung (GmbH), be used when burning wood preservatives or coatings.

ETA Heiztechnik Gesellschaft dated 06/2011. beschrankter Haftung (GmbH), A 4716, Hofkirchen an der Trattnach, Gewerbepark 1, Austria.

ETA PC 20, 25 and 32 wood Instruction manual reference Wood pellets. The fuel must pellet boilers. Manufactured by "PC20-32 Bedienung 2011-06 Edd'contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

50, ETA PE-K 35, and wood pellet "PE-Heiztechnik Gesellschaft mit dated 06/2011. beschrankter Haftung (GmbH), A 4716, Hofkirchen an der Trattnach, Gewerbepark Austria.

70 Instruction manual reference Wood pellets. The fuel must not contain halogenated organic boilers. Manufactured by ETA K35-90 Bedienung 2011-06 ENcompounds or heavy metals as a result of treatment with woodpreservatives or coatings.

ETA Heiztechnik Gesellschaft dated 06/2011. beschrankter Haftung (GmbH), A 4716, Hofkirchen an der Trattnach, Gewerbepark 1, Austria.

ETA PU 7, 11 and 15 wood Instruction manual reference Wood pellets. The fuel must pellet boilers. Manufactured by "PU7-15 Bedienung 2011-06 Elvot contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

boilers. Manufactured by ETA dated 06/2011. Heiztechnik Gesellschaft mit beschrankter Haftung (GmbH), A 4716, Hofkirchen an der Trattnach, Gewerbepark 1, Austria.

ETA SH 20, 30, 40, 50 Instruction manual reference Wood logs. The fuel must and 60 wood gasification "SH20-60_Bedienung_2011-06_EXTontain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Knights Way, Battlefields Ent dated 9th November 2011. SY1 3AB.

eVolution 4 Inset manufactured Instruction manual references Wood logs. The fuel must by Broseley Fires Limited, "eVo 4&7 Inset MS11-11" not contain halogenated organic Park, Shrewsbury, Shropshire, Fitted with a system to prevent a result of treatment with woodclosure of the secondary air preservatives or coatings. control beyond the 15mm open position.

compounds or heavy metals as

eVolution 5 model number Instruction manual references Wood logs. The fuel must M-EVO5 manufactured by "eVo 5 MS07-11" dated 8th July not contain halogenated organic

Broseley Fires Knights Way, Shropshire, SY1 3AB.

eVolution 7 Inset manufactured Instruction manual references Wood logs. The fuel must Knights Way, Battlefields Ent dated 9th November 2011. SY1 3AB.

eVolution 26 boiler stove Instruction manual references Wood logs. The fuel must Ent Park. Shropshire, SY1 3AB.

Evotherm P50. P120, P150, by Evotherm, Heiztechnik Vertriebs Gesellschaft beschrankter Haftung (GmbH), Seeleiten 24, AT 5120, St Pantaleon, Austria.

and Bella Lux, Clementina, instructions dated 5th March not contain halogenated organic Comfort Maxi, Davina, Davina Plus Davina Steel, Duchessa and Duchessa Steel, Ecologica, Esmeralda and Esmeralda Crystal, Fal� 1CP, Fal� 2CP and Falï, 1/2 1XP, Isabella, Karolina and Preziosa, all of which are manufactured by Extraflame S.p.a in Montecchio Precalcino (Vicenza), Italy.

Extraflame Comfort (Vicenza), Italy.

Extraflame Montecchio (Vicenza), Italy.

Limited, 2011 fitted with a system that compounds or heavy metals as Battlefield prevents the closure of the air a result of treatment with wood-Enterprise Park, Shrewsbury, control to less than 70% open. preservatives or coatings.

> closure of the secondary air preservatives or coatings. control beyond the 8mm open position.

manufactured by Broseley Fires "MS10-11c" dated 09/01/2012. not contain halogenated organic Ltd, Knights Way, Battlefield The appliance must be fitted compounds or heavy metals as Shrewsbury, with a mechanical stop to a result of treatment with woodprevent closure beyond the 40% preservatives or coatings. open position when sold into smoke control areas.

P100, The manufacturer's instructions Wood pellets. The fuel must P170, P200 "Operating manual" reference not contain halogenated organic boilers manufactured Version 1/2010/Rev 4.21.

and 011.

Mini The manufacturer's operating Wood pellets. The fuel must

REV 005.

Extraflame Idro manufactured The manufacturer's operating Wood pellets. The fuel must S.p.a instructions dated 28th August not contain halogenated organic Precalcino 2006, reference 004275128 compounds or heavy metals as REV 002.

by Broseley Fires Limited, "eVo 4&7 Inset MS11-11" not contain halogenated organic compounds or heavy metals as Park, Shrewsbury, Shropshire, Fitted with a system to prevent a result of treatment with wood-

compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Extraflame: Babyfiamma, Bella The manufacturer's operating Wood pellets. The fuel must Contessa, 2007, reference 004275101 compounds or heavy metals as a result of treatment with wood preservatives or coatings.

manufactured by Extraflame instructions dated 2nd October not contain halogenated organic S.p.a. in Montecchio Precalcino 2006, reference 004275115 compounds or heavy metals as a result of treatment with wood preservatives or coatings.

> a result of treatment with wood preservatives or coatings.

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Precalcino (Vicenza), Italy.

Extraflame Lucrezia Idro and The manufacturer's operating Wood pellets. The fuel must Lucrezia Steel manufactured by instructions dated 12th July not contain halogenated organic Extraflame S.p.a in Montecchio 2006, reference 004275110 compounds or heavy metals as REV 011.

a result of treatment with wood preservatives or coatings.

manufactured by Farm 2000 in Limited.

Farm 2000 boiler models The manufacturer's instructions No fuel shall be used other than BB154, BB154A and BB154/2 dated May 1994 bearing cereal straw. (when used with the Farm 2000 the reference "BB154/2VC", conversion kit BB154/2Vcx), and maintained and operated accordance with manufacturer's instructions dated September 1993 bearing the reference "BB154/2V".

Limited.

Farm 2000 boiler models HT60. The manufacturer's instructions No fuel shall be used other than HT70, HT80 and BB154/2V which in the case of models cereal straw. manufactured by Farm 2000 HT60, HT70 and HT80, are dated 1st July 1993 and bear the reference "HT60/70/80", and in the case of model BB154/2V are dated 1st September 1993 and bear the reference "9/93".

each is used with the Farm reference "HT60/70/80". 2000 conversion kit HT80cx), manufactured by Farm 2000 Limited.

used with the Farm 2000 dated May 1994 bearing cereal straw. conversion kit HT60cx), the the references "HT6780", and HT6PLUS and HT600 (when "HT6781" and maintained and each is used with the Farm 2000 operated in accordance with conversion kit HT70cx), and the manufacturer's instructions the HT7 and the HT8 (when dated 1st July 1993 bearing the

Farm 2000 model HT6 (when The manufacturer's instructions No fuel shall be used other than

Charlton & Jenrick Ltd Unit D Stafford Park 2 Telford Shropshire TF3 3AR.

"FDC Issue 02" dated 04/12. secondary air control slots preservatives or coatings. beyond the 3.5mm open position must be implemented.

FDC5 Stove manufactured by Instruction manual references Wood logs. The fuel must not contain halogenated organic The fitting of a system compounds or heavy metals as that prevents closure of the a result of treatment with wood-

FDC5i inset Jenrick Ltd Unit D Stafford Park 2 Telford Shropshire

secondary air control slots preservatives or coatings. beyond the 3.5mm open position must be implemented.

stove Instruction manual references Wood logs. The fuel must manufactured by Charlton & "FDCi Issue 06" dated 03/12. not contain halogenated organic The fitting of a system compounds or heavy metals as that prevents closure of the a result of treatment with wood-

Jenrick Ltd

TF3 3AR.

manufactured by Charlton & "FDCiT Issue 1" dated 04/12.

FDC5iT Taper inset stove Instruction manual references Wood logs. The fuel must not contain halogenated organic compounds or heavy metals as

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Unit D Stafford Park 2 Telford Shropshire TF3 3AR.

The fitting of a system a result of treatment with woodthat prevents closure of the preservatives or coatings. secondary air control slots beyond the 5mm open position must be implemented.

Jenrick Ltd Unit D Stafford Park 2 Telford Shropshire TF3 3AR.

manufactured by Charlton & "FDCi Issue 06" dated 03/12. not contain halogenated organic secondary air control slots preservatives or coatings. beyond the 9mm open position must be implemented.

FDC5iW Wide inset stoves Instruction manual references Wood logs. The fuel must The fitting of a system compounds or heavy metals as that prevents closure of the a result of treatment with wood-

FDC5W Wide manufactured by Charlton & "FDC Issue 02" dated 04/12. Jenrick Ltd Unit D Stafford Park 2 Telford Shropshire TF3 3AR.

stove Instruction manual references Wood logs. The fuel must secondary air control slots preservatives or coatings. beyond the 7mm open position must be implemented.

not contain halogenated organic The fitting of a system compounds or heavy metals as that prevents closure of the a result of treatment with wood-

FDC 8 Freestanding Wood Instruction manual references Wood logs. The fuel must Shropshire, TF3 3AR.

closure beyond the 5mm open preservatives or coatings. position when sold into smoke control areas.

Burning Stove manufactured by "FDC issue 03" dated 07/12. not contain halogenated organic Charlton & Jenrick Limited, Fitted with a mechanical stop compounds or heavy metals as Unit D Stafford Park 2, Telford, to prevent secondary air control a result of treatment with wood-

FDC Shropshire, TF3 3AR.

closure beyond the 1mm open preservatives or coatings. position when sold into smoke control areas.

Wood Instruction manual references Wood logs. The fuel must Burning Stove manufactured by "FDCi issue 03" dated 07/12. not contain halogenated organic Charlton & Jenrick Limited, Fitted with a mechanical stop compounds or heavy metals as Unit D Stafford Park 2, Telford, to prevent secondary air control a result of treatment with wood-

Italy.

closure of the secondary air preservatives or coatings. control beyond the 40% open position.

Fireball manufactured by La Instruction manual references Wood logs. The fuel must Nordica Spa, Via Summano 104 "7196801-Rev.07" dated 22nd not contain halogenated organic M. Precalcino, 36030 Vicenza, December 2010. Fitted with compounds or heavy metals as a mechanical stop to prevent a result of treatment with wood-

Sirius 405CB and Flame 5CB "FFXCBA" (4.9kW) stoves manufactured 2010. Percy Doughty Co, Imperial Point, Express Trading Estate, Stonehill Road, Farnworth, Bolton, BL4 9TN.

dated

Firefox 5CB, Vega 100CB Instruction manual references Wood logs. The fuel must January not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Firefox 5 Clean Burn II, Instruction manual references Dry wood logs. The fuel must Sirius 405 Clean Burn and 2011. Doughty & Co Limited, beyond the 50% open position. Imperial Point, Express Trading Estate, Stone Hill Road, Farnworth, Bolton, BL4 9TN.

Gallery Classic 5 Clean Burn, "FF5CBII REV:A" dated June not contain halogenated organic

Sirius 405 Classic Clean Fitted with a mechanical stop a result of treatment with wood-Burn, manufactured by Percy to prevent secondary air closure preservatives or coatings.

compounds or heavy metals as

Firefox Sirius 545 Clean Burn and 2011. Doughty & Co Limited, beyond the 50% open position. Imperial Point, Express Trading Estate, Stone Hill Road, Farnworth, Bolton, BL4 9TN.

Burn manufactured by Percy to prevent secondary air closure preservatives or coatings.

Burn, Instruction manual references Dry wood logs. The fuel must Gallery Classic 8 Clean Burn, "FF8CB REV:A" dated June not contain halogenated organic compounds or heavy metals as Sirius 545 Classic Clean Fitted with a mechanical stop a result of treatment with wood-

and 2. Omega Centre, Sandford Lane, Wareham, BH20 4DY.

by Saltfire Stoves Limited, "ECO7operation-Revision 2A" not contain halogenated organic The dated 24.01.2011.

Fireglow Eco 7, Manufactured Instruction manual references Wood logs. The fuel must compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Fireline FGi5 Jenrick Ltd Unit D Stafford Park 2 Telford Shropshire

TF3 3AR.

03/12.

that prevents closure of the preservatives or coatings. secondary air control slots beyond the 3.5mm open position must be implemented.

stove Instruction manual references Wood logs. The fuel must manufactured by Charlton & "Fgi.Fpi.Fxi Issue 06" dated not contain halogenated organic compounds or heavy metals as The fitting of a system a result of treatment with wood-

Fireline FGi8, FXi8, Shropshire, TF3 3AR.

Unit D Stafford Park 2, Telford, control closure beyond the 1mm preservatives or coatings. open position when sold into smoke control areas.

& Instruction manual references Wood logs. The fuel must FPi8 Cassette Inset Wood "FGi.FPi.FXi issue 07" dated not contain halogenated organic Burning Stoves manufactured 07/12. Fitted with a mechanical compounds or heavy metals as by Charlton & Jenrick Limited, stop to prevent secondary air a result of treatment with wood-

Fireline Fpi 5kW and Fireline "Issue 03" dated 03/10. Shropshire, TF7 4QJ.

Charlton and Jenrick G1- secondary air control beyond preservatives or coatings. G2, Halesfield 5, Telford, the 3.5mm open position should be implemented.

Fireline FP5, Fireline FX5, Instruction manual references Wood logs. The fuel must not contain halogenated organic Fxi 5kW manufactured by The fitting of a system that compounds or heavy metals as Charlton and Jenrick Ltd, prevents the closure of the a result of treatment with wood

Freestanding Jenrick Ltd Unit D Stafford Park 2 secondary air control slots preservatives or coatings.

Fireline FP5W and FX5W Instruction manual references Wood logs. The fuel must stove "FX.FP.Issue 06" dated 03/12. not contain halogenated organic manufactured by Charlton & The fitting of a system compounds or heavy metals as that prevents closure of the a result of treatment with wood-

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Telford beyond the 7mm open position Shropshire must be implemented.

TF3 3AR.

FGi5T, Instruction manual references Wood logs. The fuel must Fireline Taper inset stoves "FXiT.FPiT.FGiT Issue 01" not contain halogenated organic FXi5T manufactured by Charlton & dated 03/12. Jenrick Ltd

Unit D Stafford Park 2 that prevents closure of the preservatives or coatings. secondary air control slots Telford Shropshire beyond the 5mm open position TF3 3AR. must be implemented.

Fireline FPi5W,

manufactured by Charlton & 03/12. Jenrick Ltd

Unit D Stafford Park 2 secondary air control slots Telford Shropshire

TF3 3AR.

Fireline Freestanding Wood Burning "FX.FP. issue 08" dated 09/12. not contain halogenated organic Stoves manufactured Charlton & Jenrick Limited, to prevent secondary air control a result of treatment with wood-Unit D Stafford Park 2, Telford, closure beyond the 5mm open preservatives or coatings. Shropshire, TF3 3AR.

Firematic and **HERZ** by Ges.m.b.H, Geschaftsbereich V 1.1 ENG doc. HERZ, Feuerungstechnik, A-8272 Sebersdorf

45 Firematic manufactured Armaturen HERZ, dated "08/2009". Geschaftsbereich Feuerungstechnik. A-8272 Sebersdorf 138, Austria.

Austria.

Firematic FM FM Instruction manual references Wood 151 FM180. FM199 "Operating Instructions Herz Pellets. The fuel must not boilers manufactured by firematic 130 Herz Energietechnik GmbH, BioControl" Herzstraï;½e, 1, 7423 Betriebsanleitung

compounds or heavy metals as The fitting of a system a result of treatment with wood-

FGi5W, Instruction manual references Wood logs. The fuel must FXi5W wide inset stoves "FGi.FPi.FXi Issue 06" dated not contain halogenated organic compounds or heavy metals as The fitting of a system a result of treatment with woodthat prevents closure of the preservatives or coatings.

> beyond the 9mm open position must be implemented. FP8 Instruction manual references Wood logs. The fuel must by Fitted with a mechanical stop compounds or heavy metals as

position when sold into smoke control areas.

Armaturen Bedienungsanleitung Firematic The

90 The manufacturer's instructions Chipped wood, wood pellets or manufactured dated June 2005, reference planed wood shavings. fuel must

not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

60 Instruction manual references Wood pellets conforming HERZ "05.007 Operating instructions to "i,1/2NORM M7135 with Ges.m.b.H, - FM (1Ph) 20 35 45 60 v2.3" diameter of 6mm or wood chips up to a maximum size of 50mm and maximum water content of 35%

> The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Chips and Wood 199 contain halogenated organic version compounds or heavy metals as firematic a result of treatment with woodpreservatives or coatings.

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

�sterreich/ 20-201 BioControl Englisch V Pinkafeld. Austria.

Firenzo Aucklander Zealand.

Firenzo "AL" dated 15-01-2013 and not contain halogenated organic Woodfires UK Limited, 98 instruction manual "AU" dated compounds or heavy metals as Niven Street, Napier 4142, New 01-02-2013. Fitted with a a result of treatment with woodmechanical stop to prevent air preservatives or coatings. control slots closure beyond the 6.5mm open position when sold into smoke control areas.

stove Instruction manual references Wood logs. The fuel must

Firenzo Bronte manufactured by Zealand.

stove Instruction manual references Wood logs. The fuel must Firenzo "BI" dated 15-01-2013 and not contain halogenated organic Woodfires UK Limited, 98 instruction manual "BU" dated compounds or heavy metals as Niven Street, Napier 4142, New 01-02-2013. Fitted with a a result of treatment with woodmechanical stop to prevent air preservatives or coatings. control slots closure beyond the 6.5mm open position when sold into smoke control areas.

Firenzo Contessa manufactured by Zealand.

Firenzo "CI" dated 15-01-2013 and not contain halogenated organic Woodfires UK Limited, 98 instruction manual "CU" dated compounds or heavy metals as Niven Street, Napier 4142, New 01-02-2013. Fitted with a a result of treatment with woodmechanical stop to prevent air preservatives or coatings. control slots closure beyond the 6mm open position when sold into smoke control areas.

stove Instruction manual references Wood logs. The fuel must

manufactured by Zealand.

mechanical stop to prevent air preservatives or coatings. control slots closure beyond the 6.5mm open position when sold into smoke control areas.

Firenzo Lady Kitchener stove Instruction manual references Wood logs. The fuel must Firenzo "LKI" dated 15-01-2013 and not contain halogenated organic Woodfires UK Limited, 98 instruction manual "LKU" compounds or heavy metals as Niven Street, Napier 4142, New dated 01-02-2013. Fitted with a a result of treatment with wood-

manufactured Zealand.

Firenzo Wellingtonian stove Instruction manual references Wood logs. The fuel must Firenzo "WI" dated 15-01-2013 and not contain halogenated organic Woodfires UK Limited, 98 instruction manual "WU" dated compounds or heavy metals as Niven Street, Napier 4142, New 01-02-2013. Fitted with a a result of treatment with woodmechanical stop to prevent air preservatives or coatings. control slots closure beyond the 6.5mm open position when sold into smoke control areas.

Firestorm 4.5 SE Resistant Glass Company Limited Unit 2 Bracewell Avenue Poulton Industrial Estate Poulton Le Fylde FY6 8JF.

dated 28th April 2012. only allow a minimum 3mm preservatives or coatings. air gap between the air control plate and the appliance when

stove Instruction manual references Wood logs. The fuel must manufactured by The Heat "4.5KW SE Issue (6928) 1" not contain halogenated organic compounds or heavy metals as Fitted with a stop that will a result of treatment with wood-

> the secondary air is turned down to its minimum position.

Firestorm 6.5 SE Resistant Glass Company Limited Unit 2 Bracewell Avenue Poulton Industrial Estate Poulton Le Fylde FY6 8JF.

manufactured by The Heat "6.5KW SE Issue (6928) 3" not contain halogenated organic dated 28th April 2012. Fitted with a stop that will a result of treatment with woodonly allow a minimum air gap preservatives or coatings. 6mm between the air control plate and the appliance when the secondary air is turned down to its minimum position.

stove Instruction manual references Wood logs. The fuel must compounds or heavy metals as

Firestorm 10 SE manufactured by The Heat Resistant Glass Company Limited Unit 2 Bracewell Avenue Poulton Industrial Estate Poulton Le Fylde FY6 8JF.

Instruction manual references Wood logs. The fuel must "10 KW SE Issue (6928) 2" not contain halogenated organic dated 28th April 2012. Fitted with a stop that will a result of treatment with woodonly allow a minimum air gap preservatives or coatings. 6mm between the air control plate and the appliance when the secondary air is turned down to its minimum position.

compounds or heavy metals as

manufactured by Heat Design, "FW06C" dated 26/07/12. Dublin 12, Ireland.

30 Hawthorn Road, Western A permanent stop to prevent compounds or heavy metals as Industrial Estate, Naas Road, closure of the secondary air a result of treatment with woodcontrol beyond 20% open must preservatives or coatings. be implemented.

Firewarm 06C inset stove Instruction manual references Wood logs. The fuel must not contain halogenated organic

Firewarm 4SE manufactured by Heat Design, "FW468SE" dated 25/07/12. 30 Hawthorn Road, Western The Industrial Estate, Naas Road, to Dublin 12, Ireland.

prevent closure beyond 5mm open must be implemented.

stove Instruction manual references Wood logs. The fuel must not contain halogenated organic fitting of a system compounds or heavy metals as of a result of treatment with woodsecondary air control preservatives or coatings.

Firewarm 6SE manufactured by Heat Design, "FW468SE" dated 25/07/12. Dublin 12, Ireland.

30 Hawthorn Road, Western The fitting of a system compounds or heavy metals as Industrial Estate, Naas Road, to prevent closure of the a result of treatment with woodsecondary air control beyond preservatives or coatings. 75% from closed must be implemented.

stove Instruction manual references Wood logs. The fuel must not contain halogenated organic

Firewarm 8SE manufactured by Heat Design, "FW468SE" dated 25/07/12. Dublin 12, Ireland.

stove Instruction manual references Wood logs. The fuel must secondary air control beyond preservatives or coatings. 25% from closed must be implemented.

not contain halogenated organic 30 Hawthorn Road, Western The fitting of a system compounds or heavy metals as Industrial Estate, Naas Road, to prevent closure of the a result of treatment with wood-

Firewarm 11C inset stove Instruction manual references Wood logs. The fuel must manufactured by Heat Design, "FW11C" dated 26/07/12.

not contain halogenated organic

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Dublin 12, Ireland.

30 Hawthorn Road, Western A permanent stop to prevent compounds or heavy metals as Industrial Estate, Naas Road, closure of the secondary air a result of treatment with woodcontrol beyond 20% open must preservatives or coatings. be implemented.

Flatford 5K, Barrington 5K, Instruction manual references Wood logs. The fuel must Stoves. Limited, 192 – 200 Battersea to prevent secondary air control preservatives or coatings. Park Road London

Hampstead 5K Wood Burning "CH5K - V1" dated 14th March not contain halogenated organic

compounds or heavy metals as Manufactured by Chesneys Fitted with a mechanical stop a result of treatment with wood-

closure beyond the 18mm open position when sold into smoke SW11 4ND. control areas.

Franco Belge Model 134 08 11 The Savoy EA Technical Wood logs. The fuel must Savoy EA 8kW output wood Manual, document reference not contain halogenated organic 1290-1, reviewed 9 July 2009.

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

burning stove; Franco Belge Model 134 08 09 Savoy MK Elegance multifuel stove with KEA 13408 smoke control kit manufactured by: Franco Belge, Staub Fonderie SA, Rue Orphi;½e Variscotte, 59660,

Franco Belge manufactured by:

59660, Merville, France.

Merville, France.

SA, Rue Orphi¿½e Variscotte, with a mechanical stop preservatives or coatings. to prevent closure of the secondary air control beyond the 25% open position.

Montfort Instruction manual reference Wood logs. The fuel must MK2 wood burning stove "1295-3" dated 17th November not contain halogenated organic compounds or heavy metals as Franco Belge, Staub Fonderie The appliance must be fitted a result of treatment with wood-

Frï,½ling Commercial wood boiler 500, models and 1000 by Fr�ling Heizkessel-und Beh�lterbau Gesellschaft mit beschri; ½nkter Haftung (GmbH), A-4710 Grieskirchen, Industriestrasse 12, Austria.

Lambdamat Lambdamat chip Operating and 750 Manual reference B 069 01 04 compounds or heavy metals as manufactured of February 2004.

Communal Wood chips. The fuel must Installation not contain halogenated organic a result of treatment with wood preservatives or coatings.

Fr�ling P4 8, 15, 20, 25, 32, Instruction manual reference Wood pellets with a diameter manufactured by Fri; ½ling 2009. Heizkessel-und Beh�lterbau Ges.m.b.H, Industriestraï;½e A-4710 Grieskirchen, 12. Austria.

38, 48 and 60 Pellet Boilers "B0430408 en" dated July of 6mm. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

manufactured by Fri; ½ ling 2012. Heizkessel- und Beh�lterbau Ges.m.b.H. Industriestra�e 12

A – 4710 Grieskirchen.

100 wood pellet boilers "B043 – Version 8" dated 05 not contain halogenated organic

Frii/2ling P4 80 and P4 Instruction manual references Wood pellets. The fuel must compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Frï,½ling Turbo S4 Turbo 34 34kW, Fri; ½ling November 2008. S4 Turbo 40 40kW, Fri; ½ling S4 Turbo 50 50kW, and Frï, ½ling S4 Turbo 60 60kW manufactured by Frï, ½ling Heizkessel- und Beh�lterbau

Ges.m.b.H, Industriestra�e 12, A - 4710 Grieskirchen,

Austria.

Frï;½ling

Fr�ling

Grieskirchen, Austria.

15kW, Fri¿½ling S4 Turbo "M0970208" dated November not contain halogenated organic 22kW, Fright-ling S4 2008 and Operating instruction compounds or heavy metals as Turbo 28 28kW, Fri₆½ling manual "B0510108" dated a result of treatment with wood-

15 Assembly Instruction manual Wood logs. The fuel must preservatives or coatings.

Fri; ½ling T4 24, 30, 40, 50, 60, Instruction manual references Wood manufactured by Fr�ling 2012. Heizkessel- und Behï; ½lterbau Ges.m.b.H. Industriestra�e 12 A – 4710 Grieskirchen.

75, 90, 100 and 110kW boilers "B071 - Version 05" dated 05 chips. The fuel must not

Frii/2/ling Turbomatic 28, 35, The manufacturer's installation Wood chip less than 35%

reference 99229a.

Fr�ling Heizkessel- reference M 060 01 03. Grieskirchen, Austria.

Turbomatic

Heizkessel- reference M 060 01 03. reference 99229a.

contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

or

wood

pellets

and 55 manufactured manual dated November 2003, moisture content and meeting �NORM M 7133: 1998 size und Behi; ½lterbau Ges.m.b.H, The manufacturer's operating class G30. Wood pellets of 6mm Industriestraï₄//₂e 12, A-4710 manual dated August 2002, diameter and a moisture content below 10%. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

85, The manufacturer's instruction Wood chip less than 35% 100 and 110 manufactured manual dated November 2003, moisture content and meeting �NORM M 7133: 1998 und Behi; ½lterbau Ges.m.b.H, The manufacturer's operating of either size class G30 Industriestraï, ½e 12, A-4710 manual dated August 2002, or G50. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

> Wood pellets of 6mm diameter and a moisture content below 10%. The fuel must not contain halogenated organic compounds or heavy metals as

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Frii/½ling Turbomat 150 and The manufacturer's operating Wood pellets or wood chips. 220 manufactured by Fri; ½ling instructions dated August 2003, The Heizkessel-und Beh�lterbau reference B0310003. Ges.m.b.H, Industriestra�e A-4710 Grieskirchen, Austria.

Frii/2ling Turbomat 320 and The manufacturer's operating Wood pellets or wood chips. Heizkessel-und Behï; ½lterbau 2004, reference B0340004. Ges.m.b.H, Industriestraï;½e 12. A-4710 Grieskirchen, Austria.

with Exhaust Gas Recirculation references "M1130009" dated content ≤30% and a maximum manufactured Frï: 1/2 ling Behï, ½lterbau Industriestraï,½e 12, A-4710 Grieskirchen, Austria.

with Exhaust Gas Recirculation 2012. device manufactured by Frï;½ling Heizkesselund Behï, ½lterbau Ges.m.b.H. Industriestraï;½e 12 A – 4710 Grieskirchen.

manufactured bv Limited. Swinton Industrial Estate, Whitelee Road, Swinton S64 8BH.

boilers. Manufactured by Gilles dated November 2008. Energie und Umwelttechnik Gmbh, Koaserbauer Str. 16, A-4810 Gmunden, Austria.

20kW, 25kW, 30kW, 35kW, January 40kW, 45kW, 49kW, 60kW, Gilles/0-145/1. 70kW, 75kW, 85kW, 95kW,

500 manufactured by Frï; ½ ling instructions dated November The

Frï_i,½ling TX150 150kW boiler Installation Instruction manual Wood chips with a moisture by 09/2010 and Heizkessel-und instruction manual "B 067 00 Ges.m.b.H., 09" dated 09/2010.

Fri; ½ling TX 200 199kW Instruction manual references Wood and TX 250 250kW boilers "B067 - Version 03" dated 05 pellets. The fuel must not

Future Fires Panoramic FX1 Instruction manual reference Wood logs. The fuel must Gen-Fab "PANFXREV2" Bridge 31/10/12.

Gilles HPKI-K 180, 195, 240, "Operating Instruction HPKI- Wood 900, 995, 1200 and 1600 HPKI-K underfeed stoking"

Gilles HPK-RA 13kW, 15kW, Operating instructions dated Wood pellets or wood chips. 2007, reference The

a result of treatment with wood preservatives or coatings.

fuel must contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

fuel must contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

operating cross sectional area of 5cm² or wood pellets with a moisture content of ≤10% and a maximum diameter of 10mm. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

> chips or wood contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

pellets or wood 300, 360, 450, 550, 700, K Underfeed Stoking. 1-general chips. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

> fuel must contain halogenated organic compounds or heavy metals as

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

100kW, 120kW and 145kW manufactured by **GILLES** Energie-und Umwelttechnik GmbH. Koaserbauer Str. 16. A-4810 Gmunden, Austria.

a result of treatment with wood preservatives or coatings.

HPK-RA Manufactured by Gilles Energie manuals "BD - und Umwelttechnik Gmbh, and dated Koaserbauer Str. 16, A-4810 200-01a-02" Gmunden, Austria.

160 Instruction operation Wood and 200-01a-01" The 11/2008, and 11/2008. "BD dated 11/2008. and 200-01a-04" and dated 11/2008, "BD 200-01a-06" "BD and dated 11/2008, 200-03a-07" and dated 11/2008, and "BD 200-03a-09" and dated 11/2008.

Chips and pellets. fuel must "BD contain halogenated organic dated compounds or heavy metals as 200-01a-03" a result of treatment with wood-"BD preservatives or coatings.

180kW. 240kW 300kW boilers manufactured Gilles/150-300/1. **GILLES** Energie by und Umwelttechnik GmbH. Koaserbauer Str. 16, A-4810 Gmunden, Austria.

Gilles HPK UTSK 150kW, Operating instructions dated Wood pellets or wood chips. and January 2007, reference The

fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Gilles HPK UTSK 360kW Operating instructions dated Wood Boiler manufactured **GILLES** Energie Umwelttechnik GmbH. Koaserbauer Str. 16, A-4810 Gmunden, Austria.

by January 2008, reference Gilles/ chips. The fuel must not und 360/1.

pellets or wood contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Gilles UTSK 550kW boilers manufactured January by GILLES und Umwelttechnik GmbH. Koaserbauer Str. 16, A-4810 Gmunden, Austria.

450kW, Operating instructions dated Wood pellets or wood chips. 2008, reference The Energie- Gilles /360/1.

fuel must contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Gilles UTSK 900kW boilers manufactured January GILLES bv und Umwelttechnik GmbH, Koaserbauer Str. 16, A-4810 Gmunden, Austria.

700kW, Operating instructions dated Wood pellets or wood chips. 2008. reference The Energie- Gilles /360/1.

fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Gilles UTSK 1600kW boilers manufactured January **GILLES** bv und Umwelttechnik GmbH, Koaserbauer Str. 16, A-4810 Gmunden, Austria.

1200kW, Operating instructions dated Wood pellets or wood chips. 2008. reference The Energie- Gilles /360/1.

fuel must contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

number WPS626 and 9-36kW April 2012. number **WPS936** manufactured by Grant UK Ltd, Hopton House, Hopton Industrial Estate, Devizes, Wiltshire, SN10 2EU.

Grant Spira Condensing Wood Instruction manual references 6mm wood pellets. The fuel Pellet Boiler 6-26kW model "IRL NO.012 Rev; 1" dated must not contain halogenated

organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

Greenflame 28 Boiler manufactured Trianco Limited, Thorncliffe, Manual V.2.1" dated 07/12. Chapletown, Sheffield S35 2PH.

Pellet Instruction manual references 6mm wood pellets. The fuel by "Installation &

Operation must not contain halogenated organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

Guntamatic Biocom 50 Powercorn and manufactured GUNTAMATIC Heiztechnik GmbH A-4722 PEUERBACH, Bruck 7, Austria.

and Instruction manual references 75 "GUN/BIO/OP/V1/0709" by dated 29/07/09.

Wood pellets with a diameter of 6mm and a length of between 10 and 30mm.

The fuel must contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Guntamatic Biocom Powercorn 100 manufactured "GUN/BIO/OP/V1/0709" GUNTAMATIC dated 29/07/09. Heiztechnik GmbH A-4722 PEUERBACH. Bruck Austria.

and Instruction manual references

Wood pellets with a diameter of 6mm and a length of between 10 and 30mm or wood chip less than 35% moisture content and meeting "i,1/2NORM M 7133: 1998 size class G30.

The fuel must contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Guntamatic Powerchip and 75 manufactured by "GUN/POW/OP/V1/0709" GUNTAMATIC Heiztechnik dated 29/07/09. GmbH A-4722 PEUERBACH, Bruck 7, Austria.

50 Instruction manual references

Wood pellets with a diameter of 6mm and a length of between 10 and 30mm

The fuel must contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Guntamatic Powerchip manufactured GUNTAMATIC GmbH A-4722 PEUERBACH. Bruck 7, Austria.

100 Instruction manual references by "GUN/POW/OP/V1/0709" Heiztechnik dated 29/07/09.

Wood pellets with a diameter of 6mm and a length of between 10 and 30mm or wood chip less than 35% moisture content and meeting "i/2NORM M 7133: 1998 size class G30.

fuel must contain halogenated organic compounds or heavy metals as

Haat LD, MD and HD The manufacturer's instructions No fuel shall be used other Incinerators manufactured by dated Haat Incineration Limited.

1988 March CAA/3/88".

a result of treatment with wood preservatives or coatings.

and than fuel consisting of scrap bearing the reference "HAAT/1/ wood and foliage. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Incineration Limited.

Haat Pioneer AB1 Incinerators The manufacturer's instructions No models 12, 20, 28 and published in October 1989 and other than wood, used in 36 manufactured by Haat bearing the reference "HAAT/2/ the mixtures by volume CAA/10/89".

fuel shall be recommended in Appendix of the manufacturer's instructions. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

boiler fitted manufactured by Contracting and Trading, spol. S.r.o., Sedlište 227, postal code 739 36, district Fr�dek-Mistek Czech Republic.

Hamont CATfire 350 USZI Operating instruction reference Wood pellets with a 6mm with "Operating Manual for Boilers diameter and a maximum length CATfire 300 cyclone, both CATfire 150-500kW" effective of 30mm. Hamont from 1/1/2008.

The fuel must contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Hand�1 35T, Varde Ovne 511942. Look 1, Varde Ovne Look A permanent stop must be in compounds or heavy metals as 2. Varde Ovne Look 3, place on the air inlet to prevent a result of treatment with wood manufactured by NIBE AB Box closure beyond the 45% open preservatives or coatings. 134, 285 23 Markaryd, Sweden. position.

Handi;½1 31, Handi;½1 31A, Installation Instructions IAV Untreated dry wood with less Hand�1 32, Hand�1 32A, SE/EX 0811-4 511941 Lighting than 20% moisture. Hand�1 33T, Hand�1 34T, Instructions BAV SE/EX H30 The

fuel must contain halogenated organic

Handi; ½1 50, Handi; ½1 51, Installation Instructions IAV Untreated dry wood with less Handi, ½1 53, Handi, ½1 54, Instructions Handï; ½1 54T, Handï; ½1 51L, 0717-1 511865. by NIBE AB Box 134, 285 23 closure beyond the 45% open preservatives or coatings. Markaryd, Sweden.

Handï; ½1 52, Handï; ½1 52T, SE/EX 0737-4 511866 Lighting than 20% moisture. BAV SE/EX The

fuel must not contain halogenated organic Varde Ovne S1, Varde Ovne S2, A permanent stop must be in compounds or heavy metals as Varde Ovne S3, manufactured place on the air inlet to prevent a result of treatment with wood

Harrie Leenders Cylon, Harrie Instruction manual references Wood logs. The fuel must Leenders Doran 190, Harrie Amended June 2010". Leenders Fuga eL, Harrie with a mechanical stop to preservatives or coatings. Leenders Stor, Harrie Leenders prevent closure of the air slide Signa, Stoves manufactured by beyond the 15mm open position

Lenders Doran 160, Harrie "Supplementary Instructions not contain halogenated organic Leenders Fuga S, Harrie All appliances will be fitted a result of treatment with wood

position.

compounds or heavy metals as

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Harrie Leenders, Industrieweg when sold into smoke control 5688 DP Oirschot, areas. Netherlands.

22, Siemensstrasse Massing, Germany.

HDG Compact models 25/35 The manufacturer's operating Wood (25kW, 35kW) wood chip and instructions for the HDG pellets. The fuel must not pellet boilers manufactured by Compact 25/35 with HDG contain halogenated organic HDG Bavaria Gesellschaft mit Compact Hydronic reference compounds or heavy metals as beschrankter Haftung (GmbH), HDG Compact Version V01 of a result of treatment with wood 84323 April 2009.

chip preservatives or coatings.

HDG Bavaria Gesellschaft mit Hydronic reference 22, Siemensstrasse Massing, Germany.

HDG Compact models 50/65 The manufacturer's operating Wood (50kW, 65kW) wood chip and instructions for the HDG pellets. The fuel must not pellet boilers manufactured by Compact 50/65 with HDG contain halogenated organic beschrankter Haftung (GmbH), Compact Version V03 of April a result of treatment with wood 84323 2009.

chip HDG compounds or heavy metals as preservatives or coatings.

pellet boiler manufactured by Compact 80 with HDG Bavaria Gesellschaft mit Hydronic Siemensstrasse 22, Massing, Germany.

HDG Compact models 80 The manufacturer's operating Wood (80kW) wood chip and instructions for the HDG pellets. The fuel must not reference beschrankter Haftung (GmbH), Compact Version V03 of April a result of treatment with wood 84323 2009.

chip HDG contain halogenated organic HDG compounds or heavy metals as preservatives or coatings.

pellet boilers manufactured by Compact HDG Bavaria Gesellschaft mit reference Siemensstrasse 22, Massing, Germany.

HDG Compact models 100 The manufacturer's operating Wood (100kW) wood chip and instructions for the HDG pellets. The fuel must not HDG beschrankter Haftung (GmbH), 100-200 Version V1 of July a result of treatment with wood 84323 2008.

chip 100/150/200 contain halogenated organic Compact compounds or heavy metals as preservatives or coatings.

HDG Compact models 150, The manufacturer's operating Wood chip and pellet with model HDG manufactured HDG Bavaria Gesellschaft mit 2008. beschrankter Haftung (GmbH), Siemensstrasse 22, 84323 Massing, Germany.

200 (150kW, 200kW) wood instructions for the HDG pellets. The fuel must not boiler Compact 3113 reference HDG by 100-200 Version V1 of July a result of treatment with wood

chip 100/150/200 contain halogenated organic Compact compounds or heavy metals as preservatives or coatings.

HDG Euro models 30, 40 and The manufacturer's operating Split wood logs of 500 mm (GmbH), Siemensstrasse 22, Version V1 of June 2008. 84323 Massing, Germany.

50 (30kW, 40kW and 50kW) instructions for the HDG Euro length and maximum edge wood log boilers manufactured 30/40/50 with Lambda Control length of 120 mm and a by HDG Bavaria Gesellschaft 1 reference HDG Euro V3.0 residual moisture content of Haftung with HDG Lambda Control 1 20%. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

beschrankter mit 84323 Massing, Germany.

of June 2008.

HDG Navora models 20, 25 and The manufacturer's operating Split wood logs of 500 mm 30 (20kW, 25kW and 30kW) instructions for the HDG length and maximum edge wood log boilers manufactured Navora 20/25/30 with Lambda length of 120 mm and a by HDG Bavaria Gesellschaft Control 1 reference HDG residual moisture content of Haftung Navora 20/25/30 with HDG 20%. The fuel must not (GmbH), Siemensstrasse 22, Lambda Control 1 Version V2 contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

HDG Pelletmaster Gesellschaft beschrankter Haftung (GmbH), of October 2006. Siemensstrasse 22, 84323 Massing, Germany.

model The manufacturer's operating Wood pellets. The fuel must PM15, 15kW wood pellet instructions for the HDG not contain halogenated organic boiler manufactured by HDG Pelletmaster 15/25 reference compounds or heavy metals as mit HDG Pelletmaster Version V1 a result of treatment with wood preservatives or coatings.

Shropshire, TF3 3AR.

Unit D Stafford Park 2, Telford, secondary air control closure preservatives or coatings. beyond the 5 mm open position when sold into smoke control areas.

Heat Design of Dublin TR8 Instruction manual references Wood logs. The fuel must Curved Freestanding Wood "HD TR Freestanding Issue not contain halogenated organic Burning Stove manufactured by 01" dated 01/13. Fitted with compounds or heavy metals as Charlton & Jenrick Limited, a mechanical stop to prevent a result of treatment with wood-

Heat Design of Shropshire, TF3 3AR.

Unit D Stafford Park 2, Telford, closure beyond the 1mm preservatives or coatings. position when sold into smoke control areas.

Dublin Instruction manual references Wood logs. The fuel must TR8c Cassette Inset Wood "TRc issue 03" dated 07/12. not contain halogenated organic Burning Stove manufactured by Fitted with a mechanical stop compounds or heavy metals as Charlton & Jenrick Limited, to prevent secondary air control a result of treatment with wood-

Heat Design TR5c inset stove Instruction manual references Wood logs. The fuel must manufactured by Charlton & "TRc Issue 02" dated 04/12. Jenrick Ltd Unit D Stafford Park 2 Telford Shropshire

secondary air control slots preservatives or coatings. beyond the 3.5mm open position must be implemented.

not contain halogenated organic The fitting of a system compounds or heavy metals as that prevents closure of the a result of treatment with wood-

& Jenrick Ltd Unit D Stafford Park 2 Telford

TF3 3AR.

Shropshire TF3 3AR.

stove manufactured by Charlton "TRiT Issue 01" dated 04/12. not contain halogenated organic The fitting of a system compounds or heavy metals as that prevents closure of the a result of treatment with woodsecondary air control slots preservatives or coatings. beyond the 5mm open position must be implemented.

Heat Design TR5iT Taper inset Instruction manual references Wood logs. The fuel must

Heat Design TR6c Wide inset Instruction manual references Wood logs. The fuel must stove manufactured by Charlton "TRc Issue 02" dated 04/12. & Jenrick Ltd Unit D Stafford Park 2 Telford

secondary air control slots preservatives or coatings.

not contain halogenated organic The fitting of a system compounds or heavy metals as that prevents closure of the a result of treatment with wood-

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Shropshire TF3 3AR.

beyond the 9mm open position must be implemented.

Ireland.

Stove manufactured by Henley "Version 1" dated November not contain halogenated organic Stoves Limited, Ard Ri Marble, 2012. Fitted with a mechanical compounds or heavy metals as Curraheen, Tralee, Co. Kerry, stop to prevent closure of a result of treatment with woodthe secondary air control slots preservatives or coatings. beyond the 50% open position when sold into smoke control areas.

Henley Achill Wood Burning Instruction manual references Wood logs. The fuel must

Herz **BioFire** BF manufactured by Engietechnik �sterreich/Austria.

500 Instruction manual references Wood Herz "Operating instructions HERZ The Englisch V1.2.doc".

and chips pellets. must fuel GmbH, BioFire 500 – 1000 Biocontrol" contain halogenated organic Herstra�e 1, 7423 Pinkafeld, Reference "Betriebsanleitung compounds or heavy metals as Biofire 500-1000 Biocontrol a result of treatment with woodpreservatives or coatings.

Herz **BioFire** BF manufactured bv Engietechnik �sterreich/Austria.

600 Instruction manual references Wood Herz "Operating instructions HERZ The GmbH, BioFire 500 – 1000 Biocontrol" contain halogenated organic Herstra�e 1, 7423 Pinkafeld, Reference "Betriebsanleitung compounds or heavy metals as Englisch V1.2.doc".

and pellets. chips fuel must Biofire 500-1000 Biocontrol a result of treatment with woodpreservatives or coatings.

Herz **BioFire** BF manufactured Engietechnik �sterreich/Austria.

800 Instruction manual references Wood Herz "Operating instructions HERZ The Englisch V1.2.doc".

chips and pellets. fuel must GmbH, BioFire 500 – 1000 Biocontrol" contain halogenated organic Herstraï, ½e 1, 7423 Pinkafeld, Reference "Betriebsanleitung compounds or heavy metals as Biofire 500-1000 Biocontrol a result of treatment with woodpreservatives or coatings.

BFBioFire Herz manufactured Engietechnik �sterreich/Austria.

1000 Instruction manual references Wood Herz "Operating instructions HERZ The Englisch V1.2.doc".

chips and pellets. fuel GmbH, BioFire 500 – 1000 Biocontrol" contain halogenated organic Herstraï, ½e 1, 7423 Pinkafeld, Reference "Betriebsanleitung compounds or heavy metals as Biofire 500-1000 Biocontrol a result of treatment with woodpreservatives or coatings.

Herz Firematic 80 manufactured Herstraï;½e 1, 7423 Pinkafeld, BioControl" �sterreich/Austria.

FM Assembly and installation by instructions

Wood chips and pellets. The fuel must not Herz Engietechnik GmbH, "HERZ firematic 20 - 101 contain halogenated organic compounds or heavy metals as Reference "04.001" Installation a result of treatment with wood-Instructions – "Herz Firematic preservatives or coatings.

Operating instructions

"HERZ firematic 20 - 101

BioControl"

(1Ph) 20-101"

Reference "Betriebsanleitung firematic 20-101 BioControl Englisch V 2.53.doc".

Herz Firematic FM Assembly and installation Wood chips and pellets. 100 manufactured by Instructions "HERZ firematic The fuel must not

Herz Engietechnik GmbH, 20 �sterreich/Austria.

101 Herstraï, ½e 1, 7423 Pinkafeld, Reference "04.001" Installation compounds or heavy metals as Instructions – "Herz Firematic a result of treatment with wood-20-101". instructions "HERZ firematic 101 BioControl" Reference "Betriebsanleitung firematic 20-101 BioControl Englisch V 2.53.doc.

BioControl" contain halogenated organic Operating preservatives or coatings.

7CD and 7DD wood burning "Pevex1006/AH/ver2" stoves distributed in the UK dated June 2011. Newbourne IP12 4PS.

by Pevex Enterprises Limited, Fitted with permanent stops to a result of treatment with wood-Unit 16 Seven Acres Business ensure that the primary and preservatives or coatings. Road, secondary air controls do not Waldringfield Nr Woodbridge, close beyond 95% and 50% respectively.

Heta Scanline 7D, 7AD, 7BD, Instruction manual references Dry wood logs. The fuel must and not contain halogenated organic compounds or heavy metals as

Heta Scanline 500D, 510D, Instruction manual references Dry wood logs. The fuel must 520D and 530D wood burning "Pevex1005/AH/ver2" stoves distributed in the UK dated June 2011. Newbourne Waldringfield Nr Woodbridge, close beyond 95% and 50% IP12 4PS.

by Pevex Enterprises Limited, Fitted with permanent stops to a result of treatment with wood-Unit 16 Seven Acres Business ensure that the primary and preservatives or coatings. Road, secondary air controls do not

and not contain halogenated organic compounds or heavy metals as

Highlander 5 Clean Burn Instruction manual references Wood logs conforming to BS Manufactured by Dunsley "Highlander. The Dunsley EN 13240:2001. Heat Limited, Bridge Mills, – Enviroburn-5. Clean The fuel Huddersfield, Holmfirth, West Burn Yorkshire, HD9 3TW.

Stove operating and D12-01-09, D13-01-09, D12-12-08".

respectively.

and multi-fuel stove (product codes instructions manual reference not contain halogenated organic

must not Installation contain halogenated organic instructions. compounds or heavy metals as D060-01-09, a result of treatment with wood preservatives or coatings.

Highlander 7 Enviroburn Solo Installation manufactured by Heat Limited, Bridge Mills, Appliance Huddersfield, HD9 3TW.

Dunsley 15/6/2012. fitted with Huddersfield Road, Holmfirth, mechanical stop to prevent closure of the secondary airwash beyond 2mm. Four fixed 5mm diameter air holes are provided for the tertiary air supply.

operating Dry wood logs. The fuel must 00325, 00326 and 00327) "ENVIRO 7 DB001" dated compounds or heavy metals as a result of treatment with wooda preservatives or coatings.

number Fireplace UK Limited **Business Park**

HF277- "AL905-SE/UK-NI-ROI/V2-Wood Burning Stove. D.18-07-12" dated July 2012. to prevent closure of the preservatives or coatings. Unit 5A Holmes Chapel secondary air control beyond the 3mm open position.

Horse Flame Little Artemis Instruction manual references Wood logs. The fuel must not contain halogenated organic compounds or heavy metals as Manufactured by Hi-Flame Fitted with a mechanical stop a result of treatment with wood-

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Manor Lane Holmes Chapel Cheshire CW4 8AF.

model number HF905-SE, UK "HF905/UK-NI-ROI/ Distribution Hi-Flame Limited, V2.1-06-11" dated June 2011. Business Park, Manor Lane, prevent closure of the main air preservatives or coatings. Holmes Chapel, Cheshire, CW4 control beyond the 50% open

position.

Horse Flame Precision 1 Instruction manual references Wood logs. The fuel must not contain halogenated organic compounds or heavy metals as Unit 7B, Holmes Chapel Fitted with a mechanical stop to a result of treatment with wood-

Limited Unit 5A Holmes **Business Park** Manor Lane Holmes Chapel Cheshire

Horse Flame Precision II model Instruction manual references Wood logs. The fuel must number HF907-SE Wood "HF907-SE/UK-NI-ROI/V3-Burning Stove. Manufactured D. 14-07-12" dated July 2012. by Hi-Flame Fireplace UK Fitted with a mechanical stop a result of treatment with woodto prevent secondary air control preservatives or coatings. Chapel closure beyond the 20% open position, and a 70mm opening of the door rope seal to allow a constant flow of air when sold into smoke control areas.

not contain halogenated organic compounds or heavy metals as

Dublin 12, Ireland.

CW4 8AF.

Hothouse 4SE manufactured Instruction manual references Wood logs. The fuel must by Heat Design, 30 Hawthorn "HH468SE" dated 25/07/12. Western Estate, Naas Road, Dublin 12, to Ireland.

Hothouse 6SE manufactured by Heat Design, "HH468SE" dated 25/07/12. Dublin 12, Ireland.

Hothouse 8SE manufactured by Heat Design, "HH468SE" dated 25/07/12. Dublin 12, Ireland.

Hothouse 06C inset stove Instruction manual references Wood logs. The fuel must control beyond 20% open must preservatives or coatings. be implemented.

> prevent closure the secondary air control preservatives or coatings. beyond 5mm open must be implemented.

stove Instruction manual references Wood logs. The fuel must 30 Hawthorn Road, Western The fitting of a system compounds or heavy metals as Industrial Estate, Naas Road, to prevent closure of the a result of treatment with woodsecondary air control beyond preservatives or coatings. 75% from closed must be implemented.

stove Instruction manual references Wood logs. The fuel must 30 Hawthorn Road, Western The fitting of a system compounds or heavy metals as Industrial Estate, Naas Road, to prevent closure of the a result of treatment with woodsecondary air control beyond preservatives or coatings. 25% from closed must be implemented.

manufactured by Heat Design, "HH06C" dated 26/07/12. A not contain halogenated organic 30 Hawthorn Road, Western permanent stop to prevent compounds or heavy metals as Industrial Estate, Naas Road, closure of the secondary air a result of treatment with wood-

> not contain halogenated organic Industrial The fitting of a system compounds or heavy metals as of a result of treatment with wood-

> > not contain halogenated organic

not contain halogenated organic

manufactured by Heat Design, "HH11C" dated 26/07/12. Dublin 12, Ireland.

30 Hawthorn Road, Western A permanent stop to prevent compounds or heavy metals as Industrial Estate, Naas Road, closure of the secondary air a result of treatment with woodcontrol beyond 20% open must preservatives or coatings. be implemented.

Hothouse 11C inset stove Instruction manual references Wood logs. The fuel must not contain halogenated organic

Hotpod Limited manufactured by Hotpod LLP, "Version 3" dated June 2011. PO Box 137, St Ives, Cornwall, TR26 2WW.

Edition Instruction manual reference Wood logs. The fuel must

not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Hotpod manufactured by Hotpod LLP, "Version 3" dated June 2011. PO Box 137, St Ives, Cornwall, TR26 2WW.

Unlimited Instruction manual reference Wood logs. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Hoval AgroLyt 20, 25, 35, 45 Installation Liechtenstein.

and 193/00.

operation Wood logs with less than and 50 manufactured by Hoval manuals dated January 2006, 20% moisture. The fuel must AG, Austrasse 70, 9490 Vaduz, reference 4 205/ 194/00, and not contain halogenated organic June 2006, reference 205 compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Nottinghamshire, NG24 1JN.

BioLyt (50,70, 140, 160)" dated 03/07/2008 preservatives or coatings. "Technical information and Assembly instructions" dated 03/10/2009.

Hoval BioLyt 160 pellet Instruction manual references Wood pellets. The fuel must boiler manufactured by Hoval "Hoval Operating instructions, not contain halogenated organic Limited, Northgate, Newark, wood pellet heating boiler compounds or heavy metals as 120, a result of treatment with wood

Hoval BioLyt 50 and 70 Installation Liechtenstein.

and manufactured by Hoval AG, manuals referenced 4 204 not contain halogenated organic Austrasse 70, 9490 Vaduz, 794/01, and 4 204 793/02, dated compounds or heavy metals as June 2007.

operation Wood pellets. The fuel must a result of treatment with wood preservatives or coatings.

Hoval Forester MGS 150, 180, Instruction manual references Wood 240, 300, 360, 450, 550, "Hoval 700, 900 boilers manufactured MGS MMXXXv1" systems PO Box 42, CH-8380 dated July 2011. Eschikon Switzerland.

Forester chips

pellets or following CEN/TS (Where 14961. The fuel must not by Schmid AG, Wood firing XXX is the unit size i.e. 150) contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

300, 360, 450, 550, 700, "Forester 900, 1200, 1600 manufactured November 2009. by Schmid AG, Wood firing Systems PO Box 42, CH-8360 Eschlikon, Switzerland.

Hoval Forester UFS 180, 240, Instruction manual references Wood pellets or wood chips UFS"

dated following CEN/TS 14961. The fuel must contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Hoval STU 150. 250, 300, 350, 425 and manuals Northgate, Nottinghamshire, NG24 1JN. man/01/1, dated June 2008.

Hoval STU 600, 800, and Installation 1000 manufactured by Hoval manual Ltd, Northgate, Newark-on- man/01, 1JN.

HSV 50 + WTH 45, 49 The manufacturer's installation Wood chip or wood pellets. (GmbH), Gunderding A-4952, Weng, Austria.

80 + HSV WTH (GmbH), Gunderding A-4952, Weng, Austria.

HSV 100 100 boilers (GmbH), Gunderding A-4952, Weng, Austria.

Avalon 5 Hunter Slaughterbridge, Cornwall, PL32 9TT.

by Hunter Stoves Limited, Unit "JINHH04 6, Old Mill Industrial Estate, 22/09/2011 Stoke Canon, Devon, EX5 4RJ. "JINHH04&HHC05

200. Installation and

> and referenced dated operation manual referenced preservatives or coatings. STU/man/01/1, dated June 2008.

or 55 boilers manufactured manual version 44 for Wood The by Hargassner Gesellschaft Chip and Pellet Stoves, type contain halogenated organic mit beschrij, ½nkter Haftung HSV 30-100. Reference BA compounds or heavy metals as 8, HSV30-100 RA/RAP V44 a result of treatment with wood 0608.

70, The manufacturer's installation Wood chip or wood pellets. or 80 boilers manufactured manual version 44 for Wood The 0608.

manufactured manual version 44 for Wood The by Hargassner Gesellschaft Chip and Pellet Stoves, type contain halogenated organic mit beschrij, ½nkter Haftung HSV 30-100. Reference BA compounds or heavy metals as 8, HSV30-100 RA/RAP V44 a result of treatment with wood 0608.

> Inset Instruction manual references Wood logs. The fuel must control must contain six 5mm preservatives or coatings. holes.

Hunter Herald 4 manufactured Instruction manual references Wood logs. The fuel must revC" Stop revA" dated 22/07/11. The appliance must be fitted with a permanent stop that prevents closure of secondary air slider beyond 30% open.

manufactured by Hunter Stoves "JINHHC05 Limited, Unit 6, Old Mill 22/09/2011

revC"

operation Wood pellets. The fuel must referenced not contain halogenated organic 500 manufactured by Hoval STUman/01, dated November compounds or heavy metals as Newark, 2007, or referenced STU/ a result of treatment with wood preservatives or coatings.

operation Wood pellets. The fuel must STU/ not contain halogenated organic November compounds or heavy metals as Trent, Nottinghamshire, NG24 2007, or the installation and a result of treatment with wood

fuel preservatives or coatings.

fuel must by Hargassner Gesellschaft Chip and Pellet Stoves, type contain halogenated organic mit beschrij, ½nkter Haftung HSV 30-100. Reference BA compounds or heavy metals as 8, HSV30-100 RA/RAP V44 a result of treatment with wood preservatives or coatings.

> WTH The manufacturer's installation Wood chip or wood pellets. fuel preservatives or coatings.

stove manufactured by Hunter "JINAVI05 Rev B" dated not contain halogenated organic Stoves Ltd, Trevilla Park, 10/10/2012. The valve plate compounds or heavy metals as Camelford, adjusted by the secondary air a result of treatment with wood-

> dated not contain halogenated organic and compounds or heavy metals as Slider a result of treatment with woodpreservatives or coatings.

Hunter Herald 5 Compact Instruction manual references Wood logs. The fuel must dated not contain halogenated organic and compounds or heavy metals as

Industrial Estate, Stoke Canon, "JINHH04&HHC05 Devon, EX5 4RJ.

Stop revA" dated 22/07/11.

The appliance must be fitted with a permanent stop that prevents closure of the secondary air slider beyond 30% open.

Slider a result of treatment with woodpreservatives or coatings.

manufactured by Hunter Stoves "JINHHW05" revC" Limited, Unit 6, Old Mill 22/09/2011. Industrial Estate, Stoke Canon, Devon, EX5 4RJ.

Hunter Herald 5 Slimline Instruction manual references Wood logs. The fuel must

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

by Hunter Stoves Limited, Unit "JINHH04 6, Old Mill Industrial Estate, 22/09/2011. Stoke Canon, Devon, EX5 4RJ.

revC"

Hunter Herald 6 manufactured Instruction manual references Wood logs. The fuel must dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Stoves Ltd, Trevilla Park, 24/01/2013. Slaughterbridge, Camelford, Cornwall, PL32 9TT.

Hunter Herald 8 slimline CE vII Instruction manual references Wood logs. The fuel must stove manufactured by Hunter "JINHHW08 Rev B" dated not contain halogenated organic

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

6, The Old Mill Industrial 02/12/11 and Devon, EX5 4RJ.

dated 05/12/11.

Fitted with "smoke control area kit JHVR0401" when sold into

Hunter Herald i4 manufactured Instruction manual references Wood logs. The fuel must by Hunter Stoves Limited, Unit "JINHVR04 Rev E" dated not contain halogenated organic instruction compounds or heavy metals as Estate, Stoke Canon, Exeter, manual "JINHVR04SCK revB" a result of treatment with woodpreservatives or coatings.

Telford 5 Cornwall, PL32 9TT.

control must contain six 5mm preservatives or coatings. holes.

smoke control areas.

Inset Instruction manual references Wood logs. The fuel must stove manufactured by Hunter "JINTDI05 Rev B" dated not contain halogenated organic Stoves Ltd, Trevilla Park, 10/10/2012. The valve plate compounds or heavy metals as Slaughterbridge, Camelford, adjusted by the secondary air a result of treatment with wood-

organic compounds or heavy

Huntingdon 25 clear door The manufacturer's instruction Untreated dry wood. The fuel (model number 7057) and manual reference PM 249 Issue must not contain halogenated 25 Huntingdon tracery 1. door (model number 7058) A permanent stop must be in metals as a result of treatment Limited, Falcon Road, Sowton to prevent closure beyond the coatings. Industrial Estate, Devon, EX2 7LF.

Stovax place on the secondary air inlet with wood preservatives or

Exeter, 75% open position.

Thermal Output) fitted with Limited's mechanism to prevent closure instructions dated November of the air wash/secondary 2006, Reference: "IN 1141 Ed air control, manufactured by B.".

Hwam 30 (4.5kW Nominal Euroheat Distributors (HBS) Untreated dry wood. operational

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Nydamskvej 53 8362 Horning, with a mechanism to prevent Denmark.

HWAM Heat Design AS The appliance must be fitted closure of the air wash/ secondary air control.

Beethoven H (4.5kW Nominal Limited's Nydamsvej 53 8362 Horning, B". Denmark.

Hwam Beethoven and Hwam Euroheat Distributors (HBS) Untreated dry wood. The fuel Thermal Output) manufactured instructions dated November organic compounds or heavy by HWAM Heat Design AS 2006, Reference: "IN 1141 Ed metals as a result of treatment

The appliance must be fitted coatings. with a mechanism to prevent closure of the air wash/ secondary air control.

operational must not contain halogenated with wood preservatives or

Thermal Output) fitted with Limited's air control, manufactured by B". Denmark.

HWAM Heat Design AS The appliance must be fitted coatings. Nydamsvej 538362 Horning, with a mechanism to prevent closure of the air wash/ secondary air control.

Hwam Mozart (4.5kW Nominal Euroheat Distributors (HBS) Untreated dry wood. The fuel operational must not contain halogenated mechanism to prevent closure instructions dated November organic compounds or heavy of the air wash/secondary 2006, Reference: "IN 1141 Ed metals as a result of treatment with wood preservatives or

thermal Output) fitted with Limited's air control, manufactured by B". Denmark.

HWAM Heat Design AS The appliance must be fitted coatings. Nydamsvej 53 8362 Horning, with a mechanism to prevent closure of the air wash/

Hwam Ravel (4.5kW Nominal Euroheat Distributors (HBS) Untreated dry wood. The fuel operational must not contain halogenated mechanism to prevent closure instructions dated November organic compounds or heavy of the air wash/secondary 2006, Reference: "IN 1141 Ed metals as a result of treatment with wood preservatives or

thermal output) manufactured Limited's AS H�rning, Denmark.

secondary air control.

The appliance must be fitted coatings. with a mechanism to prevent closure of the air wash/ secondary air control.

Hwam Vivaldi (4.5kW nominal Euroheat Distributors (HBS) Untreated dry wood. The fuel operational must not contain halogenated HWAM Heat Design instructions dated November organic compounds or heavy Nydamsvej 53, 8362 2006, Reference: "IN 1141 Ed metals as a result of treatment with wood preservatives or

6 Insert Vissenbjerg, Denmark.

stove ILD 6 Insert stove instruction Wood logs. The fuel must manufactured by Scan A/ manual reference "12-1b GB" not contain halogenated organic S, Glasvi'_k½nget 3-9, 5492 dated 25/02/2013. A permanent compounds or heavy metals as stop preventing closure of a result of treatment with woodthe secondary air control preservatives or coatings. beyond 18% open must be implemented.

Insert 50 Crystal manufactured Instruction manual references Wood logs. The fuel must December 2010. Fitted with compounds or heavy metals as

by La Nordica Spa, Via "6096801-Rev.17" dated 22nd not contain halogenated organic

Summano 104 M. Precalcino, a mechanical stop to prevent a result of treatment with wood-36030 Vicenza, Italy.

closure of the secondary air preservatives or coatings. control beyond the 40% open position when sold into smoke control areas

Summano 104 M. Precalcino, December 2010. 36030 Vicenza, Italy.

Insert 70 Crystal manufactured Instruction manual references Wood logs. The fuel must by La Nordica Spa, Via "6096801-Rev.17" dated 22nd not contain halogenated organic

secondary air control beyond

compounds or heavy metals as Fitted with a mechanical stop a result of treatment with woodto prevent closure of the preservatives or coatings.

36030 Vicenza, Italy.

closure of the secondary air preservatives or coatings. control beyond the 40% open position.

the 40% open position.

Insert 80 Crystal manufactured Instruction manual references Wood logs. The fuel must by La Nordica Spa, Via "6096801-Rev.17" dated 22nd not contain halogenated organic Summano 104 M. Precalcino, December 2010. Fitted with compounds or heavy metals as a mechanical stop to prevent a result of treatment with wood-

Insert 100 Spa, Via Summano 104 M. December 2010. Precalcino, 36030 Vicenza, Italy.

Crystal Instruction manual references Wood logs. The fuel must manufactured by La Nordica "6096801-Rev.17" dated 22nd not contain halogenated organic

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

manufactured by Dik Geurts "Instruction_manual_Instyle Haardkachels BV, Industreweg 1209 ENG". Oost 11, 6662, NE Elst (Gld), The Netherlands.

Instyle 400 and 550 stoves Instruction manual referenced Wood logs. The fuel must

not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Intrepid manufactured by Vermont bearing Castings Inc.

the MAY 1990".

woodstove The manufacturer's instructions No fuel shall be used other than reference 400 millimetre firewood that "AMENDED NO. 20917C UK has been split, stacked and airdried.

La Nordica Spa, Via Summano "7095401 104 M, Precalcino, 36030, 13/12/2010. Vicenza, Italy.

Italy Built In manufactured by Instruction manual references Wood logs. The fuel must Rev.02"

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Italy Termo DSA manufactured Instruction manual references Wood logs. The fuel must by La Nordica Spa, Via "7095802 Summano 104 M. Precalcino 01/02/2011. 36030, Vicenza, Italy.

Rev.06"

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

stove manufactured by James "Ivanhoe Smellie Limited, Unit N Leona Industrial Estate Nimmings Road

multi-fuel dated June 2012.

Ivanhoe JS5000 multi-fuel Instruction manual references Wood logs. The fuel must stove not contain halogenated organic instruction manual Issue 1" compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Halesowen West Midlands B62 9JQ.

Jansen Design stove using the 5 The channel system, manufactured installed, by Kakkelovnsmakeriet A/S.

fireplace shall maintained JDS-01" dated 21/10/91.

be No fuel should be used other and than wood. The fuel must operated in accordance with not contain halogenated organic the manufacturer's instructions compounds or heavy metals as bearing the reference "CSC- a result of treatment with woodpreservatives or coatings.

Jetmaster 18f Fires Limited, Unit 2, Peacock dated June 2011. Trading Estate, Goodwood Road, Eastleigh, Hampshire SO50 4NT.

manufactured by Jetmaster "106870/18f/60f/Issue No.5" not contain halogenated organic

stove Instruction manual references Dry wood logs. The fuel must compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

manufactured by Jotul Limited. the following reference-

Jotul catalyst stove models The manufacturer's instructions No fuel should be used other 12TDIC dated November 1995 bearing than wood.

model 8TDIC: "JT8/001" and "J/S/001";

(ii)

model 12TDIC: "JT12/001" and "JT/S/001".

Jotul UK Limited, Worcestershire, B98 7AS. F100 SC appendix" dated 2010. preservatives or coatings. The appliance must be fitted with a permanent stop that prevents the closure of the secondary air control beyond the 50% open position.

Jotul F100 manufactured by Instruction manual reference Wood logs. The fuel must Unit "129980" dated September not contain halogenated organic 1, The IO Centre, Nash 2002 and smoke control area compounds or heavy metals as Road, Park Farm, Redditch, modification reference "UK a result of treatment with wood-

F263.

Manufactured by Jotul UK Manual Limited.

1 The IO Centre Nash Road Redditch

B98 7AS.

Jotul F162, F163, F262 and Instruction manual references Wood logs. The fuel must "Jotul F162/F162C/F163 not contain halogenated organic Version Po6" compounds or heavy metals as dated January and a result of treatment with wood-Supplementary instruction preservatives or coatings. "Jotul manual F162/ F163/262/263 SMOKE" dated 01/01/2012.

> Fitted with a mechanical stop to prevent secondary air control closure beyond the 20% open position when sold into smoke

control areas.

Jydepejsen Country 510 and Instruction 760 5kW stoves manufactured "Country001" by Jydepejsen

user

manual Wood logs. The fuel must reference not contain halogenated organic A/S, "Jydepejsen A/S – June 2011" compounds or heavy metals as

Ahornsvinget 3-7, Nr.Felding, dated June 2011 A permanent a result of treatment with wood-

DK-7500, Holstebro, Denmark. stop must be fitted to the preservatives or coatings. secondary air control such that it cannot be closed less than 35%

Plesmanweg 27, 7602 PD 26-07-2012. Almelo, the Netherlands.

KW990 woodchip Instruction manual references Woodchip. The fuel must not boiler manufactured by KARA "Maintenance and Operation contain halogenated organic Energy Systems B.V. P.O. Guide KARA Wood Fired compounds or heavy metals as Box 570. 7600 AN Almelo. Boiler Version 2012.02" dated a result of treatment with wood-

preservatives or coatings.

K�B Pyromat-DYN (KPM- Instruction manual references Wood logs (up to 0.5m) and Ltd, Hortonwood 30, Telford, manual Shropshire, TF1 7YP.

85 manufactured by Viessmann 01.01.2005 and instruction chips and pellets. "ID· 103708-G The English".

DYN) Models 45, 65 and "ID 103689-L English" dated off cuts of natural timber, wood

fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Ltd, Hortonwood 30, Telford, manual Shropshire, TF1 7YP.

ECO) Models 35, 45, 55, 65, 75, "ID 104646-D English" dated cuts of natural timber. 85 manufactured by Viessmann 01.01.2005 and instruction The "ID: English".

Kïi, ½ Pyromat-ECO (KPM- Instruction manual references Wood logs (up to 0.5m) and off

fuel must not 104642-B contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Viessmann Ltd, Hortonwood manual 30, Telford, Shropshire, TF1 English". 7YP.

ECO) Models 61, 81, 101 "ID 104646-D English" dated cuts of natural timber. and 151 manufactured by 01.01.2005 and instruction The "ID:

Kïi, ½ Pyromat-ECO (KPM- Instruction manual references Wood logs (up to 1.0m) and off

fuel must not 104642-B contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Kïi/½B Pyrot (KRT) Models Instruction manual references Wood chips or pellets. Ltd, Hortonwood 30, Telford, manual Shropshire, TF1 7YP.

100, 150, 220, 300, 400 and 540 "ID 104654-H English" dated The manufactured by Viessmann 01.01.2005 and instruction contain halogenated organic "ID: English".

fuel 106811-H compounds or heavy metals as a result of treatment with wood preservatives or coatings.

K�B Pyrtec (KPT) Models Instruction manual references Wood chips or pellets. Ltd, Hortonwood 30, Telford, manual Shropshire, TF1 7YP.

390, 530, 720, 950 and 1250 "ID 104661-F English" dated The manufactured by Viessmann 01.01.2005 and instruction contain halogenated organic "ID: English". be fitted with multicyclone preservatives or coatings. dedusters.

fuel 105174-F compounds or heavy metals as

Appliances must a result of treatment with wood

Kooga Cleanburn manufactured Doughty & Co, Imperial Point, 2010.

Stove Instruction manual references Wood logs. The fuel must Percy "KCB 04/10A" dated April not contain halogenated organic

compounds or heavy metals as

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Express Trading Estate, Stone Hill Road, Farnworth, Bolton, BL4 9TN.

639kW Akhisar/Manisa, Turkey.

output Only when used with a 6mm diameter wood pellets. pellet boiler manufactured by Glosfume model BMF208 The boiler owner/operator's manual preservatives or coatings. reference version 1A 2010 dated December 2010. The Glosfume Ltd maintenance and instruction manual for Glosfume BMF **Biomass** Filter units (50 to 1000kW) version AEE001-VER4 dated December 2010.

a result of treatment with wood preservatives or coatings.

fuel must Kaylıoğlu Kasabası (İzmir- ceramic particulate filter. The contain halogenated organic İstanbul Yolu �zeri) P.K 23 Green energy engineering compounds or heavy metals as Ltd (GEE) KOZ550 pellet a result of treatment with wood-

PONAST spol. s r.o. Na Potůčkï;½ch 163

757 01 Meziři; ½či;½

Czech Republic.

12, 15, 22, 25, 30 and 35 wood KWB Easyfire EN, 05.2011" not contain halogenated organic pellet boilers manufactured by dated 05 2011 and installation compounds or heavy metals as KWB – Kraft und Wij.½rme manual "M KWB Easyfire, a result of treatment with woodaus Biomasse Gesellschaft 05.2011" dated 05 2011. mit beschri; ½nkter Haftung, A-8321 St. Margarethen/Raab Industriestraï; ½e 235, Austria.

aus Biomasse Gesellschaft BA-USV 0803. mit Beschri; ½nkter Haftung, Industriestrasse 235

8321 St. Margarethen/Raab, Austria, 8321.

Wood chip and boiler manufactured June 2010. Kraft und W�rme aus Biomasse Gesellschaft mit Beschri; ½nkter Haftung, Industriestrasse 235

KP12, KP22 and KP62 Wood Service manual references Wood pellets. The fuel must Valašsk� 25/05/2012.

KWB Easyfire EF2 S/GS/V 8, Operation manual reference "B Wood pellets. The fuel must preservatives or coatings.

KWB Multifire USV 15, 25, The fireplace(s) must

pellet boilers manufactured by "QPP051-2" dated 25/05/2012 not contain halogenated organic and instructions for operation compounds or heavy metals as manual "QPP049-3" dated a result of treatment with woodpreservatives or coatings.

be Wood chips and wood 30, 40, 50, 60, 80, 99 and installed, maintained and pellets. The fuel must not 100 wood-pellet and wood- operated in accordance with contain halogenated organic chip fired boilers manufactured the manufacturer's instructions compounds or heavy metals as Kraft und Wij. ½rme dated August 2003, reference a result of treatment with woodpreservatives or coatings.

KWB Multifire USV 49.5kW Instruction manual references Wood wood "BA Multifire 06.2010" dated pellets. The fuel must not

chips and contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

8321 St. Margarethen/Raab, Austria, 8321.

KWB TDS Powerfire 130, The manufacturer's instructions Wood mit Beschri; ½nkter Haftung fuels. (GmbH) of Industriestrasse 235, A-8321 St. Margarethen an der Raab, Austria.

240 and 300 manufactured dated 14th May 2008, reference chips. The fuel must not by KWB-Kraft und Wi¿½rme BA TDS-05.2008, including contain halogenated organic aus Biomasse Gesellschaft specification of recommended compounds or heavy metals as

wood a result of treatment with wood preservatives or coatings.

150, manufactured KWB-Kraft und Wï, ½rme BA TDS-0805. aus Biomasse Gesellschaft mit Beschrij¹/₂nkter Haftung (GmbH) of Industriestrasse 235, A-8321 St. Margarethen an der Raab, Austria.

Powerfire The manufacturer's instructions Wood by dated August 2005, reference chips. The fuel must not

pellets or wood contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

a multi-cyclone (type LIN-KA dated 27/01/2010. 3x2) manufactured by LIN-KA Maskinfabrik A/S, Nylandsvej 38 DK-6940 Lem St. Denmark.

fitted with either a mono- "LIN-KA H 1500 Hot Water diameter 8mm. cyclone (type LIN-KA 2000) or Manual/Ver. 2005/Rev. 1.10" The

Lin-ka H1500 Hot Water Boiler Instruction manual reference Wood Pellets of maximum

contain halogenated organic

compounds or heavy metals as

must

Thurlow Control Wood Burning Stove operating instructions dated 30 manufactured by Town & June 2007, issue No.3. Country Fires Limited, Enterprise Way, Thornton Road Industrial Estate, Pickering, North Yorkshire, YO18 7NA.

a result of treatment with wood preservatives or coatings. Smoke Town and country Fires' Seasoned logs of less than 20% moisture and of a maximum length of 350 mm. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment

with wood preservatives or

coatings.

by Aga, Station Road, Ketley, N00471 AXX Telford, Shropshire. TF1 5AQ. DP081219.

Rev

Little Wenlock Classic SE Operating instructions dated Dry and split wood logs of Wood Fuel Stove manufactured 19th December 2008, reference a maximum length of 25 cm 001 and a maximum diameter of 10 cm. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Stoves Limited. House. Junction

Darwen, Lancashire, BB3 2RB. control slots beyond the 21mm preservatives or coatings. open position when sold into smoke control areas.

LogFire LF6cT Wood Burning Instruction manual references Wood logs. The fuel must Stove manufactured by LogFire "LF6cT-1" dated 18/12/2012. not contain halogenated organic Britannia Fitted with a mechanical stop compounds or heavy metals as Street, to prevent closure of the air a result of treatment with wood-

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Lotus Heating Systems A/S Petite Agertoften 6 Denmark 5550.

to prevent closure of the air preservatives or coatings. damper beyond the 5mm open position must be implemented.

Lotus H370 Petite 6.6kW Instruction manual references Wood logs. The fuel must insert stove manufactured by "Fireplace Insert, Lotus H370 not contain halogenated organic Version 1" dated compounds or heavy metals as 11/10/2012. A mechanical stop a result of treatment with wood-

Lotus Liva 1, Liva 2, Liva 3 and Instruction manual "Mounting Wood logs. The fuel must Agertoften 6, 5550 Langeskov, dated January 2010. Denmark.

Liva 4G Stoves manufactured and User Instructions Lotus- not contain halogenated organic by Lotus Heating Systems A/S, Liva series Stoves" Version 4, compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Agertoften 6, 5550 Langeskov, dated January 2010. Denmark.

Lotus Sola, Sola S, Sola M and Instruction manual "Mounting Wood logs. The fuel must Sola MST Stoves manufactured and User Instructions Lotus- not contain halogenated organic by Lotus Heating Systems A/S Sola series Stoves" Version 2 compounds or heavy metals as

a result of treatment with wood preservatives or coatings.

Hunter Stoves Limited, Unit installation 6, Old Mill Industrial Estate, manual version 07/08. Stoke Canon, Exeter, Devon. EX5 4RJ.

and

L�venholm manufactured by L�venholm Multifuel stove Untreated wood with a moisture operation content below 20%. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

L�venholm, L�venholm installation Traditional, European, Pedestal stoves manufactured by Hunter Stoves Limited, Unit 6, Old Mill Industrial Estate, Stoke Canon, Exeter, Devon, UK EX5 4RJ.

and L�venholm manual version 06/09.

L�venholm L�venholm Multifuel stove Untreated wood with a moisture operation content below 20%.

> fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Loxton 3 stoves manufactured Instruction manual references Wood logs. The fuel must Unit H1, Mendip Industrial 3," dated July 2012. Estate, Mendip 2UG.

by Mendip Stoves Limited, "Mendip Stoves Ltd, 2012, ver not contain halogenated organic Road, A permanent stop to fix the a result of treatment with wood-Rooksbridge, Somerset, BS26 secondary air control such preservatives or coatings. that it cannot be closed more than 25% open must be implemented.

compounds or heavy metals as

Loxton 5. Churchill and Sqabox Uno manufactured by Mendip Industrial Somerset, BS26 2UG.

5 Instruction manual references Wood logs. The fuel must stoves "Mendip Stoves Ltd, 2012, ver not contain halogenated organic Mendip 3" dated July 2012. Stoves Limited, Unit H1, A permanent stop such that the a result of treatment with wood-Estate, secondary air 'closed position' preservatives or coatings. Mendip Road, Rooksbridge, results in a 2.5mm gap in the two secondary air openings must be implemented.

compounds or heavy metals as

Duo stoves manufactured by 3" dated July 2012. Somerset, BS26 2UG.

6, Churchill 8 and Sqabox "Mendip Stoves Ltd, 2012, ver not contain halogenated organic

Mendip Stoves Limited, Unit A permanent stop on the a result of treatment with wood-H1, Mendip Industrial Estate, secondary air control such preservatives or coatings. Mendip Road, Rooksbridge, that it cannot be closed more than 35% open must be implemented.

Loxton 6, Loxton 8, Churchill Instruction manual references Wood logs. The fuel must compounds or heavy metals as

SE) manufactured by Aga, 13th July 2011. Station Road, Ketley, Telford, Shropshire, TF1 5AQ.

Ludlow Wood Burning Smoke Instruction manual references Dry wood logs. The fuel must Exempt Stove (Ludlow Stove "N00529AXX REV:001" dated not contain halogenated organic

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Marvic Multifuel (inset) manufactured by Fires & Stoves, Netherlands.

roomheater "INK.00.7927" Wanders 20/12/2011. Amtweg All appliances will be fitted a result of treatment with wood-4, Netterden, NL-7077 AL, with a modification to the preservatives or coatings. secondary air control to ensure that the air supply holes remain 3mm open when the operator

Cassette Instruction manual reference Wood logs. The fuel must dated not contain halogenated organic compounds or heavy metals as

Mawera Fu-ria models 110, The manufacturer's instructions No fuel should be used 140, 180, 220, 280 and 350 dated 31st manufactured by Mawera (UK) and bearing the reference or wood products, Limited.

October 098234-01.

has nominally shut the control.

2002 other than natural wood forest residues and forest thinnings, uncoated MDF chipboard, plywood and compound wood products. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

(Hooton) Ltd, Station Works, Hooton Road, Hooton, South Wirral, CH66 7NF.

MEG 4.5 (also known as the Instruction manual references Wood logs. The fuel must Sirius 450) manufactured by "Meg Solid Fuel Stoves Manual not contain halogenated organic

Meg Stoves, F.E. Robinson (107)" dated 28th January 2011. compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Meg 5.0 stove and Sirius 600 Instruction manual references Wood logs. The fuel must Inset stove. Manufactured by F.E. Robinson 27/07/2012. (Hooton) Ltd. Station Works Hooton Road Hooton South Wirral CH66 7NF.

"Manual Version 1.3" dated not contain halogenated organic Fitted with a mechanical stop a result of treatment with wood-

to prevent secondary air control preservatives or coatings. closure beyond the 10mm open position when sold into smoke control areas.

compounds or heavy metals as

MEG 7.5 (also known as the Instruction manual references Wood logs. The fuel must (Hooton) Ltd, Station Works, Hooton Road, Hooton, South Wirral, CH66 7NF.

Sirius 750) manufactured by "Meg Solid Fuel Stoves Manual not contain halogenated organic Meg Stoves, F.E. Robinson (107)" dated 28th January 2011. compounds or heavy metals as

a result of treatment with woodpreservatives or coatings.

manufactured by Engineering Limited, Unit 7, Newton Chambers Way, Thorncliffe Industrial Estate, Chapeltown, Sheffield S35 2PH.

Mendip SE Wood Burning Instruction manual references Wood logs. The fuel must 5kW Space Heating Stove "700273 Iss. 2 Rev. 1" dated not contain halogenated organic TR January 2012.

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

manufactured by Engineering Limited, Unit 7, Newton Chambers Way, Thorncliffe Industrial Estate, Chapeltown, Sheffield, S35 2PH

Mendip SE Wood Burning Instruction manual references Wood logs. The fuel must 8kW Space Heating Stove "700275 Iss. 2 Rev.1" dated not contain halogenated organic TR January 2012.

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Mescoli PB50 Mescoli PB35 by MESCOLI CALDAIE S.rl. 2 Caldaie – Termocucine Via Edition 1.7 dated 1/2006. del Commercio, 285 4 1058 Vignola (MO) Italy.

Instruction and Installation Wood Mescoli PB28 Manufactured P, C, B - COMBIFIRE (DIN 51731). PB28/35/50 BOILERS" The

Pellets following manual reference "SY315EVO" i. ½NORM M7 135 or DIN plus

> fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

known as the Sirius 450) "Micromet 125 Bridge Street, Birkenhead, 16/06/2010. Merseyside, CH41 1BD.

Solid

Micromet MEG 4.5 stove (also Instruction manual references Dry wood logs. The fuel must Fuel not contain halogenated organic manufactured by Micromet, Stoves Manual (24)" dated compounds or heavy metals as a result of treatment with wood preservatives or coatings.

known as the Sirius 750) "Micromet 125 Bridge Street, Birkenhead, 16/06/2010. Merseyside, CH41 1BD.

Solid

Micromet MEG 7.5 stove (also Instruction manual references Dry wood logs. The fuel must Fuel not contain halogenated organic manufactured by Micromet, Stoves Manual (24)" dated compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Milan Series 4 manufactured by Instruction manual references Wood logs. The fuel must Battersea Park Road, London November 2010. SW11 4ND.

Chesney's Limited, 194 – 200 "CH4K Milan-V2" dated 18 not contain halogenated organic Fitted with a system to prevent a result of treatment with woodclosure of the air control beyond preservatives or coatings. the 25mm open position.

compounds or heavy metals as

November 2010.

Milan Series 6 manufactured by Instruction manual references Wood logs. The fuel must Chesney's Limited, 194 – 200 "CH6K Milan-V2" dated 18 not contain halogenated organic compounds or heavy metals as

SW11 4ND.

closure of the air control beyond preservatives or coatings. the 40mm open position.

Battersea Park Road, London Fitted with a system to prevent a result of treatment with wood-

Monaco multifuel Stove, Staub Instruction manual references Wood logs. The fuel must 59660 Merville, France.

Rue Orphee Variscotte, BP73, closure of the secondary air preservatives or coatings. control beyond 4mm from closed when sold into smoke control areas.

Fonderie-Franco Belge model "1303 – 1" dated 04/05/2010. not contain halogenated organic 1340605, manufactured by Appliances will be fitted with compounds or heavy metals as Staub Fonderie-Franco Belge, a mechanical stop to prevent a result of treatment with wood-

Mondo 1, Mondo 2 and Mondo Instruction manual references Wood logs. The fuel must Denmark.

closure of the air dampers preservatives or coatings. beyond the 8mm open position must be implemented.

petite stoves manufactured by "Lotus –Mondo Series Stoves not contain halogenated organic Lotus Heating Systems A/S, Version 1" dated 15/10/12. A compounds or heavy metals as a Agertoften 6, 5550 Langeskov, mechanical stop to prevent result of treatement with wood-

Monterrey 6, York Midi, Instruction manual references Wood logs. The fuel must SY1 3AB.

Serrano 5 manufactured by "09TJD" dated 01 2010. not contain halogenated organic Broseley Fires Ltd, Knights The fitting of a system that compounds or heavy metals as Way, Battlefield Enterprise prevents the closure of the a result of treatment with wood Park, Shrewsbury, Shropshire, secondary air flaps to be less preservatives or coatings. than 8mm open position should be implemented.

by MORSï, ½ Limited, Unit 7 "ï, ½-Collection" Valley, Rugby, Warwickshire, manual CV21 1TW.

MORSï_{i,\('/2}-ï_{i,\('/2}\)4 manufactured Instruction manual references Wood logs. The fuel must - io centre Valley Drive, Swift 01.02.2010 and instruction compounds or heavy metals as "72000400" 01.02.2010.

Applies to units manufactured

after 01 February 2010.

dated not contain halogenated organic dated a result of treatment with wood preservatives or coatings.

Morsï, ½ 1400 series consisting Installation of the 1412 and manufactured by Mors� 2008, reference 72146800. Jernst�beri A/S DK-7900 Nykï;½bing, Mors, Denmark.

and 1442 manual dated 10th January 20% moisture. The fuel must

operation Wood logs with less than not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Mors� 1416, 1418, 1446 and Instruction manual references Wood logs. The fuel must 1448 4kW stoves manufactured "Mors� 1416, Swift Valley, Rugby, CV21 dated 31/01/2012. Part No: preservatives or coatings.

72150000.

1418, not contain halogenated organic by Mors� UK Limited, Unit 1446 & 1448. Instruction compounds or heavy metals as 7 The io Centre, Valley Drive, for installation and use" a result of treatment with wood-

Morsi, ½ 3100 series consisting Installation manufactured by Mors� 2008, reference 72311200. Jernst�beri A/S, DK-7900 Nyk�bing, Mors, Denmark.

and

operation Wood logs with less than of the 3112 and 3142 models manual dated 4th February 20% moisture. The fuel must not contain halogenated organic compounds or heavy metals as

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Morsi; ½ 3400 Owl GB Series The manufacturer's instructions No fuel shall be used other for wood burning manufactured dated DK-7900 Nyk�bing, Mors, "72345600". Denmark.

 1^{st} January by Mors� Jernst�beri A/S, and bearing the reference (a)

a result of treatment with wood preservatives or coatings.

2000 than—

untreated dry wood which has been split, stacked and air dried; or

(b)

air dried wood briquettes.

Mors \ddot{i}_0 6140 and 6148 Installation Jernstiζ,½beri A/S DK-7900 2007, reference 72610400. Nykï;½bing, Mors, Denmark.

and manufactured by Morsi¿½ manual dated 4th September 20% moisture. The fuel must

operation Wood logs with less than not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Model 7642. 7644 7648 stoves manufactured dated 14.07.2010. Valley Drive, Swift Valley, minimum 1TW.

and use 7600 reference "72762200" 20% moisture. The fuel must by Morsi, ½ Limited, UK The air control on UK models compounds or heavy metals as distribution by Morsi, 1/2 UK has been altered such that a result of treatment with wood Limited, Unit 7, The io Centre, this equates to an increased preservatives or coatings. open position. Rugby, Warwickshire, CV21 Reference drawings Morsi, ½ 7600-137, 7600-138, 7600-139,

Morsï; ½ Model 7600 including Instructions for installation and Wood logs with less than not contain halogenated organic

and 3440 for wood burning dated 1st manufactured by Mors� reference 72345600. Jernsti; ½beri A/S DK-7900 Nyk�bing, Mors, Denmark.

Morsi; ½ Owl 3410, 3420 The manufacturer's instruction Untreated dry wood which has January

7600-140 and 7600-141.

2000, been split, stacked and air dried; or air dried wood briquettes.

Mors� S10-40 5kW stove Instruction manual references Wood logs. The fuel must manufactured by Morsi, ½ UK " Morsi, ½ S10. Instruction not contain halogenated organic Rugby, CV21 1TW.

Rugby, CV21 1TW.

Morsï; ½ Valley Drive, Swift Valley, 72114200. Rugby, CV21 1TW.

72104000.

Morsï; ½ S10-70 5kW stove Instruction manual references Wood logs. The fuel must manufactured by Morsï_i,½ UK "Morsï_i,½ S10-70. Instruction not contain halogenated organic Limited, Unit 7 The io Centre, for installation and use" compounds or heavy metals as Valley Drive, Swift Valley, dated 31/01/2012. Part No: a result of treatment with wood-72103000.

S11-40, S11-42, Instruction manual references "Wood logs. The fuel must

Limited, Unit 7 The io Centre, for Installation and use" compounds or heavy metals as Valley Drive, Swift Valley, dated 31/01/2012. Part No: a result of treatment with woodpreservatives or coatings.

preservatives or coatings.

S11-43 and S11-90 4kW stoves Morsï₄½ S11 serien. Instruction not contain halogenated organic manufactured by Morsï_i,½ UK for Installation and use" compounds or heavy metals as Limited, Unit 7 The io Centre, dated 31/01/2012. Part No: a result of treatment with woodpreservatives or coatings.

Morsï₄½ S81-90 4kW stove Instruction manual references Wood logs. The fuel must manufactured by Mors� UK "Mors� S81-90. Instruction not contain halogenated organic

Valley Drive, Swift Valley, 30/01/2012. Rugby, CV21 1TW.

Limited, Unit 7 The io Centre, for Installation and use" dated compounds or heavy metals as

a result of treatment with woodpreservatives or coatings.

Multibio 49 Inc. Semecska 187, 411 15 04/07/2012. Trebivlice, Czech Republic.

pellet boiler Instruction manual references Wood manufactured by Ekoefekt "MB49/IM/ISSUE 001" dated kernels. The fuel must not

pellets or contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

De Lion, B-5660, Frasnes Les and dated June 2010. Couvin, Belgium.

Nestor Martin C23 multifuel Euroheat Distributors (HBS) Untreated dry wood. The fuel stove (7.7kW) manufactured by Limited's operation Instructions must not contain halogenated Nestor Martin S.A., 11 Rue Reference: "IN1213 Edition B" organic compounds or heavy

metals as a result of treatment with wood preservatives or coatings.

stove (9.2kW) manufactured by Limited's Nestor Martin S.A., 11 Rue Instructions Couvin, Belgium.

De Lion, B-5660, Frasnes Les "IN1213 Edition B" and dated metals as a result of treatment June 2010.

Nestor Martin C33 multifuel Euroheat Distributors (HBS) Untreated dry wood. The fuel operation. must not contain halogenated Reference: organic compounds or heavy with wood preservatives or coatings.

De Lion, B-5660, Frasnes Les B", and dated June 2010. Couvin, Belgium.

Nestor Martin D33 multifuel Euroheat Distributors (HBS) Untreated dry wood. The fuel

stove (8kW) manufactured by Limited's operation Instructions must not contain halogenated Nestor Martin S.A., 11 Rue Reference: "IN1213 Edition organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Nestor Martin H13 multi-fuel stove (5kW) Limited's manufactured bv B-5660, Frasnes Les Couvin, June 2010. Belgium.

The minimum air bleed flap coatings.

must be set at a minimum of

14.5mm.

'Harmony' Euroheat Distributors (HBS) Untreated dry wood. The fuel operation. must not contain halogenated Nestor Instructions Reference: "IN organic compounds or heavy Martin, S. A., 11 Rue De Lion, 1116 Edition D5" and dated metals as a result of treatment with wood preservatives or

Nestor Martin 'Harmony' H23 Euroheat Distributors (HBS) Untreated dry wood. The fuel (6kW) and H33 (8kW) multi- Limited's De Lion, B-5660 Frasnes Les June 2010. Couvin, Belgium.

operation, must not contain halogenated fuel stoves manufactured by Instructions Reference: "IN organic compounds or heavy Nestor Martin S. A., 11 Rue 1116 Edition D5" and dated metals as a result of treatment with wood preservatives or coatings.

Nestor Martin IN13 Insert Euroheat Distributors (HBS) Untreated dry wood. The fuel multi-fuel stove Frasnes Les Couvin, Belgium.

(5kW), Limited's 2010.

operation. must not contain halogenated manufactured by Nestor Martin Instructions Reference: "IN organic compounds or heavy S. A., 11 Rue De Lion, B-5660 1214 Edition B" and dated June metals as a result of treatment with wood preservatives or

The minimum air bleed flap coatings. must be set at a minimum of 14 5mm

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Nestor Martin IT13 multi-fuel Euroheat Distributors (HBS) Untreated dry wood. The fuel stove (3.5kW), manufactured Limited's Couvin, Belgium.

operation. must not contain halogenated by Nestor Martin S A., 11 Rue Instructions Reference: "IN organic compounds or heavy De Lion, B-5660, Frasnes Les 1180 Edition D1" and dated metals as a result of treatment June 2010.

The minimum air bleed flap coatings. must be set at a minimum of 14.5mm.

Stove (6kW) manufactured by Limited's Couvin, Belgium.

November 2006.

Nestor Martin R23 Multi-fuel Euroheat Distributors (HBS) Untreated dry wood. The fuel operation, must not contain halogenated Nestor Martin S. A., 11 Rue Instructions Reference: "IN organic compounds or heavy De Lion, B-5660, Frasnes Les 1141 Edition B" and dated metals as a result of treatment with wood preservatives or coatings.

with wood preservatives or

multifuel stove, manufactured Limited's by Nestor Martin S A., 11 Rue Instructions Couvin, Belgium.

January 2007.

Nestor Martin R33 (8kW) Euroheat Distributors (HBS) Untreated dry wood. The fuel operation. must not contain halogenated Reference: organic compounds or heavy De Lion, B-5660, Frasnes Les "IN1116 Edition D" and dated metals as a result of treatment with wood preservatives or coatings.

Nestor Martin 'Stanford' S13 Euroheat Distributors (HBS) Untreated dry wood. The fuel Multi-fuel Stove Frasnes Les Couvin, Belgium. June 2010.

(3.5kW) Limited's manufactured by Nestor Martin Instructions Reference "IN organic compounds or heavy S. A., 11 Rue De Lion, B-5660, 1116 Edition D5" and dated metals as a result of treatment The minimum air bleed flap coatings.

14.5mm

operation. must not contain halogenated with wood preservatives or must be set at a minimum of

Nestor Martin 'Stanford' S23 Euroheat Distributors (HBS) Untreated dry wood. The fuel (6kW), SP23 (6kW), S33 Limited's Nestor Martin S. A., 11 Rue June 2010. De Lion, B-5660, Frasnes Les Couvin, Belgium.

operation. must not contain halogenated (8kW) and SP33 (8kW) Multi- Instructions Reference: "IN organic compounds or heavy fuel stoves manufactured by 1116 Edition D5" and dated metals as a result of treatment with wood preservatives or coatings.

Newark EGTL05 manufactured Instruction manual references Wood logs. The fuel must Elite Group Limited, Room 1208, Kak Tak 5th July 2011. Kong 999077.

Des Voeux Road Central, Hong stop to prevent any closure of preservatives or coatings. the tertiary air control.

Trading "EGTL05 Version 1.4" dated not contain halogenated organic compounds or heavy metals as Commercial Building, 317-319 Factory fitting of a permanent a result of treatment with wood-

Freestanding manufactured by IP12 4PS.

stoves "Pevex1012/AH/ver1" Acres, Waldringfield, Suffolk, minimum opening area of 1cm² preservatives or coatings. for the primary air slider when in the fully closed position and a tertiary air inlet area of 4cm².

Newbourne 40 and Newbourne Instruction manual references Wood logs. The fuel must not dated contain halogenated organic Pevex Jan 2013. A permanent stop compounds or heavy metals as Enterprises Ltd, Unit 16, Seven must be implemented using a a result of treatment with wood-

manufactured by IP12 4PS.

Newbourne 40 inset stove Instruction manual references Wood logs. The fuel must not Pevex "Pevex1015/AH/ver1" dated contain halogenated organic Enterprises Ltd, Unit 16, Seven Jan 2013. The appliance must compounds or heavy metals as Acres, Waldringfield, Suffolk, be fitted with permanent stops a result of treatment with woodthat ensure the secondary and preservatives or coatings. tertiary air controls do not close beyond 1.1cm open and 2cm open positions respectively.

manufactured by Engineering Limited, Unit 7, Newton Chambers Way, Thorncliffe Industrial Estate, Chapeltown, Sheffield, S35 2PH.

Newton SE Wood Burning Instruction manual references Wood logs. The fuel must 5kW Space Heating Stove "700504 Iss. 2 Rev 1" dated not contain halogenated organic TR January 2012.

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Newton SE Wood Burning Instruction manual references Wood logs. The fuel must manufactured by Engineering Limited, Unit 7, Newton Chambers Way, Thorncliffe Industrial Estate, Chapeltown, Sheffield, S35 2PH.

8kW Space Heating Stove "700506 Iss. 3 Rev. 2" dated not contain halogenated organic TR January 2012.

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

C DE A Ingenieria Ltda, number Jose Miguel Carrera 6, Colina, 20/07/2012. Santiago, 9361294, Chile.

"1001"

Nordic 350 manufactured by Instruction manual reference Wood logs. The fuel must dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

models 10, 11, 12, 13, 14, 15, dated 9th December 1988 and and 23 manufactured in part 9/12/88". by Nordfab A/S and in part by Danstoker A/S.

Nordist Waste Fired System, The manufacturer's instructions Softwood shavings, hardwood shavings or sawdust shall be 16, 17, 18, 19, 20, 21, 22 bearing the reference "P.S. 501 used. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Nï;½rreskoven manufactured for Hunter Stoves "Cleanburn, Limited, Unit 6, Old Mill MkII, Devon, EX5 4RJ.

Multifuel Instructions, v01.11." dated preservatives or coatings. January 2011. The device has a factory fitted stop to prevent closure of secondary air control beyond 40%.

MkII Instruction manual references Wood logs. The fuel must N�rreskoven not contain halogenated organic Stove. compounds or heavy metals as Industrial Estate, Stoke Canon, Installation and Operating a result of treatment with wood-

Norvik 5 manufactured by Elite Instruction manual references Wood logs. The fuel must Group Trading Limited, Room "EGTL05A Version 1.5" dated not contain halogenated organic 1208 Kak Tak, Commercial 12th September 2011. The compounds or heavy metals as Building 317-319 Des voeux appliance must be fitted with a result of treatment with woodpreservatives or coatings.

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Road, Central Hong Kong a permanent stop to prevent 999077. any closure of the tertiary air control.

Octoplus 10 and Octoplus Installation instructions Version Wood pellets. The fuel must 15 Boiler manufactured by 1.1 Solarfocus, Werkstrasse 1, 4451 Operating manual St.Ulrich, Steyr, Austria.

dated 10.051 dated 10/05/2010.

19/04/2010. not contain halogenated organic Version compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

�koFEN Pellematic PE08, �koFEN PEK25, PES12, PEK32, PES16, PES20, PES25. PESK12, PES32. PESK16. PESK20, PESK25 and PESK32 manufactured by �koFEN Forschungs-und Entwicklungs Ges.m.b.H of Gewerbepark 1, 4133 Niederkappel, Austria.

PE12, PE16, PE20, PE25, instructions dated February diameter 6 mm and maximum PE32, PEK12, PEK16, PEK20, 2007, reference PE/HB/001.E.

operation Wood pellets of maximum length 4 cm. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

�koFEN Pellematic PE36, �koFEN PESK36, PESK48, PESK56 revision dated March 2008. manufactured by �koFEN Forschungs-und Entwicklungs Ges.m.b.H of Gewerbepark 1, 4133 Niederkappel, Austria.

PE48, PE56, PEK36, PEK48, instructions reference PBV diameter 6 mm and maximum PEK56, PES36, PES48, PES56, 2000 CMP 1.4 (V2.31) and with length 4 cm. The fuel must

operation Wood pellets of maximum not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Olymberyl Baby model number UK Distribution by Limited, Unit Cheshire, CW4 8AF.

HF217-SE. "HF217-SE/UK-NI-ROI/ Hi- V2.16-06-11". Dated June compounds or heavy metals as 7B 2011. Holmes Chapel Business Park, Fitted with a mechanical stop preservatives or coatings. Manor Lane, Holmes Chapel, to prevent closure of the secondary air control beyond the 3mm open position.

Gabriel Instruction manual references Wood Logs. The fuel must not contain halogenated organic a result of treatment with wood-

Optifire 800 Green, Infire 800 Instruction manual reference Wood logs. The fuel must Green, Wood Burning Stoves. "07DH8000A" dated 11/11. Gonav Limited. Rue De Lambinon

3 Harze Belgium

4920.

Manufactured by Bodart & Fitted with a "UK kit for compounds or heavy metals as smokeless areas OPTI IF 800" a result of treatment with woodwhen sold into smoke control preservatives or coatings. areas.

not contain halogenated organic

Speciale 80, 100, 110, 110 x 160 and 120; TOP Superiore 100 and 120; GR 100, 120, 140, 120 x 160, 140 x 160, 140 x 180 and 180; OT 100, 120, 140, 120 OOLinst.2 FVR.100 x 160, 140 x 160, 140 x 180 OOLinst.3 FVR 110

Orchard Ovens models: FVR The manufacturer's instructions Untreated dry wood. dated 25th October

references:

Instruction Model

OOLinst.1 FVR 80

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

and 180; the Valoriani Piccolo, OOLinst.4 FVR 120 all of which are manufactured OOLinst.5 FVR 110 x 160 by Valoriani of Via Caselli alla OOLinst.6 TOP 100 Fornace, 213, 50066 Reggello, OOLinst.7 TOP. 120 Firenze, Italy.

OOLinst.8 GR 100 and OT 100 OOLinst.9 GR 120 and OT 120 OOLinst.10 GR 140 and OT 140 OOLinst.11 GR 120 x 160 and OT 120 x 160 OOLinst.12 GR 140 x 160 and OT 140 x 160 OOLinst.13 GR 140 x 180 and OT 140 x 180 OOLinst.14 GR 180 and OT OOLinst.15 Valoriani Piccolo.

Limited, Room 1208, Kak Tak 5th July 2011. Commercial Building, 317-319 Des Voeux Road Central, Hong Kong 999077.

Oregon EGTL03 manufactured Instruction manual references Wood logs. The fuel must by Elite Group Trading "EGTL03 Version 1.3" dated not contain halogenated organic

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Osby Parca PB2 2000kW boiler Operating & Osby Parca Division, PO Box "manual 93, SE-283 22 Osby, Sweden.

PB2 ENG Rev2 JAN2012" dated Jan 2012.

Maintenance Wood pellets. The fuel must manufactured by Enertech AB, manual, PB2 boiler reference not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Osby Parca PB2 3000kW boiler Operating Osby Parca Division, PO Box "manual 93, SE-283 22 Osby, Sweden.

& manufactured by Enertech AB, manual, PB2 boiler reference wood briquettes. The fuel must PB2 ENG Rev2 JAN2012"

dated Jan 2012.

Maintenance Wood pellets, wood chips, not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Caprice Parkrav Limited, Unit 6, The Old Mill 02/12/11 Exeter, Devon, EX5 4RJ.

4 Instruction manual references Wood logs. The fuel must manufactured by Hunter Stoves "JINCAP04 Rev E" dated not contain halogenated organic and Industrial Estate, Stoke Canon, manual "JINCAP04SCK revB" a result of treatment with wooddated 05/12/11.

instruction compounds or heavy metals as preservatives or coatings.

Fitted with "smoke control area kit JCAP0401" when sold into smoke control areas.

Parkray Caprice Cornwall, PL32 9TT. dated 06/07/12. The appliance preservatives or coatings. must be fitted with smoke control area kit JCAP0501.

inset Instruction manual references Wood logs. The fuel must stove manufactured by Hunter "JINCAP05 Rev B" dated not contain halogenated organic Stoves Ltd, Trevilla Park, 10/12/2012 and instruction compounds or heavy metals as Slaughterbridge, Camelford, manual "JINCAP05SCK revA" a resultof treatment with wood-

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Parkrav stove manufactured by Hunter "JINCAP06 Slaughterbridge, Cornwall, PL32 9TT.

RevB" 06/07/2012. dated appliance must be fitted with smoke control area kit JCAP0501.

Caprice 6 inset Instruction manual references Wood logs. The fuel must dated not contain halogenated organic Stoves Ltd, Trevilla Park, 10/12/2012 and instruction compounds or heavy metals as Camelford, manual "JINCAP05SCK revA" a result of treatment with wood-The preservatives or coatings.

Parkray Chevin 5 Slaughterbridge, Cornwall, PL32 9TT.

Inset Instruction manual references Wood logs. The fuel must stove manufactured by Hunter "JINCHI05 Rev B" dated not contain halogenated organic Stoves Ltd, Trevilla Park, 10/10/2012. The valve plate compounds or heavy metals as Camelford, adjusted by the secondary air a result of treatment with woodcontrol must contain six 5mm preservatives or coatings.

manufactured by Hunter Stoves "JINCNC05 Limited, Unit 6, Old Mill 22/09/2011 Industrial Estate, Stoke Canon, "JINCND05&CNC05 Devon, EX5 4RJ.

revC" Stop revA" dated 22/07/11. The appliance must be fitted with a permanent stop that prevents closure of secondary air slider beyond 30% open.

Parkray Consort 5 Compact Instruction manual references Wood logs. The fuel must dated not contain halogenated organic and compounds or heavy metals as Slider a result of treatment with woodpreservatives or coatings.

Parkrav Consort manufactured by Hunter Stoves "JINCND05" revC" Limited, Unit 6, Old Mill 22/09/2011 Industrial Estate, Stoke Canon, "JINCND05&CNC05 Devon, EX5 4RJ.

5 Instruction manual references Wood logs. The fuel must Stop revA" dated 22/07/11. The appliance must be fitted with a permanent stop that prevents closure of the secondary air slider beyond 30% open.

dated not contain halogenated organic and compounds or heavy metals as Slider a result of treatment with woodpreservatives or coatings.

Parkray Consort 5 Slimline Instruction manual reference Wood logs. The fuel must manufactured by Hunter Stoves "JINHHW05 Limited, Unit 6, Old Mill 22/09/11. Industrial Estate, Stoke Canon, Devon, EX5 4RJ.

revC"

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Parkray Consort Limited, Unit 6, Old Mill Industrial Estate, Stoke Canon, Devon, EX5 4RJ.

7 Instruction manual references Wood logs. The fuel must manufactured by Hunter Stoves "JNCS07 revC" dated 22/09/11. not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Parkray Consort Stoves Ltd, Trevilla Park, 14/12/12. Slaughterbridge, Camelford, Cornwall, PL32 9TT.

slimline Instruction manual references Wood logs. The fuel must 9 manufactured by Hunter "JINCSS09 Rev C" dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

PCE 50 500kW wood chip Instruction manual references Wood chips. The fuel must boiler manufactured by Groupe "PCE50 rev00" Compte. R, ZI de Vaureil, F - 29/01/2013. 63220 Arlanc, France.

PCE 70 700kW wood chip Instruction manual references Wood chips. The fuel must boiler manufactured by Groupe "PCE70" rev00" Compte. R, ZI de Vaureil, F - 29/01/2013. 63220 Arlanc, France.

PCE 90 900kW wood chip Instruction manual references Wood chips. The fuel must boiler manufactured by Groupe "PCE90 rev00" Compte. R, ZI de Vaureil, F - 29/01/2013. 63220 Arlanc, France.

PCE 120 1200kW wood chip Instruction manual references Wood chips. The fuel must boiler manufactured by Groupe "PCE120 rev00" Compte. R, ZI de Vaureil, F - 29/01/2013. 63220 Arlanc, France.

150 1500kW boiler Instruction manual references Wood chips. The fuel must manufactured Groupe "PCE150 by rev00" Compte. R, ZI de Vaureil, F - 29/01/2013. 63220 Arlanc, France.

7.6kW stove manufactured by Dik Geurts Haardkachels BV, Industrieweg Oost 11, 6662 NE Elst (Gld), The Netherlands.

Pelletstar 10, 20, 30, 45 Operating instructions dated Wood pellets corresponding to HERZ Armaturen Ges.m.b.H, V2.2. Gesch�ftsbereich HERZ Feuerungstechnik, A-8272 Sebersdorf 138, Austria.

PelletTop 15 and PelletTop Installation instructions version Wood pellets. The fuel must 25 Boiler manufactured by 020905 Solarfocus, Werkstrasse 1, 4451 Operating manual St.Ulrich, Steyr, Austria.

manufactured IP12 4PS.

Pelle 5kW stove, Vidar Small Instruction manual reference Dry wood logs. The fuel must 5kW stove and Vidar Medium "8900009004" dated July 2011. not contain halogenated organic

and 60 manufactured by November 2007, reference "i/2" NORM M7135 of 6 mm

270906 dated 27/09/2006.

supply that does not allow the preservatives or coatings. slider to be shut off completely

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

> compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

> diameter. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

dated 02/09/2005. not contain halogenated organic version compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Pevex 60 convector stove Instruction manual references Wood logs. The fuel must Pevex "Pevex1016/AH/ver1" dated not contain halogenated organic Enterprises Ltd, Unit 16, Seven Jan 2013. A permanent stop compounds or heavy metals as Acres, Waldringfield, Suffolk, fitted to the secondary air a result of treatment with wood-

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

> and remains open by 40% of its full travel whilst the tertiary air remains open by 100% must be implemented.

multi-fuel stoves manufactured 2010. by Pevex Enterprises Limited, Unit 16 Seven Acres Business Park, Newbourne Road. Waldringfield Nr Woodbridge, IP12 4PS.

Pevex Bohemia X 30, X 40, Instruction manual references Dry wood logs. The fuel must X 40 Cube, X 50 and X 60 "AH/Ver3" and dated July not contain halogenated organic

compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Pevex Bohemia Inset multi-fuel manufactured bv Enterprises Limited, Park. Newbourne IP12 4PS.

appliance "Pevex1004/AH/ver2" Pevex dated June 2011. Unit Fitted with permanent stops that a result of treatment with wood-16 Seven Acres Business ensure the primary and tertiary preservatives or coatings. Road, air controls do not close beyond Waldringfield, Nr Woodbridge, 0.5cm open and 2cm open positions respectively.

40 Instruction manual references Dry wood logs. The fuel must and not contain halogenated organic compounds or heavy metals as

Pevex Serenity 40D inset multi- Instruction manual references Dry wood logs. The fuel must fuel appliance manufactured "Pevex1003/AH/ver2" by Pevex Enterprises Limited, dated June 2011. Newbourne Waldringfield Nr Woodbridge, tertiary air controls do not close IP12 4PS.

Unit 16 Seven Acres Business Fitted with permanent stops a result of treatment with wood-Road, that ensure the secondary and preservatives or coatings.

> beyond 1.1cm open and 2cm open positions respectively.

and not contain halogenated organic compounds or heavy metals as

Trent, Staffordshire, ST4 4TJ.

Portway 1 Stove manufactured Instruction manual referenced: Wood logs. The fuel must used with a modification to preservatives or coatings. the secondary air slide which inhibits closure further than the 25mm from the left position.

by BFM Europe Limited, "Solid Fuel Stoves Manual not contain halogenated organic Trentham Lakes, Stoke on issued - 20/08/2009 (291) compounds or heavy metals as 2". The appliance must be a result of treatment with wood

Trentham ST4 4TJ.

used with a modification to preservatives or coatings. the secondary air slide which inhibits closure further than the 20mm from the left position.

Portway 2 and 3 Stoves Instruction manual referenced: Wood logs. The fuel must manufactured by BFM Europe "Solid Fuel Stoves Manual not contain halogenated organic Lakes, issued - 20/08/2009 (291) compounds or heavy metals as Stoke on Trent, Staffordshire, 2". The appliance must be a result of treatment with wood

Portway Inset Trentham Limited, ST4 4TJ.

secondary air control must preservatives or coatings. be implemented such that

Stove Instruction manual referenced: Wood logs. The fuel must manufactured by BFM Europe "Solid Fuel Stoves Manual not contain halogenated organic Lakes, issued - 20/08/2009 (291) compounds or heavy metals as Stoke on Trent, Staffordshire, 2". A modification of the a result of treatment with wood

> the 20mm from left position is maintained during use. In addition the primary air control must be modified such that the minimum setting allows a bleed of air to pass through.

PO Box 28150, Havelock 2011. North 4157, Hawke Bay, New Zealand.

Pyroclassic IV manufactured Instruction manual reference Wood logs. The fuel must by Pyroclassic Fires Limited, "PYROS 04" dated August not contain halogenated organic

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Furtmï; ½hlstrasse 32,

A-5101 Bergheim bei Salzburg. PZ101RL" dated July 2012. preservatives or coatings. Reference BTMoBeWe ENG.

PZ 65 RL and PZ 100 RL Instruction manual references Wood pellets. The fuel must pellet boilers. Manufactured by "Assembly instruction - not contain halogenated organic Biotech Energietechnik GmbH, Instruction manual – servicing compounds or heavy metals as & cleaning PZ65RL/PZ100RL/ a result of treatment with wood-

Freestanding Wood Burning dated 9th October Stove, manufactured by Hearth reference 250-6931B. & Home Technologies 1445 North Highway, Colville, WA 99114, USA.

Quadra-Fire 2100 Millennium The manufacturer's instructions Dry cured untreated wood 2003, of maximum size 38.1cm x 10.16cm x 5.08cm. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

Stove, manufactured by Hearth 7006-186. & Home Technologies 1445 North Highway, Colville, WA 99114, USA.

Quadra-Fire Cumberland Gap The manufacturer's instructions Dry cured untreated wood Freestanding Wood Burning dated 8th July 2003, reference of maximum size 43.18cm x 10.16cm x 10.16cm. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

Quadra-Fire Stove, manufactured by Hearth 7004-187. & Home Technologies 1445 North Highway, Colville, WA 99114, USA.

Yosemite The manufacturer's instructions Dry cured untreated wood Freestanding Wood Burning dated 4th June 2003, reference of maximum size 38.1cm x 10.16cm x 5.08cm. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

Rais 2:1 inset manufactured Industrivei 20, Frederikshavn, Denmark. 2009. Part number 9106510.

stove Instruction manual reference Wood logs. The fuel must by Rais A/ "USER MANUAL Rais 2:1 not contain halogenated organic 9900, Revision 2". Dated December compounds or heavy metals as a result of treatment with wood preservatives or coatings.

700 Rais inset

stove Instruction manual reference Wood logs. The fuel must manufactured by Rais A/ "USER MANUAL Rais 700 not contain halogenated organic Revision 0". Dated 2010.

compounds or heavy metals as

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Industrivei 20, 9900. Frederikshavn, Denmark.

Epoca, Rais Frederikshavn, Denmark.

RAIS Q-Tee 57 Industrivei 20, Frederikshavn, Denmark.

RAIS Q-Tee 65 manufactured by Rais A/ Industrivei 20, Frederikshavn, Denmark.

RAIS Q-Tee 85 manufactured by Rais A/ Industrivei 20, Frederikshavn, Denmark.

Rais A/S Industrivej 20, 9900, and Frederikshavn, Denmark.

December 2009. Part number preservatives or coatings. 2106510.

manufactured by Rais A/ "Manual for RAIS Q-Tee not contain halogenated organic 9900, Revision 1" June 2011 and Supplementary a result of treatment with woodinstructions Rais Q-Tee dated preservatives or coatings. 7th July 2011.

Fitted with a mechanical stop to prevent air control closure beyond the 11.7mm open position.

Instruction manual references Dry wood logs. The fuel must 9900. Revision 1" instructions Rais Q-Tee dated preservatives or coatings. 7th July 2011.

Fitted with a mechanical stop to prevent air control closure beyond the 11.7mm open position.

9900, Revision dated instructions Rais Q-Tee dated preservatives or coatings. 7th July 2011.

Fitted with a mechanical stop to prevent air control closure beyond the 11.7mm open position.

RAIS Q-Tee Wall 57, Rais Instruction manual references Dry wood logs. The fuel must Q-Tee Wall 65 and Rais Q- "Manual for RAIS Q-Tee not contain halogenated organic Tee Inset manufactured by Revision 2" dated 07/12/2012 compounds or heavy metals as Instructions Rais Rev.3" dated preservatives or coatings. 31/01/2013. Fitted with a mechanical stop to prevent air control closure beyond the 11.7mm open position.

Mino II stoves manufactured by "USER MANUAL Rais Rondo not contain halogenated organic

a result of treatment with wood preservatives or coatings.

Poleo Instruction manual reference Wood logs. The fuel must 95 and Rais Poleo 106 "USER MANUAL Rais Poleo not contain halogenated organic stoves manufactured by Rais 95 & Rais Poleo 106 & compounds or heavy metals as A/S Industrivej 20, 9900, Rais Epoca Revision 1". Dated a result of treatment with wood

> Instruction manual references Dry wood logs. The fuel must dated 28th compounds or heavy metals as

> "Manual for RAIS Q-Tee not contain halogenated organic dated 28th compounds or heavy metals as June 2011, and Supplementary a result of treatment with wood-

> Instruction manual references Dry wood logs. The fuel must "Manual for RAIS Q-Tee not contain halogenated organic 28th compounds or heavy metals as June 2011, and Supplementary a result of treatment with wood-

> > "Supplementary a result of treatment with wood-

Rais Rondo Classic and Rais Instruction manual reference Wood logs. The fuel must & Rais Mino II revision 2". compounds or heavy metals as

Frederikshavn, Denmark.

Rais Rondo 92 and Rais Rondo Instruction manual reference Wood logs. The fuel must Frederikshavn, Denmark.

RAIS VIVA 98. VIVA 98G, RAIS 120. RAIS **VIVA** RINA Rais A/S. Industrivei 20. Vangen. DK-9900. Frederikshavn, Denmark.

RanHeat appliances models The manufacturer's instructions No fuel shall be used other than WA150, WA300 and WA500, following reference— RanHeat (i) manufactured bv Energy Limited.

RanHeat Boiler Type RHA The manufacturer's instructions No fuel shall be used other 20, manufactured by RanHeat dated Energy A/S.

RanHeat Boiler Types RHA The manufacturer's instructions No fuel shall be used other 160, 200 and 250, manufactured dated by RanHeat Energy Limited.

Redfyre Kensal 20 code top (product manufactured by Cookers, Osprey Road, Sowton A permanent stop must be in Industrial Estate, Devon, EX2 7JG.

Rais A/S Industrive 20, 9900, Dated March 2008. Part number a result of treatment with wood 5056510.

120 stoves manufactured by "USER MANUAL Rais Rondo not contain halogenated organic Rais A/S Industrivej 20, 9900, 92 & Rais Rondo 120 revision compounds or heavy metals as 2". Dated December 2009. Part a result of treatment with wood number 4076510.

Burning Stoves, manufactured "Supplementary Instructions preservatives or coatings. Rais" dated 27th September 2011.

> Fitted with a mechanical stop to prevent closure of the air damper beyond the 8.5mm open position when sold into smoke control areas.

MSU150, MSU300, MSU500, dated July 1994 bearing the chipboard, fibreboard, wood

models MSU150, MSU300 dust. 1994":

(ii) models WA150, WA300 and preservatives or coatings. WA500: "WA150/500 1994".

 30^{th} and bearing the reference shavings. "RHGBEA 30388".

 30^{th} March GB and bearing the reference shavings. "RHGBEA 30388".

Redfyre Issue 1.

Exeter, place on the secondary air inlet to prevent closure beyond the 50% open position.

preservatives or coatings.

preservatives or coatings.

RAIS Instruction manual references Wood logs. The fuel must VIVA "Manual for RAIS Rina, not contain halogenated organic 120G, RAIS Viva" dated 29th August compounds or heavy metals as Wood 2011, and instruction manual a result of treatment with wood-

> offcuts, softwood shavings or dust, hardwood shavings or The fuel must not and MSU500: "MSU150/500 contain halogenated organic compounds or heavy metals as a result of treatment with wood-

> > March 1988 than hardwood and softwood

1988 than hardwood and softwood

Flat The manufacturer's instruction Untreated dry wood. The fuel RF- manual dated July 2008, must not contain halogenated EN20M), Redfyre Kensel 33 reference PM247 Issue 1, organic compounds or heavy Flat top (product code RF- and instruction manual dated metals as a result of treatment KEN33M and RF-KEN33W), January 2009, reference PM280 with wood preservatives or coatings.

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Resolute Acclaim woodstove The manufactured by Castings Inc.

fireplaces shall Vermont installed, maintained operated in manufacturer's dried. with the bearing instructions the reference "AMENDED NO. 200 - 0908 UK OCTOBER 1991".

be No fuel shall be used other than and 400 millimetre firewood that accordance has been split, stacked and air-

Rika Como manufactured bv Innovative Ofentechnik GmbH 2011. M�llerviertel 20 AT - 4563 Micheldorf. Austria.

pellet stove Instruction manual references 6 mm wood pellets. The fuel RIKA "IN1226 Edition 1" dated June must not contain halogenated

organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

Rika Evo 15 manufactured by SHT "J18/HB" dated 27/02/2009. Heiztechnik aus Salzburg GmbH, Rechtes Salzachufer 40 A-5101, Salzburg-Bergheim, Austria.

Aqua 9 and Instruction manual references 6mm wood pellets. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

Rika Memo manufactured by Innovative Ofentechnik GmbH 2011. M�llerviertel 20 AT - 4563 Micheldorf, Austria.

RIKA "IN1228 Edition 1" dated June must not contain halogenated

pellet stove Instruction manual references 6 mm wood pellets. The fuel organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

pellet Rika Pico manufactured bv Innovative Ofentechnik GmbH 2011. Mïi.1/2llerviertel 20 AT - 4563 Micheldorf, Austria.

RIKA "IN1230 Edition 1" dated June must not contain halogenated

stove Instruction manual references 6 mm wood pellets. The fuel organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

Rika Revo pellet manufactured by Innovative Ofentechnik GmbH 2011. M�llerviertel 20 AT - 4563 Micheldorf, Austria.

RIKA "IN1229 Edition 1" dated June must not contain halogenated

stove Instruction manual references 6 mm wood pellets. The fuel organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

Rika Tema 6kW manufactured by Innovative Ofentechnik GmbH, January 2012. M�llerviertel 20, AT- 4563 Micheldorf, Austria.

Rika "IN1218 Edition 2" dated not contain halogenated organic

stove Instruction manual references Wood logs. The fuel must compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Rika Topo pellet manufactured bv Innovative Ofentechnik GmbH 2011. M�llerviertel 20 AT – 4563 Micheldorf, Austria.

RIKA "IN1227 Edition 1" dated June must not contain halogenated

stove Instruction manual references 6 mm wood pellets. The fuel organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

Cassette Industrial Estate. Devon, EX2 7LF.

Issue 2 dated January 2010.

A permanent stop must be positioned to prevent closure of the secondary air control below the 50% open position.

4.9kW Instruction manual references Wood logs. The fuel must stoves manufactured by Stovax PM235 Issue 2 dated August not contain halogenated organic Limited, Falcon Road, Sowton 2009 and smoke control kit compounds or heavy metals as Exeter, instruction manual PM375 a result of treatment with wood preservatives or coatings.

by Stovax Limited, Falcon Issue 2 dated January 2010. Exeter, Devon, EX2 7LF.

Avanti, Riva 40 Avanti Midi PM226 Issue 2 dated August not contain halogenated organic and Riva 40 Avanti Highline 2009, and smoke control kit compounds or heavy metals as 4.9kW stoves manufactured instruction manual PM375. a result of treatment with wood Road, Sowton Industrial Estate, A permanent stop must be positioned to prevent closure of the secondary air control below the 50% open position.

Riva 40 Freestanding, Riva 40 Instruction manual references Wood logs. The fuel must preservatives or coatings.

Riva Cassette Wood Burning Stoves.

Manufactured by Limited.

Falcon Road Sowton Industrial Estate

Exeter

Devon EX2 7LF.

numbers RV45 & RV45B) "PM375 Issue 5" dated June not contain halogenated organic Stovax references "PM235 Issue 5" a result of treatment with wooddated June 2012.

A permanent stop must be positioned to prevent closure of the secondary air control below the 50% open position.

(model Instruction manual references Wood logs. The fuel must 2012 and Instruction manual compounds or heavy metals as preservatives or coatings.

Cassette Manufactured by Limited.

Falcon Road Sowton Industrial Estate

Exeter Devon EX2 7LF.

numbers RV50 & RV50B) "PM375 Issue 5" dated June not contain halogenated organic inset Wood Burning Stoves. 2012 and Instruction manual compounds or heavy metals as Stovax references "PM235 Issue 5" a result of treatment with wooddated June 2012.

A permanent stop must be positioned to prevent closure of the secondary air control below the 50% open position and the primary air control fixed to allow a bleed of air to enter the firebox from underneath the grate.

(model Instruction manual references Wood logs. The fuel must preservatives or coatings.

Industrial Estate, Devon, EX2 7LF.

Riva 66 Freestanding 8kW PM226 Issue 2 dated August not contain halogenated organic stoves manufactured by Stovax 2009 and smoke control kit compounds or heavy metals as Limited, Falcon Road, Sowton instruction manual PM375. a result of treatment with wood Exeter, Issue 2 dated January 2010.

A permanent stop must be positioned to prevent closure of the secondary air control below the 50% open position and the primary air control fixed

Riva 55 Avanti Midi and Instruction manual references Wood logs. The fuel must preservatives or coatings.

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

> to allow a bleed of air to enter the firebox from underneath the grate.

Road, Sowton Industrial Estate, Issue 2 dated January 2010. Exeter, Devon, EX2 7LF.

Cassette, Riva 66 Avanti PM235 Issue 2 dated August not contain halogenated organic Cassette stoves manufactured 2009 and smoke control kit compounds or heavy metals as by Stovax Limited, Falcon instruction manual PM375. a result of treatment with wood

A permanent stop must be positioned to prevent closure of the secondary air control below the 50% open position and the primary air control fixed to allow a bleed of air to enter the firebox from underneath the grate.

Riva 55 Cassette, Riva 66 Instruction manual references Wood logs. The fuel must preservatives or coatings.

Small Exeter, Devon, EX2 7LF.

(5kW), Instruction manual references Wood logs. The fuel must Midi (6.5kW) and Medium PM231 Issue 3 dated June not contain halogenated organic (8kW) Stoves manufactured 2009 and smoke control kit compounds or heavy metals as by Stovax Limited, Falcon instruction manual PM402 a result of treatment with wood Road, Sowton Industrial Estate, Issue 1 dated November 2009. preservatives or coatings. A permanent stop must be positioned to prevent closure of the secondary air control below the 25% open position.

Riva Studio 1 wood freestanding manufactured bv Industrial Estate, Devon, EX2 7LF.

stove PM452 Issue 1 dated June not contain halogenated organic Limited, Falcon Road, Sowton instruction manual PM400 a result of treatment with wood Exeter, Issue 3 dated June 2010.

A permanent stop must be positioned to prevent closure of the secondary air control below the 45% open position and the primary air control fixed to prevent full closure to allow a bleed of air to enter the firebox at the base of the fuel bed.

(5kW) Instruction manual references Wood logs. The fuel must Stovax 2010 and smoke control kit compounds or heavy metals as preservatives or coatings.

Riva Studio 2 freestanding wood manufactured by Industrial Estate. Devon, EX2 7LF.

(8kW) Instruction manual references Wood logs. The fuel must Exeter, Issue 3 dated June 2010.

A permanent stop must be positioned to prevent closure of the secondary air control below the 25% open position and the primary air control fixed to prevent full closure to allow a bleed of air to enter the firebox at the base of the fuel bed.

stove PM452 Issue 1 dated June not contain halogenated organic Stovax 2010 and smoke control kit compounds or heavy metals as Limited, Falcon Road, Sowton instruction manual PM400 a result of treatment with wood preservatives or coatings.

Riva Exeter, Devon, EX2 7LF.

(5kW) Stove manufactured PM274 Issue 2 dated October not contain halogenated organic by Stovax Limited, Falcon 2009 and smoke control kit compounds or heavy metals as Road, Sowton Industrial Estate, instruction manual PM400 a result of treatment with wood Issue 1 dated November 2009. preservatives or coatings.

A permanent stop must be positioned to prevent closure of the secondary air control below the 45% open position and the primary air control fixed to prevent full closure to allow a bleed of air to enter the firebox at the base of the fuel bed.

Cassette Instruction manual references Wood logs. The fuel must

Riva Studio Exeter, Devon, EX2 7LF. Issue 1 dated November 2009. preservatives or coatings. A permanent stop must be

positioned to prevent closure of the secondary air control below the 25% open position and the primary air control fixed to prevent full closure to allow a bleed of air to enter the firebox at the base of the fuel bed.

Cassette Instruction manual references Wood logs. The fuel must (8kW) Stove manufactured PM274 Issue 2 dated October not contain halogenated organic by Stovax Limited, Falcon 2009 and smoke control kit compounds or heavy metals as Road, Sowton Industrial Estate, instruction manual PM400 a result of treatment with wood

RVS-500 Wood 7LF.

Industrial Estate, Exeter, EX2 2012. Fitted with Smoke preservatives or coatings. Control Kit RVS500SCKIT to prevent secondary air closure beyond the 50% open position when sold into smoke control

Riva Studio Cassette 500 Instruction manual references Wood logs. The fuel must Burning "PM400 Issue 4" dated October not contain halogenated organic Stove manufactured by Stovax 2012 and instruction manual compounds or heavy metals as Limited, Falcon Rd, Sowton "PM274 Issue 9" dated August a result of treatment with wood-

Wood Burning manufactured bv 7LF.

Riva Studio Duplex RVS-2DS Instruction manual references Wood logs. The fuel must Stove "PM935 Issue 1" dated not contain halogenated organic Stovax October 2012 and instruction compounds or heavy metals as Limited, Falcon Rd, Sowton manual "PM904 - Issue 1" a result of treatment with wood-Industrial Estate, Exeter, EX2 dated August 2012. Fitted preservatives or coatings. with Smoke Control Kit RVS-2DSSCKIT to prevent secondary air closure beyond the 91mm open position when sold into smoke control areas.

2012. Fitted with Smoke preservatives or coatings.

Riva Studio Freestanding 500 Instruction manual references Wood logs. The fuel must Wood Burning "PM400 Issue 4" dated October not contain halogenated organic Stove manufactured by Stovax 2012 and instruction manual compounds or heavy metals as Limited, Falcon Rd, Sowton "PM452 Issue 3" dated August a result of treatment with wood-

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Industrial Estate, Exeter, EX2 Control Kit RVS500SCKIT to 7LF.

prevent secondary air closure beyond the 50% open position when sold into smoke control areas

Riva Vision Medium (8kW) Instruction manual references Wood logs. The fuel must Exeter, Devon, EX2 7LF.

Multifuel Stove manufactured PM278 Issue 2a dated October not contain halogenated organic by Stovax Limited, Falcon 2009 and smoke control kit compounds or heavy metals as Road, Sowton Industrial Estate, instruction manual PM401 a result of treatment with wood Issue 1 dated January 2010.

A permanent stop must be positioned to prevent closure of the secondary air control below the 25% open position.

Road, Sowton Industrial Estate, Issue 1 dated January 2010. Exeter, Devon, EX2 7LF.

Riva Vision Small (5kW) and Instruction manual references Wood logs. The fuel must Riva Vision Midi (6.5kW) PM278 Issue 2a dated October not contain halogenated organic Multifuel Stoves manufactured 2009 and smoke control kit compounds or heavy metals as by Stovax Limited, Falcon instruction manual PM401 a result of treatment with wood A permanent stop must be

positioned to prevent closure of the secondary air control below the 50% open position.

No.

04"

Rosedale Inset Smoke Control Instruction manual reference Wood logs. The fuel must inset roomheater manufactured "Issue by Town and Country Fires 11.01.2012. Limited,

Unit 1 Enterprise Way

Thornton Road Industrial Estate closure beyond the 30% open Pickering

North Yorkshire YO18 7NA

Royal

wood

Rosedale SC Multifuel Stove Rosedale manufactured by Town & Stove Installation and User 20% moisture. Country Fires Limited, Enterprise Way, Thornton Road May 2010. North Yorkshire, YO18 7NA.

Klima

Porcia (PN), 33080, Italy.

pellet stove

position when sold into smoke control areas. Smoke

Instructions "Issue 1" dated 1st The Industrial Estate, Pickering, The appliance must be fitted compounds or heavy metals as to prevent closure of the preservatives or coatings. secondary air control beyond the 50% open position when

> Idro Instruction manual references Wood pellets. The fuel must 0047700880" boiler "cod. 1993 and Smoke Control preservatives or coatings. Areas" reference 004723000 dated 01/2012.

sold into smoke control areas.

preservatives or coatings.

preservatives or coatings.

dated not contain halogenated organic compounds or heavy metals as Fitted with a mechanical stop a result of treatment with woodto prevent secondary air control preservatives or coatings.

Control Wood logs with a maximum of

fuel must not contain halogenated organic a mechanical stop a result of treatment with wood

dated not contain halogenated organic manufactured by Palazzetti 09/2011 and supplementary compounds or heavy metals as Lelio S.p.A, Via Roveredo 103, information "Clean Air Act a result of treatment with wood-

18

5 stoves (also known as Ekol 15/12/2011. Crystal 5).

Manufactured by 4BG.

Saltfire Ecoview 12, Fireglow Instruction manual references Wood logs. The fuel must 12 stoves (also known as Ekol 15/12/2011. Crystal 12).

Manufactured by 4BG.

Saltfire Manufactured by Stoves Limited, Units 1 and 2, dated 24.01.2011. The Omega Centre, Sandford Lane, Wareham, BH20 4DY.

San Remo 4SE manufactured Instruction manual references Wood logs. The fuel must by Heat Design, 30 Hawthorn "SR468SE" dated 25/07/12. Road, Western Estate, Naas Road, Dublin 12, to Ireland.

San Remo manufactured by Heat Design, "SR468SE" dated 25/07/12. Dublin 12, Ireland.

San Remo 8SE manufactured by Heat Design, "SR468SE" dated 25/07/12. Dublin 12, Ireland.

Scan 58-1, Scan 58-1 Wall, Scan Scan 58-3, Scan 58-3 Wall, "GB Scan 58-7, Scan 58-7 High reference Top, Scan 58-8, Scan 58-8 dated

Saltfire Ecoview 5, Fireglow Instruction manual references Wood logs. The fuel must Eco 5, and Ecowarm Crystal "Evoview5 Manual 1.0" dated not contain halogenated organic

Saltfire prevent closure of the tertiary preservatives or coatings. Stoves Limited, Station Works, air beyond the 4mm open John's Road, Wareham, BH20 position when sold into smoke control areas.

Eco 12, and Ecowarm Crystal "Evoview12 Manual 1.0" dated not contain halogenated organic

Fitted with a mechanical stop to a result of treatment with wood-Saltfire prevent closure of the tertiary preservatives or coatings. Stoves Limited, Station Works, air beyond the 4mm open John's Road, Wareham, BH20 position when sold into smoke control areas.

> Oslo-Eco Instruction manual references Wood logs. The fuel must Saltfire "ECO7operation-Revision 2A" not contain halogenated organic

> Industrial The fitting of a system compounds or heavy metals as prevent closure secondary air control preservatives or coatings. the beyond 5mm open must be implemented.

stove Instruction manual references Wood logs. The fuel must 30 Hawthorn Road, Western The fitting of a system compounds or heavy metals as Industrial Estate, Naas Road, to prevent closure of the a result of treatment with woodsecondary air control beyond preservatives or coatings. 75% from closed must be implemented.

stove Instruction manual references Wood logs. The fuel must 30 Hawthorn Road, Western The fitting of a system compounds or heavy metals as Industrial Estate, Naas Road, to prevent closure of the a result of treatment with woodsecondary air control beyond preservatives or coatings. 25% from closed must be implemented.

58 Assembly Scan 58-2, Scan 58-2 Wall, Instruction manual reference not contain halogenated organic 90358500-5" Scan 58-4, Scan 58-4 Wall, 24/03/2011 and Scan 58 Series a result of treatment with wood-Scan 58-5, Scan 58-5 Wall, supplementary instructions for preservatives or coatings. Scan 58-6, Scan 58-6 Wall, UK Smoke Control Areas "SCAN58SCA" 01/03/2013.

compounds or heavy metals as Fitted with a mechanical stop to a result of treatment with wood-

compounds or heavy metals as

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

not contain halogenated organic of a result of treatment with wood-

not contain halogenated organic

not contain halogenated organic

and Wood logs. The fuel must dated compounds or heavy metals as

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

5492 Vissenbjerg, Denmark.

High Top, Scan 58-9, Scan 58-9 mechanical stop to prevent High Top, Scan 58-10, Scan closure of the secondary 58-10 High Top, manufactured air control beyond the 1/3rd by Scan A/S, Glasv�nget 3-9, open position when sold into smoke control areas must be implemented.

Scan Andersen A/S Vissenbjerg, Denmark.

4-5 The manufacturer's instruction Untreated dry wood. The fuel

A permanent stop must be coatings. in place on the secondary air inlet to prevent closure beyond 20mm.

manufactured by Krog Iversen manual dated 15 November must not contain halogenated DK-5492 2007 entitled "Scan Andersen organic compounds or heavy 4-5", reference Edition 09/05- metals as a result of treatment with wood preservatives or

Scan DSA 7-5 wood-burning Instruction Inset roomheater. Box 20, 5492 Vissenbjerg, Denmark.

- GB, supplement "DSA preservatives or coatings. 7-5 - UK smoke control areas" reference "DSA 7-5 SMOKE" dated 01/01/2012, and instructions for installation (including directions for use and stoking) reference "Edition 05.10.2010 - GB". Fitted with a mechanical stop to prevent closure of the air wash control lever beyond the 50% open position.

manual Wood logs. The fuel must "Instructions for installation not contain halogenated organic Manufactured by Scan A/S, PO and use: SCAN DSA 6 & compounds or heavy metals as DSA 7-5" Edition 17.09.2010 a result of treatment with wood-

Scan Ild 1 and 4 stoves Instruction manual references Wood logs. The fuel must Vissenbjerg, Denmark.

secondary air control beyond preservatives or coatings. the 83mm open position.

manufactured by Scan A/ "11.1c" dated 02/2012. Fitted not contain halogenated organic S, Glasvaenget 3-9, 5492 with a mechanical stop compounds or heavy metals as to prevent closure of the a result of treatment with wood-

S, Glasvaenget 3-9, 5492 with Vissenbjerg, Denmark.

a secondary air control beyond preservatives or coatings. the 83mm open position.

Scan Ild 2 and 5 stoves Instruction manual references Wood logs. The fuel must manufactured by Scan A/ "11-1d" dated 02/2012. Fitted not contain halogenated organic mechanical stop compounds or heavy metals as to prevent closure of the a result of treatment with wood-

Scanline 80, B, Scanline Denmark.

open when fully closed must be preservatives or coatings. implemented.

Scanline 80 Instruction manual references Wood logs. The fuel must 80BF stoves "Pevex1019/AH/ver1" dated not contain halogenated organic manufactured by Heta A/S, Jan 2013. A permanent stop compounds or heavy metals as Jupitervej 22, 7620 Lemvig, fixing the air control to 31% a result of treatment with wood-

Lemvig, Denmark.

Scanline Aqua Denmark.

soapstone and accumulation, open when fully closed must be preservatives or coatings. Scanline 820 with shelf, implemented. Scanline 820 soapstone and shelf stoves, manufactured by Heta A/S, Jupitervej 22, 7620 Lemvig, Denmark.

Scanline accumulation, Scanline 830 "Pevex1019/AH/ver1" accumulation 7620 Lemvig, Denmark.

and accumulation, Scanline 840 open when fully closed must be preservatives or coatings. high ash door, accumulation implemented. and soapstone, Scanline 840 baking oven with high ash door, Scanline 840 baking oven with high ash door and soapstone stoves manufactured by Heta A/ S, Jupitervej 22, 7620 Lemvig, Denmark.

7620 Lemvig, Denmark.

A/S, Jupitervej 22, 7620 open when fully closed must be preservatives or coatings. implemented.

> and Instruction manual references Wood logs. The fuel must open when fully closed must be preservatives or coatings. implemented.

Scanline 800, Scanline 810 Instruction manual references Wood logs. The fuel must standard, Scanline 810 with "Pevex1019/AH/ver1" dated not contain halogenated organic high ash door and soapstone Jan 2013. A permanent stop compounds or heavy metals as stoves, manufactured by Heta fixing the air control to 31% a result of treatment with wood-

Scanline 800 Aqua low boiler "Pevex1018/AH/ver1" dated not contain halogenated organic stoves manufactured by Heta A/ Jan 2013. A permanent stop compounds or heavy metals as S, Jupitervej 22, 7620 Lemvig, fixing the air control to 52% a result of treatment with wood-

Scanline 820 baking oven, Instruction manual references Wood logs. The fuel must Scanline 820 with soapstone "Pevex1019/AH/ver1" dated not contain halogenated organic and baking oven, Scanline Jan 2013. A permanent stop compounds or heavy metals as 820 accumulation, Scanline 820 fixing the air control to 31% a result of treatment with wood-

extra Instruction manual references Wood logs. The fuel must dated not contain halogenated organic and Jan 2013. A permanent stop compounds or heavy metals as soapstone stoves, manufactured fixing the air control to 31% a result of treatment with woodby Heta A/S, Jupitervej 22, open when fully closed must be preservatives or coatings. implemented.

Scanline 840 high ash door Instruction manual references Wood logs. The fuel must and shelf, Scanline 840 high "Pevex1019/AH/ver1" dated not contain halogenated organic ash door, shelf and soapstone, Jan 2013. A permanent stop compounds or heavy metals as Scanline 840 high ash door fixing the air control to 31% a result of treatment with wood-

Scanline 850 on pedestal, Instruction manual references Wood logs. The fuel must open when fully closed must be preservatives or coatings. implemented.

with a

Scanline 850 soapstone on "Pevex1019/AH/ver1" dated not contain halogenated organic pedestal stoves manufactured Jan 2013. A permanent stop compounds or heavy metals as by Heta A/S, Jupitervej 22, fixing the air control to 31% a result of treatment with wood-

Scan Warm 1 and 4 stoves Instruction manual references Wood logs. The fuel must manufactured by Scan A/ "11-1a" dated 02/2012. Fitted not contain halogenated organic mechanical stop compounds or heavy metals as

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Vissenbjerg, Denmark.

secondary air control beyond preservatives or coatings. the 83mm open position.

S, Glasvaenget 3-9, 5492 to prevent closure of the a result of treatment with wood-

Scan Warm 2 and 5 stoves Instruction manual references Wood logs. The fuel must Vissenbjerg, Denmark.

manufactured by Scan A/ "11-1b" dated 02/2012. Fitted not contain halogenated organic S, Glasvaenget 3-9, 5492 with a mechanical stop compounds or heavy metals as secondary air control beyond preservatives or coatings. the 83mm open position.

to prevent closure of the a result of treatment with wood-

Schmid UTSK 180, 240, 300, "Instruction manual UTSK - Wood Pellets or Wood Chips 360, 450, 550, 700, 900, 1200, ABC.22 – AME – S – PPU" 1600kW. Wood Firing Systems PO Box 42 CH-8380 Eschlikon, Switzerland.

Dated 25.09.2008. Manufactured by Schmid AG Where ABC is Model Number The

following CEN/TS 2005.

700, 900, 1200, 1600.

fuel must ie. 180, 240, 300, 360, 450, 550, contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

80, 110, 150kW. Manufactured by Schmid AG Chips and Pellets Wood Firing Systems PO Box 42

"Operating Manual Wooden following CEN/TS Lignumat UTSL" dated The 23.12.2004.

Schmid UTSL 30, 40, 50, 65, Instruction manual references Wood Pellets or Wood Chips 14961: Plant. 2005.

CH-8380 Eschlikon, Switzerland.

fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Schmid UTSP 180, 300kW. Manufactured by Schmid AG Dated 25.09.2008. Wood Firing Systems PO Box 42 CH-8380 Eschlikon, Switzerland.

240, Instruction manual "UTSK - Wood Pellets following CEN/ ABC.22 - AME - S - PPU". TS 14961: 2005. ie. 180, 240, 300.

The fuel must Where ABC is Model Number contain halogenated organic compounds or heavy metals as

a result of treatment with wood

preservatives or coatings.

900kW.

Dated 25.09.2008.

550, 700, 900.

Schmid UTSR 150, 180, 240, Instruction manual "UTSR - Wood Pellets or Wood Chips 300, 360, 450, 550, 700, ABC.22 – AME – S – PPV". following CEN/TS 14961: 2005.

Manufactured by Schmid AG Where ABC is Model Number The Wood Firing Systems PO Box 42 CH-8380 Eschlikon, Switzerland.

fuel must not ie. 150, 180, 240, 300, 360, 450, contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Switzerland.

Schmid UTSW 900.32 boiler Instruction manual references Wood instruction and "PersonalTouch". Version 2010 dated 2010. EVO10

chips manufactured by Schmid AG "Instruction manual. Wood pellets. The fuel must not - woodfiring systems, PO chip furnace with boiler type contain halogenated organic Box 42, CH-8360 Eschlikon, Schmid Pyrotronic Modular" compounds or heavy metals as issue 1, dated 07.01.2013 a result of treatment with woodmanual preservatives or coatings.

V531\PT 2010 C3.

Serenity 40 FS. 40 LS. IP12 4PS.

Serenity 50FS, Serenity 50LS, Instruction manual references Wood logs. The fuel must Serenity 50FW and Serenity "Pevex1014/AH/ver1" dated not contain halogenated organic 50 Ped stoves manufactured Jan 2013. The secondary air compounds or heavy metals as by Pevex Enterprises Ltd, Unit slider has a built in stop that a result of treatment with wood-16, Seven Acres, Waldringfield, does not allow the slider to be preservatives or coatings. Suffolk, IP12 4PS.

Serenity 50 Inset manufactured bv IP12 4PS.

Serrano 5 Multi Fuel Shropshire, SY1 3AB.

Shropshire, SY1 3AB.

Sirius Traditional Area Gao Zhuangzi Village, 09/11/2010. Xin Zhuang Town, Jin Nan

Serenity Instruction manual references Wood logs. The fuel must Serenity 40 FW "Pevex1014/AH/ver1" dated not contain halogenated organic stoves manufactured by Pevex Jan 2013. The appliance must compounds or heavy metals as Enterprises Ltd, Unit 16, Seven be fitted with permanent stops a result of treatment with wood-Acres, Waldringfield, Suffolk, that ensure the secondary and preservatives or coatings. tertiary air controls do not close beyond 1.1cm open and 2cm open positions respectively.

> shut off completely and remains open by 40% of its full travel. The tertiary air has no slider and is factory designed with a 2cm open slot and remains 100% open.

stove Instruction manual references Wood logs. The fuel must Pevex "Pevex1014/AH/ver1", dated not contain halogenated organic Enterprises Ltd, Unit 16, Seven Jan 2013. The secondary air compounds or heavy metals as Acres, Waldringfield, Suffolk, slider has a built in stop that a result of treatment with wooddoes not allow the slider to be preservatives or coatings. shut off completely and remains open by 40% of its full travel. The tertiary air has no slider and is factory designed with a 2cm open slot and remains 100% open.

and Monterrey Instruction manual references Wood logs. The fuel must Stoves "TJ09C" dated 21st December not contain halogenated organic manufactured by Broseley Fires 2009. The fitting of a system compounds or heavy metals as Ltd, Knights Way, Battlefield that prevents the closure of the a result of treatment with wood-Enterprise Park, Shrewsbury, secondary air flaps to be less preservatives or coatings. than 8mm open position should be implemented.

> the secondary air flaps to be preservatives or coatings. less than 10mm open position should be implemented.

Stove Instruction and

Serrano 7 Multi Fuel stove Instruction manual references Wood logs. The fuel must manufactured by Broseley Fires "TJ09C" dated 21st December not contain halogenated organic Ltd, Knights Way, Battlefield 2009. The fitting of a system compounds or heavy metals as Enterprise Park, Shrewsbury, that prevents the closure of a result of treatment with wood-

Operating Wood logs. The fuel must manufactured by Tianjin Focus Instruction manual reference not contain halogenated organic Arts & Crafts Co, Industrial "v173 of 09/11/2010" dated compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

District, Tianjin, P.R. China 300350.

SP Dual 15kW boiler, SP Dual 28kW boiler, SP Dual 34kW reference boiler, SP dual 40kW boiler, Edition 09/10/2012". manufactured by Fr�ling Heizkessel- und Behï, ½lterbau Ges.m.b.H., Industriestraï, ½e A-4710 12. Grieskirchen, Austria.

fuel Boiler Dual 22kW boiler, SP Dual Dual Operating instructions pellets. The fuel must not

SP Wood logs wood "B0760212 en contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Spacewarmer manufactured bv Limited

B200, The manufacturer's instructions a) Clearair published December 1983 and No fuel shall be used other bearing the reference "B200/ than hardwood or softwood DEC 83".

offcuts, a mixture of offcuts (hardwood or softwood) and sandwich with no more than 50 per cent of the mixture being sawdust, or chipboard offcuts. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings;

(b)

The fireplace shall not be used to burn chipboard unless an afterburner supplied by the manufacturer of the fireplace and capable of producing 50 megajoules of heat per hour has been fitted to the fireplace.

Spacewarmer manufactured by Limited.

B500, The manufacturer's instructions No fuel shall be used other than Clearair published in December 1983 hardwood or softwood offcuts. and bearing the reference "B500/DEC 83".

code 7118), Stockton 4 Flat manual dated July 2008, must not contain halogenated top (product codes 7101 and reference PM227 ENG Issue 2, organic compounds or heavy 7102), Stockton 5 Flat top and instruction manual dated metals as a result of treatment (product code 7127), Stockton January 2009, reference PM271 with wood preservatives or 5 midline (product code Issue 2. 7130), Stockton 6 Flat top A permanent stop must be in (product codes 7100 and 7162), place on the secondary air inlet Stockton 6 Highline (product to prevent closure beyond the code 7117) and Stockton 50% open position. 7 Flat top (product codes 7120 and 7163) manufactured by Stovax Limited, Falcon Road, Sowton Industrial Estate, Exeter, Devon, EX2 7LF.

Stockton 3 Flat top (product The manufacturer's instruction Untreated dry wood. The fuel coatings.

Canopy (model number 7160) Issue 4. Road, Sowton Industrial Estate, 50% open position. Exeter, Devon, EX2 7LF.

Stockton 7 Inset Convector The manufacturer's instruction Untreated dry wood. The fuel manufactured 7125C) Stovax Limited, Falcon Road, instruction Sowton Industrial Exeter, Devon, EX2 7LF.

Stockton Milner (4.6kW) inset Instruction manual reference Wood logs. The fuel must Exeter, 2010). Industrial Estate, Devon, EX2 7LF.

Stoven Mayfair SE & Stoven Newman Fireplaces Limited's Wood logs. The fuel must Chuangve Road, Industrial Estate), Provence, China. 455000.

Strebel **SRP** TR manufactured by Strebel Ltd, reference 1f Albany Park, Camberley, operation Surrey, GU16 7PB.

Stove SE) manufactured by 12th July 2011. Aga, Station Road, Ketley, Telford, Shropshire TF1 5AQ.

number 7119), Stockton 5 manual reference PM 176 - must not contain halogenated

and Stockton 5 Midline (model A permanent stop must be in metals as a result of treatment number 7133) manufactured place on the secondary air inlet with wood preservatives or by Stovax Limited, Falcon to prevent closure beyond the coatings.

> manual Issue 1.

A permanent stop must be in place on the secondary air inlet to prevent closure beyond the 50% open position.

stove – smoke control version PM416 Issue 1, (June 2010) and not contain halogenated organic - manufactured by Stovax smoke control kit instruction compounds or heavy metals as Limited, Falcon Road, Sowton manual PM501 Issue 1 (June a result of treatment with wood

> A permanent stop must be positioned to prevent closure of the secondary air control below the 50% open position.

Kensington SE 5kW Wood Instruction manual references not contain halogenated organic Burning Stoves. Manufactured "3-4" dated 27th November compounds or heavy metals as by Ciang Stoves Limited, South 2011. Fitted with mechanical a result of treatment with wood-(Hanling stops to prevent closure of the preservatives or coatings. Beiguan secondary air control beyond Section, Anyang City, Henan the 25% open position and the tertiary air beyond the 1mm open position when sold into smoke control areas.

90, The Strebel SRP 90kW output pellet boiler pellet boiler installation manual The "Installation instructions 09:2010.

Stockton 5 Flat top (model The manufacturer's instruction Untreated dry wood. The fuel organic compounds or heavy

(product codes 7125F and manual dated May 2008, must not contain halogenated by reference PM230 Issue 1, organic compounds or heavy dated metals as a result of treatment Estate, January 2009, reference PM281 with wood preservatives or coatings.

preservatives or coatings.

TR 90 6mm diameter wood pellets. fuel must and contain halogenated organic for compounds or heavy metals as special pellet-furnace" version a result of treatment with woodpreservatives or coatings.

Stretton Insert Smoke Exempt Instruction manual references Dry wood logs. The fuel must Wood Fuel Stove (Stretton "N00530AXX REV:001" dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

STU 195 and STU 975 biomass Instruction. boilers manufactured by Hoval maintenance. Nottinghamshire, NG24 1JN.

operation assembly May 2011.

and Wood Pellets. The fuel must Instruction not contain halogenated organic Limited, Northgate, Newark, manual for STU wood-pellet compounds or heavy metals as fired hot water boiler skid a result of treatment with wood-"STUman" dated preservatives or coatings.

Stuv 30 Compact de-Villers, Belgium.

January 2013. Fitted with a preservatives or coatings. mechanical stop to prevent air control closure beyond the positions between settings 3 and 4 when sold into smoke control areas

stove Instruction manual references Wood logs. The fuel must manufactured by Stuv Sa, Rue "SN94770" dated January 2013 not contain halogenated organic Jules Borbouse 4, B-5170 Bois- and installation instruction compounds or heavy metals as manual "SN 94770" dated a result of treatment with wood-

Jules Borbouse 4, B-5170 Bois- 2013 de-Villers, Belgium.

and instruction manual 131766" dated January 2013. preservatives or coatings. Fitted with a mechanical stop to prevent air control closure beyond the positions between settings 3 and 4 when sold into smoke control areas.

Stuv 30 Compact H stove Instruction manual references Wood logs. The fuel must manufactured by Stuv Sa, Rue "SN 131766" dated January not contain halogenated organic installation compounds or heavy metals as "SN a result of treatment with wood-

manufactured by Stuv Sa, Rue 2013 de-Villers, Belgium.

Stuv 30 Compact IN and Instruction manual references Wood logs. The fuel must and dated January 2013. Fitted with preservatives or coatings. a mechanical stop to prevent air control closure beyond the positions between settings 3 and 4 when sold into smoke control areas

Stuv 30 Compact R stoves "SN 112787" dated January not contain halogenated organic installation compounds or heavy metals as Jules Borbouse 4, B-5170 Bois- instruction manual "112787" a result of treatment with wood-

Hard Top manufactured by La "7095701 Nordica Spa, Via Summano 104 13/12/2010. M, Precalcino, 36030, Vicenza, Italy.

Suprema, Mamy and Italy Instruction manual references Wood logs. The fuel must Rev.09"

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Talbott 150-CMH output Biomass Air Heater Talbott 150-CMH hand-fed density fibreboard (MDF) or manufactured by Biomass Energy Limited. Tollgate Tollgate Industrial Estate, 2011. Stafford ST16 3HS.

150kW Instruction manual

for Softwood, Hardwood, medium Talbott's Biomass Air Heater operating chipboard offcuts. The fuel Systems package reference "OM-150- must not contain halogenated Drive, CMH version.1" dated January organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

Talbott Heater. manufactured Talbott's Heating Limited.

Automatic The manufacturer's instructions No fuel shall be used other than by published in January 1989 and softwood shavings, hardwood T5-A-1-89".

bearing the reference "Jan.89, shavings or chipboard dust. fuel The must contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Talbott's Automatic Biomass The manufacturer's instructions No fuel shall be used other than Air Heaters, models T1.5/ bearing the reference "T/A hardwood or softwood shavings T3/A, T5/A and TM/ January 1990". A, formerly manufactured A by Talbott's Heating Limited and now manufactured by Talbott's Biomass Energy Systems Limited, **Tollgate** Tollgate Industrial Drive, Estate, Stafford ST16 3HS.

or sawdust. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

by Talbott's Heating Limited Range". and now manufactured by Talbott's Biomass Energy Systems Limited. Tollgate Tollgate Industrial Drive, Estate, Stafford ST16 3HS.

The Talbott's Biomass Energy The manufacturer's instructions No fuel shall be used other than Models C1, C2, C3 and dated August 1995 bearing chipboard or wood shavings or formerly manufactured the reference "Issue C1000/C/ forestry chips. The fuel must

not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

T1.5/A, T3/A, T5/A and TM/ JANUARY 1990". A manufactured by Talbott's Heating Limited.

Talbott's Energy Saving Wood The manufacturer's instructions No fuel shall be used other than Burning Automatic published in January 1990 and hardwood or softwood shavings Warm Air Heaters models bearing the reference "T/A or sawdust. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

T300 Biomass Air Heaters dated 1st January 1995 bearing than wood offcuts, wood waste, formerly Talbott's Heating and now manufactured by "gen/sttech". Talbott's **Biomass** Energy Systems Limited. **Tollgate** Drive. Tollgate Industrial Estate, Stafford ST16 3HS.

Talbott's model T75, T150, The manufacturer's instructions No fuel shall be used other manufactured by the following reference - pallets, or chipboard. The fuel Limited models T75, T150 and T300: must not contain halogenated organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

manufactured by Heating Limited.

Talbott Pirojet P150 Heater The manufacturer's instructions (a) bearing the "No.P150-2.87".

Talbott's dated February 1987 and No fuel shall be used other than reference hardwood or softwood offcuts, or chipboard. The fuel must not contain halogenated organic compounds or heavy metals as

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

> a result of treatment with woodpreservatives or coatings;

When the fireplace is used to burn chipboard, an afterburner which is supplied with the fireplace and which must be capable of continuously producing 20 megajoules of heat per hour shall be used;

(c)

The fireplace shall not be used to burn sawdust in bulk.

Talbott Pirojet P300 Heater The manufacturer's instructions (a) manufactured by Talbott's dated February 1987 and No other fuel shall be used other Heating Limited. bearing the "No.P300-2-87".

reference than hardwood or softwood offcuts, or chipboard. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings:

(b)

When the fireplace is used to burn chipboard, an afterburner which is supplied with the fireplace and which must be capable of continuously producing 40 megajoules of heat per hour shall be used;

(c)

The fireplace shall not be used to burn sawdust in bulk.

Talbott Pirojet P600 Heater The manufacturer's instructions (a) manufactured by Talbott's dated Heating Limited.

December "No.P600-12.86".

1986 No fuel shall be used other than and bearing the reference hardwood or softwood offcuts or chipboard. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings;

(b)

When the fireplace is used to burn chipboard, an afterburner which is supplied with the fireplace and which must be capable of continuously producing 75 megajoules of heat per hour shall be used;

The fireplace shall not be used to burn sawdust in bulk.

D500 and D700 manufactured 1991 Ref No. D257". by Talbott's Heating Limited.

Talbott Down Firing range of The manufacturer's instructions No fuel shall be used other warm air heaters, models D250, bearing the reference "May than chipboard. The fuel must

not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Waste Burning Automatic Hot dated October 1993 and bearing Water Heaters, models T1.5/ the reference "Issue: A1001". AB, T3/AB, T5/AB and TM/ AB, manufactured by Talbott's Heating Limited.

Talbott's Energy Saving Wood The manufacturer's instructions No fuel shall be used other than hardwood or softwood shavings or sawdust. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

CM4 manufactured by Talbott's the reference "Issue: CM897". Heating Limited.

models CM1, CM2, CM3 and dated August 1997 and bearing

Talbott's Combustion Units The manufacturer's instructions No fuel shall be used other than wood waste, pallets, medium density fibreboard, or untreated and airdried wood offcuts. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Heating Limited.

C4 manufactured by Talbott's the reference "Issue: C10000/C/ Range".

Talbott's Combustion Units The manufacturer's instructions No fuel shall be used other than models C1, C2, C3 and dated August 1995 bearing chipboard or wood shavings, or forestry chips. The fuel must not contain halegonated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

T150, T300, D250B, D500B and D700B, manufactured by Talbott's Heating Limited.

dated 1st January 1995 bearing the following reference—

models T75, T150 and T300: "gen/sttech";

(ii)

models D250B, D500B and D700B: "Gen/Tech".

Talbott's Heating models T75, The manufacturer's instructions No fuel shall be used other than the following—

models T75, T150 and T300: wood offcuts, wood waste, pallets, or chipboard;

models D250B, D500B and D700B: hardwood or softwood offcuts, or chipboard.

The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Talbott's heater (afterburn formerly manufactured Talbott's Heating and now Talbott's Biomass Energy

by bearing the reference A10000. Limited The afterburn cycle shall last manufactured by not less than 25 minutes and

T500 Biomass Air The manufacturer's instructions No fuel shall be used other model) dated 1st January 1983, and than wood offcuts, wood waste, pallets, or chipboard.

fuel must contain halogenated organic compounds or heavy metals as

Systems Limited, Drive, Tollgate Estate, Stafford ST16 3HS.

Tollgate shall come into operation each a result of treatment with wood-Industrial time the loading door is opened. preservatives or coatings.

manufactured by La Nordica "7095802 Spa, Via Summano 104 M. 01/02/2011. Precalcino 36030, Vicenza, Italy.

Termosuprema Compact DSA Instruction manual references Wood logs. The fuel must Rev.06"

dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Therminator II 22 Therminator II 30 Werkstrasse 1, 4451 St.Ulrich, "V8.051" Steyr, Austria.

and Installation Boiler "Version 11/08/06" dated Maintenance Instructions "Ver preservatives or coatings. 01/09/06" dated 2006.

Instructions Wood pellets. The fuel must dated not contain halogenated organic manufactured by Solarfocus, 07/2006. Operating Manual compounds or heavy metals as 09/2009. a result of treatment with wood-

Therminator П 27 Therminator II 36 Boiler "Version Werkstrasse 1, 4451 St.Ulrich, "V8.051" Steyr, Austria.

and Installation 11/08/06" manufactured by Solarfocus, 07/2006. Operating Manual compounds or heavy metals as dated Maintenance Instructions "Ver preservatives or coatings. 01/09/06" dated 2006.

Instructions Wood logs. The fuel must dated not contain halogenated organic 09/2009. a result of treatment with wood-

Therminator II 40 Boiler Installation manufactured by Solarfocus, "Version Werkstrasse 1, 4451 St. Ulrich, 07/2006. Steyr, Austria.

Instructions Wood 11/08/06" "V8.051" dated 01/09/06" dated 2006.

pellets or wood dated chips. The fuel must not Operating Manual contain halogenated organic 09/2009. compounds or heavy metals as Maintenance Instructions "Ver a result of treatment with woodpreservatives or coatings.

Therminator Π 49 Therminator II 60 Boiler "Version Werkstrasse 1, 4451 St. Ulrich, "V8.051" Steyr, Austria.

and Installation 11/08/06" dated 01/09/06" dated 2006.

Instructions Wood logs or wood pellets dated or wood chips. The fuel must manufactured by Solarfocus, 07/2006. Operating Manual not contain halogenated organic 09/2009. compounds or heavy metals as Maintenance Instructions "Ver a result of treatment with woodpreservatives or coatings.

Thornhill manufactured by Thornhill Eco "ED/11/05" Canterbury, Kent, CT1 3RS.

small Instruction manual references Wood logs. The fuel must dated that prevents the tertiary air preservatives or coatings. controller from closing more than 17mm and opening more than 45mm.

January not contain halogenated organic Design Ltd, 58/60 Wincheap, 2011. The appliance must compounds or heavy metals as be fitted with an air plate a result of treatment with wood-

Tiger SuperClean manufactured by Tiger stoves, "INSTALLATION Focus Arts & Crafts Co, OPERATING Village, Xin Zhuang Town, 148" (dated April 2010). Jin Nan District, Tianjin, P.R. China 300350.

stove Instruction manual references Wood logs. The fuel must

AND not contain halogenated organic compounds or heavy metals as Industrial Area Gao Zhuangzi INSTRUCTIONS document v. a result of treatment with wood preservatives or coatings.

T.R. Engineering Ltd, Unit 25/06/2012. 7, Newton Chambers Way, Thorncliffe Industrial Estate, Chapeltown, Sheffield, S35 2PH.

pellet boiler manufactured by "Item No. 400001 Iss. 2" dated must not contain halogenated

Trianco Greenflame15 wood Instruction manual references 6mm wood pellets. The fuel organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

90 Triancomatic manufactured by Redfyre Limited.

boiler The manufacturer's instructions No Trianco dated July 1987 and which— (i)

in the case of installation manufacturer's instructions. instructions bear the reference "No. 46576"; and

in the case of the user instructions bear the reference "No. 46574".

fuel shall be used than washed other the coals recommended in the

Triancomatic 140 manufactured by Redfyre Limited.

boiler The manufacturer's instructions No fuel shall be used other than Trianco dated November 1986 and the washed coals recommended which-

(i)

in the case of the installation instructions bear the reference "No. 48375"; and

(ii)

in the case of the user instructions bear the reference "No. 48374".

in the manufacturer's user instructions.

80T Turbhogar Alfa Turbhogar Delta 80T and 65T, dated Turbhogar Lambda 80T and supplementary 65T, Turbhogar Omega 80T and 20/09/2010. Business Centre. North Yorkshire, BD23 2TZ.

and Manual of assembly and Wood logs. The fuel must 65T, Turbhogar Beta 80T, use referenced "RR100920" not contain halogenated organic 20/09/2010 65T, Turbhogar Sigma 80T and manual "UK100920" dated preservatives or coatings.

Turbhogar Tau 80T and 65T Appliances will be fitted with fireplace inserts manufactured a system that prevents the by Rofer & Rodi UK Ltd, Unit full closure of the air control 10, Millennium Road, Airedale opening, so that the air openings Skipton, remain 3mm (30%) open at the minimum setting.

and compounds or heavy metals as instruction a result of treatment with wood-

Turbo Heat, models 1000 and The manufacturer's instructions No fuel shall be used other than Engineers Limited.

1000/1200 1990".

1200 manufactured by CBR published in 1990 and bearing hardwood or softwood offcuts, the reference "CBR Turbo Heat or chipboard. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Twin Heat by manufactured

version 6.0.03.

CS150i Operating instructions dated Wood pellets of a maximum TWIN 17th December 2008, reference length of 30 mm and diameter of 6 mm and conforming to

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

HEAT A/S, N�rrevangen 7, DK-9631 Gedsted, Denmark.

CEN/TS 14961:2005. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

USP-10. 15, 20, and 30, manufactured by KWB-Kraft and W�rme Biomasse Gesellschaft aus mit beschrii/2nkter Haftung (GmbH) of Industriestrasse 235, A-8321 St. Margarethen an der Raab, Austria.

fired boilers, model numbers dated 28th July 2003, reference not contain halogenated organic 25 BA-USP 0703.

USP wood pellet- The manufacturer's instructions Wood pellets. The fuel must compounds or heavy metals as a result of treatment with wood preservatives or coatings.

75, EOS 80, EOS 85 boilers R1" dated May 2012. fitted with a multi-cyclone manufactured by Uniconfort srl, Via dell'Industria, 21, 35018 San Martino di Lupari, PD, Italy.

EOS 55, EOS 65, EOS 70, EOS "Uniconfort EOS MANUAL: not contain halogenated organic

Uniconfort EOS 45, EOS 50, Instruction manual references Wood pellets. The fuel must compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Uniconfort EOS 90 boiler Instruction manual references Wood manufactured by Uniconfort R1" dated May 2012. srl, Via dell'Industria, 21, 35018 San Martino di Lupari, PD, Italy.

fitted with a multi-cyclone "Uniconfort EOS MANUAL: chips. The fuel must not

pellets or wood contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

pellet boiler (also exempt as references manufactured by Windhager instruction Zentralheizung GmbH, Anton- "092945/00" dated 01 2010. Windhager-Str. 20, A-5201 Seerkirchen bei Salzburg, Austria.

66

VarioWIN VA 120 12kW wood Installation Instruction manual Wood pellets, 6mm diameter, 092947/00" length 80% between 15-30mm the VarioWIN VA 12kW) dated 01/2010 and operating and a density of at least 1.1kg/ manual dm $i_1^{1/2}$.

Estate, Stone Hill Road, Jan/2013. Farnworth, Bolton BL4 9TN.

Vega 100 Clean Burn II Instruction manual references Wood logs. The fuel must stove manufactured by Percy "Vega 100 Clean Burn II not contain halogenated organic Doughty & Co Limited, Installation and Operation compounds or heavy metals as Imperial Point, Express Trading Instructions REV: D" dated a result of treatment with wood-Fitted with mechanical stop to prevent secondary air control closure beyond the 50% open position when sold into smoke control

a preservatives or coatings.

Vega 200 Clean

Burn Instruction manual references Wood logs. The fuel must stove manufactured by Percy "Vega 200 Clean Burn not contain halogenated organic

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Doughty & Co Limited, Installation Estate, Stone Hill Road, Jan/2013. Farnworth, Bolton, BL4 9TN.

and Fitted with mechanical stop to prevent secondary air control closure beyond the 50% open position when sold into smoke control

Operation compounds or heavy metals as Imperial Point, Express Trading Instructions REV: D" dated a result of treatment with wooda preservatives or coatings.

Vesuvio CLM Bakery System srl, and (PN), Italy, and previously dated 29/11/2011. manufactured by CLM srl, Via I Maggio 35, 31043, Fontanelle (Treviso), Italy.

400kW automatic CLM Vesuvio oven instruction 'CalorPan' pizza oven manufactured by manual reference "Instruction briquette, octagonal section, Via Monteli, 3-33092 Meduno ENGLISH" version Review 0.1 height 75-90mm. Manufactured

100% beech maintenance manual length 260-300mm, width and from dried beech sawdust. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

manufactured by Industrial Estate, Devon, EX2 7LF.

Exeter, Issue 1 dated June 2010.

A permanent stop must be positioned to prevent closure of the secondary air control below the 50% open position.

View 3 (3.8kW) and View Instruction manual references Wood logs. The fuel must 5 (4.9kW) multifuel stoves PM485 Issue 1 dated June not contain halogenated organic Stovax 2010 and smoke control kit compounds or heavy metals as Limited, Falcon Road, Sowton instruction manual PM490 a result of treatment with wood preservatives or coatings.

View (4.9kW)Industrial Estate, Devon, EX2 7LF.

stove manufactured by Stovax PM485 Issue 1 dated June not contain halogenated organic Issue 1 dated June 2010.

A permanent stop must be positioned to prevent closure of the secondary air control below the 50% open position.

wood Instruction manual references Wood logs. The fuel must Limited, Falcon Road, Sowton 2010 and smoke control kit compounds or heavy metals as Exeter, instruction manual PM490 a result of treatment with wood preservatives or coatings.

code manufactured by Industrial Estate, Devon, EX2 7LF.

View 7 (7kW) inset appliance Instruction manual reference Wood logs. The fuel must VW-7NMF "PM552 - Issue 1" dated June not contain halogenated organic Stovax 2011 and smoke control kit compounds or heavy metals as Limited, Falcon Road, Sowton instruction manual reference a result of treatment with wood-Exeter, "PM490 Issue 2" dated July preservatives or coatings. 2011.

A permanent stop must be in place on the secondary air inlet to prevent closure beyond the 50% open position.

by Ciang Stoves Limited, South Fitted with mechanical stops

Vista Magnifico SE & Vista Newman Fireplaces Limited's Wood logs. The fuel must Perfetto SE 4.9kW Wood Instruction manual references not contain halogenated organic Burning Stove. Manufactured "1-2" dated 24th October 2011. compounds or heavy metals as

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Chuangye Road. Industrial Estate), Provence, China 455000.

(Hanling to prevent closure of the a result of treatment with wood-Beiguan secondary air control beyond preservatives or coatings. Section, Anyang City, Henan the 30% open position and the tertiary air beyond the 50% open position when sold into smoke control areas.

Vitae 06C inset Dublin 12, Ireland.

manufactured by Heat Design, "VIT06C" dated 26/07/12. A not contain halogenated organic 30 Hawthorn Road, Western permanent stop to prevent compounds or heavy metals as Industrial Estate, Naas Road, closure of the secondary air a result of treatment with woodcontrol beyond 20% open must preservatives or coatings. be implemented.

stove Instruction manual references Wood logs. The fuel must

Vitae 11C inset Dublin 12, Ireland.

stove Instruction manual references Wood logs. The fuel must control beyond 20% open must preservatives or coatings. be implemented.

manufactured by Heat Design, "VIT11C" dated 26/07/12. A not contain halogenated organic 30 Hawthorn Road, Western permanent stop to prevent compounds or heavy metals as Industrial Estate, Naas Road, closure of the secondary air a result of treatment with wood-

Westcott 5SE manufactured Instruction manual references Wood logs. The fuel must by Dimplex, GDC Group 08/51351/0 - Issue 0 Dated not contain halogenated organic Limited, Millbrook House, 07/09/10. compounds or heavy metals as Grange Drive, Hedge End, Southampton, SO30 2DF.

a result of treatment with woodpreservatives or coatings.

Westfire Series Two stove series manufactured by Westfire, and T�mrervej 3, Varde, Denmark.

installation DK-6800 and supplementary Instruction a result of treatment with woodmanual reference "Westfire preservatives or coatings. supplementary instructions June 2011/Version 1" dated 1st June 2011. The appliance must be fitted with a permanent stop to prevent closure of the secondary air control less than 50% open.

Westfire Series One stove and Westfire WF One and Two Wood logs. The fuel must manual not contain halogenated organic operating instructions compounds or heavy metals as

Westfire Uniq 15, 16 and 20 Installation (also known as WF UNIQ instructions DK-6800 Varde, Denmark.

and dated instructions dated reference 01 wfuk.2007.

A permanent stop must be in place on the secondary air inlet to prevent closure beyond 50mm.

operating Untreated dry wood. The fuel 2007, must not contain halogenated 15, 16 and 20) manufactured reference WF15-WF16-WF20, organic compounds or heavy by Westfire Ti₁/2/mrervej 3 together with supplementary metals as a result of treatment 2007, with wood preservatives or coatings.

Westfire Uniq 18 Westfire Uniq 17 Westfire Uniq 19 Westfire Uniq 23 Westfire Uniq 23 side Glass Instruction manual references Wood logs. The fuel must "WESTFIRE SUPPLEMENTARY INSTRUCTIONS 2010".

not contain halogenated organic compounds or heavy metals as JUNE a result of treatment with wood preservatives or coatings.

Westfire Uniq 23 Inset stoves All appliances will be fitted manufactured by Westfire APS, with a mechanical stop Ti, ½mrervej 3 DK-6800 Varde, to prevent closure of the Denmark.

secondary air slide beyond the 30mm open position when sold into smoke control areas.

Westfire Uniq 21 stove, Westfire WF21 Westfire Uniq 21 pedestal stove manual Westfire, Ti, ½mrervej 3, DK- "Westfire 6800 Varde, Denmark.

and and Westfire Uniq 21 wall instructions and supplementary compounds or heavy metals as hung stove manufactured by Instruction manual reference a result of treatment with woodinstructions June 2011/Version 1" dated 1st June 2011. The appliance must be fitted with a permanent stop to prevent closure of the secondary air control less than 60% open.

installation Wood logs. The fuel must operating not contain halogenated organic supplementary preservatives or coatings.

Westfire Uniq 26 Westfire Uniq 27 manufactured by T�mrervej Varde, Denmark.

WF26. stove, Westfire stove WF28 installation Westfire, and supplementary Instruction a result of treatment with wood-DK-6800 manual reference "Westfire preservatives or coatings. supplementary instructions June 2011/Version 1" dated 1st June 2011. The appliance must be fitted with a permanent stop to the secondary air slider control to prevent closure more than 20mm from the fully closed position.

WF27, Wood logs. The fuel must manual not contain halogenated organic and Westfire Uniq 28 stove and operating instructions compounds or heavy metals as

Westfire Uniq and Westfire stove Freestanding manufactured by Tï; ½mrervej 3, Varde, Denmark.

Inset Westfire WF23/Uniq23, WF32/ Wood logs. The fuel must Uniq Uniq 32 inset stove installation manual Westfire, operating instructions DK-6800 supplementary manual reference "Westfire supplementary instructions June 2011/Version 1" dated 1st June 2011. The appliance must be fitted with a permanent stop to prevent closure of the secondary air control less than 50% open.

stove not contain halogenated organic and compounds or heavy metals as and a result of treatment with wood-Instruction preservatives or coatings.

by Windhager Zentralheizung dated May 2008. GmbH, Anton-Windhager-Str. 20, A-5201 Seerkirchen bei Salzberg, Austria.

Windhager BioWin 100, 150, The manufacturer's instruction Wood pellets. The fuel must

210 and 260 manufactured manual reference 0916197/00, not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Zentralheizung GmbH, Anton- dated August 2008. Windhager-Str. 20, A-5201 Seerkirchen bei Salzberg, Austria.

Windhager FireWin 90 and 120 The manufacturer's instruction Wood pellets. The fuel must manufactured by Windhager manual reference 092125/00, not contain halogenated organic

compounds or heavy metals as a result of treatment with wood preservatives or coatings.

80 manufactured by Valoriani dated January 2011. of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

Wood Fired Ovens by Jamie Instruction manual reference Untreated wood of less than Oliver Limited's Valoriani Casa "OOLinst.1 FVR 80 v2" and 20% moisture. The fuel must

not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

100 manufactured by Valoriani dated January 2011. of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

Oliver Limited's Valoriani Casa "OOLinst.2 FVR 100 v2" and 20% moisture. The fuel must

Wood Fired Ovens by Jamie Instruction manual reference Untreated wood of less than not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

110 manufactured by Valoriani dated January 2011. of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

Oliver Limited's Valoriani Casa "OOLinst.3 FVR 110 v2" and 20% moisture. The fuel must

Wood Fired Ovens by Jamie Instruction manual reference Untreated wood of less than not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

120 manufactured by Valoriani dated January 2011. of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

Oliver Limited's Valoriani Casa "OOLinst.4 FVR120 v2" and 20% moisture. The fuel must

Wood Fired Ovens by Jamie Instruction manual reference Untreated wood of less than not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Wood Fired Ovens by Jamie Instruction manual reference Untreated wood of less than Valoriani of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

Oliver Limited's Valoriani Casa "OOLinst.5 FVR 110x160 v2" manufactured by and dated January 2011.

20% moisture. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Wood Fired Ovens by Jamie Instruction manual reference Untreated wood of less than 100 manufactured by Valoriani January 2011. of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

Oliver Limited's Valoriani Villa "OOLinst.6 TOP 100 v2" dated 20% moisture. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

120 manufactured by Valoriani January 2011. of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

Wood Fired Ovens by Jamie Instruction manual reference Untreated wood of less than Oliver Limited's Valoriani Villa "OOLinst.7 TOP 120 v2" dated 20% moisture. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

Wood Fired Ovens OT Valoriani Ristorante 100 2011. manufactured by Valoriani of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

Jamie Oliver Limited's GR "OOLinst.8 GR 100 and OT 20% moisture. The fuel must Valoriani Ristorante 100 and 100 v2" and dated January not contain halogenated organic

by Instruction manual reference Untreated wood of less than compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Wood Fired Ovens OT Valoriani Ristorante 120 2011. manufactured by Valoriani of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

by Instruction manual reference Untreated wood of less than Jamie Oliver Limited's GR "OOLinst.9 GR 120 and OT 20% moisture. The fuel must Valoriani Ristorante 120 and 120 v2" and dated January not contain halogenated organic

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Wood Fired Ovens OT Valoriani Ristorante 140 2011. manufactured by Valoriani of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

Jamie Oliver Limited's GR "OOLinst.10 GR 140 and OT 20% moisture. The fuel must Valoriani Ristorante 140 and 140 v2" and dated January not contain halogenated organic

by Instruction manual reference Untreated wood of less than compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Ristorante 120x160 and OT OT Valoriani Ristorante 120x160 January 2011. manufactured by Valoriani of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

Wood Fired Ovens by Jamie Instruction manual reference Untreated wood of less than Oliver Limited's GR Valoriani "OOLinst.11 GR 120x160 and 20% moisture. The fuel must 120x160 v2". Dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Wood Fired Ovens by Jamie Instruction manual reference Untreated wood of less than Valoriani Ristorante 140x160 January 2011. manufactured by Valoriani of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

Oliver Limited's GR Valoriani "OOLinst.12 GR 140x160 and 20% moisture. The fuel must Ristorante 140x160 and OT OT 140x160 v2" and dated not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Oliver Limited's GR Valoriani "OOLinst.13 GR 140x180 and 20% moisture. The fuel must Ristorante 140x180 and OT OT 140x180 v2" and dated not contain halogenated organic Valoriani Ristorante 140x180 January 2011. manufactured by Valoriani of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

Wood Fired Ovens by Jamie Instruction manual reference Untreated wood of less than compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Wood Fired Ovens OT Valoriani Ristorante 180 2011. manufactured by Valoriani of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

by Instruction manual reference Untreated wood of less than Jamie Oliver Limited's GR "OOLinst.14 GR 180 and OT 20% moisture. The fuel must Valoriani Ristorante 180 and 180 v2" and dated January not contain halogenated organic

compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Oliver Limited's Piccolo manufactured Valoriani of Via Caselli alla Fornace, 213, 50066 Reggello, Firenze, Italy.

Valoriani "OOLinst.15 Valoriani Piccolo 20% moisture. The fuel must by v2" and dated January 2011.

Wood Fired Ovens by Jamie Instruction manual reference Untreated wood of less than not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

Woodpecker 15. 25 pellet 45 wood Energy UK, Abbey Manor 2012". Business Centre, Preston Road, Yeovil, BA20 2EN. Previously manufactured by Garranlea Renewables Ltd of Barnard, Garranlea, New Inn, Cashel, Co. Tipperary, Ireland.

and Instruction manual references Wood pellets conforming to boilers "Installation and Operating CEN TS 14961. The fuel must manufactured by Woodpecker Manual Issue 6 dated May not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Woodpecker 50kW by Woodpecker Abbey Manor Centre, Preston Road, Yeovil, Version 2 dated May 2012". Somerset, BA20 2EN.

pellet boilers manufactured "Installation and Operating CEN TS 14961. The fuel must Energy, Manual Woodpecker 50 Model not contain halogenated organic Business Wood Pellet Boiler System compounds or heavy metals as

wood Instruction manual references Wood pellets conforming to a result of treatment with woodpreservatives or coatings.

Energy UK, Abbey Manor 2012". Business Centre, Preston Road, Yeovil, BA20 2EN.

Woodpecker Thermon 150, Instruction manual references 6mm wood pellets. The fuel 200, 250 and 300 boilers "Installation and Operating must not contain halogenated manufactured by Woodpecker Manual Issue 2 dated February organic compounds or heavy

metals as a result of treatment with wood-preservatives or coatings.

Woodpecker Thermon 199 Instruction manual references 6mm wood pellets. The fuel by Woodpecker Energy UK, 2012. Abbey Manor Business Centre, Preston Road, Yeovil, BA20 2EN.

kW pellet boiler manufactured "Issue 2.0" dated February must not contain halogenated

organic compounds or heavy metals as a result of treatment with wood-preservatives or coatings.

Wood Waste Technology Ltd The manufacturer's instruction Medium density fibreboard, Waste Technology Limited, dated 16th February 2009. Units 1&2, Drummond Road, Astonfields Industrial Estate, Stafford, Staffordshire ST16 3HJ.

WT5, manufactured by Wood manual reference WT5 v2, chipboard and hard

softwood offcuts. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Wood Waste Heater, models WT10 and dated 19th January 2005 and WT15, manufactured by Wood bearing the reference WT10 and Waste Technology Limited, WT15. Units 1&2, Drummond Road, Astonfields Industrial Estate, Stafford, Staffordshire ST16 3HJ.

Technology The manufacturer's instructions Medium density fibreboard,

chipboard and hard softwood offcuts. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with wood preservatives or coatings.

Worcester Centair 40 Solid Fuel The manufacturer's instructions Union Warm Air Heater manufactured which by Worcester Engineering Co. (i) Limited.

"BC40.1.2 July 1983"; and

maintenance instructions bear cent. the reference "BC40.OM2 July 1983".

Coal Briquettes, manufactured by Rheinbraun AG of Germany in the case of installation comprising lignite compressed instructions bear the reference into briquettes of approximately 15 centimetres in length with square ends and with a sulphur in the case of operating and content not exceeding one per

WTA WT Drummond Road, Astonfields 2011. Industrial Estate, Stafford, ST16 3HJ.

Auto 200kW Instruction manual references Chipboard, Medium Density Airheater manufactured by "WTA Installation Operation Fibreboard, Softwood, Technology & Maintenance Instructions" Hardwood. All fuels to be Limited, Units 1, 2 & 3, WTA v1 Issue A dated April chipped to a maximum size

of 25mm and a maximum moisture content of 20%. Maximum fines (sawdust) content 5%. The fuel must not contain halogenated organic compounds or heavy metals as a result of treatment with woodpreservatives or coatings.

WTH 150 and 200 boilers (GmbH), Gundering 8, A-4952, Weng, Austria.

WTH The manufacturer's installation Wood manufactured manual version 91 for Large pellets. The fuel must not by Hargassner Gesellschaft Capacity Boiler WTH 150-200. contain halogenated organic mit beschrij/2nkter Haftung Reference BA GK V90b 0309. compounds or heavy metals as

chip a result of treatment with wood preservatives or coatings.

Xeoos 5kW stove Versions Instruction manual entitled: Wood logs Conforming to DIN Natur, Style, Harmony, "Operating and Installation 51731.
 Pur, Classic, Elegance and Instructions Xeoos 5kW/8kW The Stone Xeoos 8kW stove Model Versions – Basic, Pur, Classic, Revisions – Index 01/08 compounds or heavy metals as Elegance Stone and Instruction manual references. Manufactured by Specht Modulare Ofensysteme GmbH & Co, KG Projektmanagement Bahnhofstr.2, D-35116 Hatzfeld, Germany.

2008" Air Fassung January 2008.

fuel must Reference; contain halogenated organic a result of treatment with wood preservatives or coatings.

Product code manufactured by Industrial Estate, Devon, EX2 7LF.

YM-CLMB "PM559 - Issue 1" dated June not contain halogenated organic Stovax 2011 and smoke control kit compounds or heavy metals as Limited, Falcon Road, Sowton instruction manual reference a result of treatment with wood-Exeter, "PM491 Issue 2" dated June preservatives or coatings. 2011.

A permanent stop must be positioned to prevent closure of

Yeoman CL Milner Stove Instruction manual reference Wood logs. The fuel must

Changes to legislation: There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked). (See end of Document for details)

> the secondary air control below the 50% open position.

manufactured by Industrial Estate, Devon, EX2 7LF.

CL5 (4.9kW) multifuel stoves PM489 Issue 1 dated June not contain halogenated organic Stovax 2010 and smoke control kit compounds or heavy metals as Limited, Falcon Road, Sowton instruction manual PM491 a result of treatment with wood Exeter, Issue 1 dated 5th April 2010. A permanent stop must be positioned to prevent closure of the secondary air control below

Yeoman CL3 (3.8kW) and Instruction manual references Wood logs. The fuel must preservatives or coatings.

Industrial Estate. Devon, EX2 7LF.

stove manufactured by Stovax PM489 Issue 1 dated June not contain halogenated organic Limited, Falcon Road, Sowton 2010 and smoke control kit compounds or heavy metals as Exeter, instruction manual PM491 a result of treatment with wood Issue 1 dated 5 April 2010.

the 50% open position.

A permanent stop must be positioned to prevent closure of the secondary air control below the 50% open position.

Yeoman CL5 (4.9kW) wood Instruction manual references Wood logs. The fuel must preservatives or coatings.

Yeoman CL 7 (7kW) inset Instruction manual reference Wood logs. Sowton Industrial Exeter, Devon, EX2 7LF.

appliance Product code YM- "PM553 - Issue 1" dated June The CL7NMF manufactured by 2011 and smoke control kit contain halogenated organic Stovax Limited, Falcon Road, instruction manual reference compounds or heavy metals as Estate, "PM491 Issue 2" dated June a result of treatment with wood-2011.

> A permanent stop must be in place on the secondary air inlet to prevent closure beyond the 50% open position.

fuel must not preservatives or coatings.

Door and High Canopy 2 Door Issue 1 dated January 2010. Exeter, Devon, EX2 7LF.

Yeoman Devon Multifuel Flat Instruction manual references Wood logs. The fuel must Top 1 Door, Flat Top 2 Door, PM184 Issue 3 dated February not contain halogenated organic Low Canopy 1 Door, Low 2008 and smoke control kit compounds or heavy metals as Canopy 2 Door, High Canopy 1 instruction manual PM403 a result of treatment with wood (9kW) Stoves manufactured A permanent stop must be by Stovax Limited, Falcon positioned to prevent closure Road, Sowton Industrial Estate, of the secondary air control below the 50% open position and a system that ensures a gap of 1mm for bleed of primary air when the spin wheels are rotated to their fully closed positions.

preservatives or coatings.

(4.9kW) Stoves manufactured Issue 1 dated January 2010. by Stovax Limited, Falcon

Yeoman Exe Multifuel Flat Instruction manual references Wood logs. The fuel must

Top 1 Door, Flat Top 2 PM184 Issue 3 dated February not contain halogenated organic Door, Low Canopy 1 Door 2008 and smoke control kit compounds or heavy metals as and Low Canopy 2 Door instruction manual PM403 a result of treatment with wood preservatives or coatings.

Road, Sowton Industrial Estate, A permanent stop must be Exeter, Devon, EX2 7LF.

positioned to prevent closure of the secondary air control below the 60% open position and a system that prevents full closure of the primary air controls.

Yeoman Exmoor Multifuel Flat Instruction manual references Wood logs. The fuel must Top and Multifuel Low Canopy PM184 Issue 3 dated February not contain halogenated organic (4.9kW) Stoves manufactured 2008 and smoke control kit compounds or heavy metals as by Stovax Limited, Falcon instruction manual PM403 a result of treatment with wood Road, Sowton Industrial Estate, Issue 1 dated January 2010. Exeter, Devon, EX2 7LF.

A permanent stop must be

positioned to prevent closure of the secondary air control below the 60% open position and a system that prevents full closure of the primary air controls.

preservatives or coatings.

EXPLANATORY NOTE

(This note is not part of the Regulations)

These Regulations revoke the Smoke Control Areas (Exempted Fireplaces) (No.2) Regulations (Northern Ireland) 2012 (S.R. 2012 No. 379), and subsequently re-instate the provisions. In addition, a number of new classes of fireplace are declared exempt from the provisions of Article 17 of the Clean Air (Northern Ireland) Order 1981 (S.I. 1981/158 (N.I. 4)) ("the Clean Air Order"). The list of all exempted fireplaces can be found in the Schedule to these Regulations.

Status:

Point in time view as at 23/08/2013.

Changes to legislation:

There are currently no known outstanding effects for the The Smoke Control Areas (Exempted Fireplaces) Regulations (Northern Ireland) 2013 (revoked).