

SCHEDULE 2
SOLVENT EMISSIONS

PART 2
SEPA functions

8. SEPA may permit emissions to exceed a fugitive emission limit required under sub-paragraph (a) of Article 59(1) of the Industrial Emissions Directive, provided that—

- (a) it is not technically and economically feasible to comply with that sub-paragraph,
- (b) SEPA ensures that the operator of the installation uses the best available techniques in respect of those emissions, and
- (c) SEPA is satisfied that there are no significant risks to human health and the environment.