

FIRST SCHEDULE

THE MISCELLANEOUS MINES (GENERAL) REGULATIONS, 1956, HAVING EFFECT AS IF MADE UNDER SECTION ONE HUNDRED AND FORTY-ONE OF THE MINES AND QUARRIES ACT, 1954

PART IX

Machinery and ropes

General

37.—(1) No person shall clean any machinery which is in motion.

(2) No person shall oil or grease any machinery which is in motion unless provision is made for the operation to be performed in safety.

(3) No person shall put any belt on or off a pulley while any machinery of which it forms part is in motion under mechanical power otherwise than by means of a safety contrivance.

38. At every mine a competent person appointed for that purpose by the manager shall at intervals not exceeding seven days examine any machinery and apparatus forming part of the equipment of the mine other than machinery or apparatus the periodical examination of which at more frequent intervals is expressly provided for by regulations (including these regulations) or any winding or haulage apparatus which is in use solely for carrying persons through any shaft, staple-pit or unwalkable outlet but which is not ordinarily so used.