

## SCHEDULE 12

### (Annex XIII to the Lifts Directive) FULL QUALITY ASSURANCE FOR LIFTS (module H)

**1.** Full quality assurance is the procedure whereby the installer of a lift who satisfies the obligations of Section 2 ensures and declares that lifts satisfy the requirements of the Directive that apply to them.

The installer of a lift must affix the CE marking on each lift and draw up an EC declaration of conformity. The CE marking must be accompanied by the identification number of the notified body responsible for the surveillance as specified in Section 4.