## SCHEDULE 4

## Types of accidents and incidents occurring within the Channel Tunnel System that must be notified to the Rail Accident Investigation Branch immediately and by the quickest means available

- 3. A collision that occurs on any line other than a siding, between rolling stock and—
  - (a) other rolling stock;
  - (b) an object capable of causing damage to or derailment of the rolling stock; or
  - (c) a buffer stop.