

## SCHEDULE 1

### ESSENTIAL REQUIREMENTS

#### **Reliability**

**8.** A meter measuring system shall be designed to reduce as far as possible the effect of a defect that would lead to an inaccurate measurement result, unless the presence of such a defect is obvious.